

1 THE PRESIDENT: Yes, CMDR Rush.

2

3 CMDR RUSH: Sir, we propose to deal with the wreck site of
4 HMAS Sydney and the imagery that was taken by Geosounder.
5 The witnesses involved in the preparation of the report
6 concerning this aspect are Mr Jeremy, Dr Cannon,
7 Mr Buckland and Mr de Yong. I ask that they come forward.

8

9 THE PRESIDENT: Come forward, gentlemen.

10

11 <JOHN CHRISTOPHER JEREMY, on former affirmation: [10.01am]

12

13 <STUART MARTIN CANNON, on former affirmation: [10.01am]

14

15 <LEO VINCENT de YONG, on former affirmation: [10.01am]

16

17 <MICHAEL EDMOND BUCKLAND, on former affirmation: [10.01am]

18

19 CMDR RUSH: Dr Michael Skeen, sir, has been responsible
20 for a great deal of the preparation of the report. For
21 this aspect at least, he will use the pointer.

22

23 Gentlemen, if I could ask you to go to page 144 of the
24 report and if we could have figure 111 placed on the
25 screen.

26

27 While it is coming on the screen, may I ask about the
28 site of the wreck of Sydney. Firstly, the bow, as I think
29 has been discussed, was separated from the main section of
30 the ship. Were you able to determine the distance between
31 the bow and the ship?

32

33 DR CANNON: Yes. The two images that we have are,
34 firstly, the side scan sonar image from Sydney that is
35 taken from John Perryman's report, and, secondly, we also
36 lifted one of the images from the real-time video. By
37 overlaying the distance of the remainder of the ship, the
38 length of the bow, we have overlaid on the figure the
39 distance, and the distance between the bow and the stern of
40 Sydney is approximately 470 metres, which means that it is
41 a relatively compact wreck site in terms of the debris
42 field.

43

44 CMDR RUSH: In relation to the sinking of the ship, is the
45 compactness of the debris site of any significance?

46

47 DR CANNON: We'll probably come to that later. Yes, the

1 compactness of the debris field is one of the indicators
2 that we have to suggest that the bow would have remained
3 intact on the surface and that she separated during the
4 sinking process. We'll come to that later on in the
5 report.

6
7 CMDR RUSH: Does the compactness of the debris site mean
8 anything in relation to the manner in which equipment and
9 material separated from the ship as it sank?

10
11 MR JEREMY: Yes, it does. The compactness also indicates
12 that the sinking was a fairly rapid process and it gives us
13 some idea of which bits of the ship left before others. As
14 we would expect to find, masts and items like that left
15 quite early, and they are further away from the ship, for
16 example, than some other items.

17
18 CMDR RUSH: We have figure 111 on the screen, which is
19 described as the side sonar scan of Sydney. What is
20 detailed on that scan?

21
22 MR JEREMY: This is an image, as Stuart mentioned, from
23 John Perryman's report, and it shows a side scan sonar
24 image of the site of the wreck and the debris field. The
25 Finding Sydney Foundation have marked items which they were
26 able to visually identify. As you can see, right towards
27 the top of the screen, there is the foremast and part of
28 the mainmast, which is quite close to the bow section.
29 There is a funnel also in that area.

30
31 CMDR RUSH: We have the bow section and the main part of
32 the ship.

33
34 I might firstly ask some general questions. Probably,
35 Mr Buckland, they relate to you. We'll come back to the
36 debris field, but in general terms were you able to
37 identify from the wreck site where the torpedo hit Sydney?
38

39 MR BUCKLAND: From the wreck, yes.

40
41 CMDR RUSH: In general terms, how were the marks on the
42 hull as a consequence of the torpedo damage shown?

43
44 MR BUCKLAND: It would be easier if we could bring up the
45 figure, because it shows the indentation in the side of the
46 bow.

1 CMDR RUSH: We might have to wait, then.

2

3 MR JEREMY: This shows the location of the bow of Sydney,
4 and you can see nearby the foremast. There is the base of
5 the mainmast just there (indicating).

6

7 THE PRESIDENT: Perhaps it would be convenient if we went
8 round clockwise from where we are now.

9

10 MR JEREMY: I will do that, certainly. One of the funnels
11 is just nearby. The other funnel is still draped over one
12 of the turrets. There is one of the 4 inch guns. There's
13 a boat, a catapult, a set of torpedo tubes. The supporting
14 structure, the base of the high-angle control system, is
15 there. If we move further down clockwise, we have another
16 set of torpedo tubes and then there are some miscellaneous
17 pieces of debris quite close to the ship. We can see the
18 body of the ship lying there facing towards the bottom of
19 the screen. Just behind the ship, we can see a boat cradle
20 and then a boat lying there.

21

22 We have two boats located there (indicating), then
23 a sole torpedo. There's one identified there as "not
24 seen", which they weren't able to locate with the ROV,
25 I believe. There is another boat. There is the high-angle
26 control centre, from the top of the tower. The director
27 control tower is there with the roof of the bridge lying up
28 against it. Then we have returned to the bow.

29

30 That northern area, which has the bow and those other
31 items, would be fairly close to being underneath where
32 Sydney left the surface. We would expect to see the
33 foremast, possibly funnels and things like that, which
34 would offer considerable resistance to the water but very
35 little strength, to have been removed as the ship plunged,
36 and they are, predictably, lying in that area. The hull of
37 the ship, of course, is a bit further away.

38

39 THE PRESIDENT: The ship, absent the bow, is, as
40 I understand what you just said, facing south-east or
41 south-south-east, if it is north and south up and down the
42 screen?

43

44 MR JEREMY: I'm not certain that that is accurately north
45 and south, but I believe it is approximately so, yes.

46

47 THE PRESIDENT: But for present purposes, the question I'm

1 asking is this: the bow is what we'll call north of the
2 stern?

3
4 MR JEREMY: Yes.

5
6 THE PRESIDENT: Whereas the ship is facing south?

7
8 MR JEREMY: Yes.

9
10 THE PRESIDENT: So the ship, in some fashion, minus the
11 bow, has ended up in a position where the bow is closer to
12 the stern than where the bow was?

13
14 MR JEREMY: That's correct. We have an illustration
15 towards the end of the report that shows how that might
16 have happened in the descent to the bottom. Whilst the
17 extent of the debris field is over a circle of about
18 500 metres, it sounds a lot, but when you look at it in
19 relationship to the depth of water in which she sank, it is
20 actually very compact. The ship was probably maintaining
21 a little bit of forward motion through the water, but that
22 is probably best illustrated by the drawings that we have
23 later on in the report.

24
25 CMDR RUSH: Is it possible, moving on from the debris
26 field, to determine where the bow broke off from the main
27 structure of the ship?

28
29 MR JEREMY: Not precisely, but we would be reasonably
30 confident that it broke off fairly close to the surface.

31
32 CMDR RUSH: You refer to frame 19?

33
34 MR JEREMY: The location on the ship, yes. The separation
35 of the deck we have in the report here at frame 19.

36
37 CMDR RUSH: We will show that in due course. You mention
38 that the bow is inverted on the ocean floor. I think that
39 figure 113 is a photograph of the bow on the ocean floor.
40 Mr Buckland, is there damage that can be seen on the bow of
41 the ship that relates to torpedo damage?

42
43 MR BUCKLAND: Yes. We had to separate the damage from the
44 sinking process of the bow ripping away from the main
45 section of the ship, but if you go to figure 114, in this
46 image here you can see an indentation on the keel of the
47 bow. That's typical of an explosion happening next to the

1 surface. So this would be the very edge of the damage from
2 the torpedo, so this is around frame 19. The actual
3 torpedo hit would be aft of frame 19. We estimate that the
4 actual detonation would have occurred around frame 25.

5
6 CMDR RUSH: Can you tell us what figure 115 depicts?
7

8 MR BUCKLAND: That depicts where the hit on the port side
9 has occurred; where the actual detonation has occurred.

10
11 CMDR RUSH: In the vicinity of that hit, from the ship's
12 point of view, what was the area in and around the frame?
13

14 MR BUCKLAND: The detonation from that explosive - we're
15 talking about 300kg of explosive - would have knocked the
16 plating through into the structure. At that point, we're
17 getting down to the breadth of the ship of about 4 to
18 5 metres. It is close enough to the forward tanks, the
19 fresh water tanks just forward of that hit point, which, if
20 full of water, would have pushed the explosive energy
21 across to the other side of the bow. In the next image,
22 image 117, you will see where the bow has flared out on the
23 other side. If Mike points to where the flaring has
24 occurred, this is the hull on the other side of that hole
25 where we expect that the explosive energy has pushed that
26 out, either transferred through the fresh water tanks or
27 pushed some of the deck through to that spot.

28
29 CMDR RUSH: Are you able to determine whether there was
30 a hole on that side of the ship or whether there was just
31 a bulge?
32

33 MR BUCKLAND: No, we can't determine if there was a hole.
34 Probably more bulging or bending there.
35

36 CMDR RUSH: If I could ask you to go to figure 116, it
37 gives another view of the ship and the torpedo hit. Again,
38 that is another aspect of the ship showing the torpedo hit.
39 The bulge or hole is pretty much opposite that on the
40 starboard side?
41

42 MR BUCKLAND: Yes, directly opposite that.
43

44 THE PRESIDENT: But the torpedo, or its blast, did not
45 penetrate right through the hull on its starboard side?
46

47 MR BUCKLAND: There would have been damage on the

1 starboard side. The amount of damage that is on the
2 starboard side is undetermined.

3

4 CMDR RUSH: We have examined the damage to the hull. Was
5 there damage which could be identified to the internal
6 sections of the ship as a consequence of torpedo damage?

7

8 MR BUCKLAND: If you go to figure 119, this is the view
9 inside the bow section. We see that all the platforms have
10 been removed from that bow section, but that could have
11 been through the sinking process of the actual hull. But
12 there would have been a lot of damage within that structure
13 to some of the decks and some of the watertight bulkheads
14 in that area.

15

16 CMDR RUSH: Figure 120, shows the forecastle deck. Did
17 you consider that there may have been damage rippling
18 through the ship to the forecastle deck as a consequence of
19 the torpedo?

20

21 MR BUCKLAND: We did consider that, but it is more likely
22 that, if you look at the damage, there may have been some
23 damage to that as there was a heaving of the ship, but not
24 from the explosive energy itself. So this would have been
25 more from when it was tearing away in the sinking process.

26

27 CMDR RUSH: From torpedo damage, is there a rippling
28 effect through the structure in the hull of the ship?

29

30 MR BUCKLAND: The general process from a torpedo is that
31 from the explosion you'll get a large hole in the side of
32 the hull. Those bits of hull that have been torn off
33 through the explosive will cause fragmentation, and they
34 will be thrown through that part of the ship and cause
35 extra damage. You will also get, from a large explosion,
36 a push of the water away from the hull. Then that wall
37 will collapse into that hole, so you will get a large
38 generation of water into the hull, and that will cause
39 extra damage as well.

40

41 CMDR RUSH: I might address my next question to Dr Cannon
42 and Mr Jeremy. As a consequence of the separation of the
43 bow from the ship, was there a ripping effect on the ship
44 and, if so, what were the consequences of that?

45

46 DR CANNON: When you say "a ripping effect", are you
47 talking about the global response of the ship or the

1 structure?

2

3 CMDR RUSH: The structure - both, really.

4

5 DR CANNON: Yes, as the torpedo would have hit the ship,
6 certainly the ship would have heaved significantly, as in
7 come out of the water, trimmed by the stern, and then, as
8 she flooded, she would have come slightly deeper by the
9 bows, so that global response would have occurred.

10

11 CMDR RUSH: I think if we look at figure 120, which is on
12 the screen, we have a tear in the forecandle deck on the
13 main hull. That is due to the separation of the bow?

14

15 DR CANNON: Yes. This picture is linked in with some of
16 the other pictures that we will show you later. It
17 indicates that the decks around the keel area have actually
18 been torn away from the hull. If the bow had come apart
19 due to the torpedo, we would have expected some sort of
20 compressive damage or buckling damage, but we don't really
21 identify that. That's one of the key factors that have led
22 us to say that it probably occurred during the sinking
23 process.

24

25 CMDR RUSH: Did you consider whether it could have been
26 caused as a consequence of the detonation in magazine?

27

28 MR BUCKLAND: Yes, we had a look at that, but we can see
29 the actual deck still in place through the main hull
30 section of the magazine, still intact.

31

32 CMDR RUSH: So that, as a consequence, is discounted?

33

34 MR BUCKLAND: That's right.

35

36 CMDR RUSH: If we could look at figure 122, that shows the
37 starboard side of the main hull bent upwards?

38

39 MR BUCKLAND: Yes.

40

41 CMDR RUSH: Was that caused, again, as a consequence of
42 the bow separation?

43

44 MR BUCKLAND: We believe so. There is a lot of damage to
45 the main section of the ship from the sinking process, the
46 tearing and also the final resting on the seabed, so it is
47 fairly difficult to interpret some of the tearing that's

1 there now.

2

3 CMDR RUSH: Going backwards to figure 121, that shows a
4 section of the deck that appears to be wrapped around
5 A turret on the ship. Again, what would be the cause of
6 that?

7

8 MR JEREMY: We think that has occurred during the sinking,
9 but it has been very hard to formulate the mechanism which
10 did that, because the plating has been wrapped around the
11 barrels. Almost certainly, it's a combination of the bow
12 tearing away and the subsequent plunging through the ocean.

13

14 CMDR RUSH: Is the sinking a violent process?

15

16 MR JEREMY: It's an extremely violent process.
17 HMAS Sydney, probably in her final plunge, left the surface
18 in less than a minute and would have dived nose-first
19 towards the bottom of the ocean. The pressure of the water
20 rushing into the open bow would have torn the remaining bow
21 off the ship. In that process - we can't imagine or detail
22 just exactly how this would happen - there would have been
23 significant tearing and breaking of structure. The
24 structure that's left on the hull would have been further
25 distorted and bent by the process of passage through the
26 water towards the bottom.

27

28 CMDR RUSH: Mr Buckland, were you able to determine, in
29 a general sense, the nature of the hole in the port side of
30 Sydney?

31

32 MR BUCKLAND: Yes, from viewing the video evidence,
33 I think figure 124 is the extent of that hole.

34

35 CMDR RUSH: What frames is the hole covering?

36

37 MR BUCKLAND: You can see from frame 19, that's an obvious
38 section that we can identify from the drawings and the
39 actual pictures. So we can identify exactly where frame 19
40 ends. The hole starts at that section, and then the extent
41 is down to almost frame 35.

42

43 CMDR RUSH: The areas within that section of the ship are
44 identified in the diagram?

45

46 MR BUCKLAND: Yes. The section on the hull is near the
47 fresh water tanks and the type 125 gear compartment and the

1 compressor room. You can see that is above the waterline
2 there, so it is probably a fairly shallow torpedo depth.

3

4 THE PRESIDENT: I see that it impinges upon the aviation
5 spirits compartment, which I understand to be highly
6 inflammable.

7

8 MR BUCKLAND: Yes.

9

10 THE PRESIDENT: Do you think that the aviation spirit
11 ignited?

12

13 MR BUCKLAND: No - oh, it's very difficult to say, but
14 that's the extent of the hole in the side. The detonation
15 would have been closer to the type 125 gear room, so the
16 actual explosion was at a distance. That is a mid
17 cut-through, so the aviation spirit room was protected
18 externally by the hull. It could have released aviation
19 fuel into the water that could have caught fire at a later
20 stage, but there wouldn't have been a detonation of the
21 aviation fuel.

22

23 CMDR RUSH: Is the damage consistent with one torpedo or
24 two torpedoes or three, four?

25

26 MR BUCKLAND: It is consistent with one torpedo.

27

28 CMDR RUSH: Apart from that one torpedo, is there any
29 other suggestion of damage by torpedo to Sydney?

30

31 MR BUCKLAND: No other damage.

32

33 CMDR RUSH: You discuss the shell and fragment damage in
34 the report at page 152. Mr Buckland, if I could ask you,
35 firstly, how difficult or easy was it to identify the shell
36 hits, from all of the armament, on Sydney as it lay in the
37 water at this time?

38

39 MR BUCKLAND: We're looking at the ROV footage and the
40 photographs from the Finding Sydney Foundation. The wreck
41 is 2.5km down, so they did a good job of getting the
42 images. However, with silt, and after 67 years of being at
43 the bottom of the ocean, there are other a lot of other
44 damaging processes that have occurred, which we will
45 identify later on in this chapter, but with regard to the
46 actual weapon hits that we could positively identify, as
47 you'll see, they're very clear. In the state that the ship

1 is in now, they're very clear.

2

3 CMDR RUSH: If we look at the summary of weapon damage at
4 table 18, firstly in relation to the port side of Sydney,
5 you have attempted, as far as the location is concerned, to
6 identify the general areas on the port side of Sydney of
7 the 15cm shell hits?

8

9 MR BUCKLAND: Yes, we identified the 15cm shell hits, so
10 we're looking at holes to 15cm. As you'll see from some of
11 the images, it's hard to get the resolution. We're looking
12 at a ship that is 180 metres long.

13

14 CMDR RUSH: When you say you're "looking at holes", does
15 that mean that the shell has detonated or exploded?

16

17 MR BUCKLAND: As you will see in table 18, we have
18 identified contact detonation. There were nose-fuse
19 detonated shells, and they will have large holes or a lot
20 of fragments on the hull surface. There are shells that
21 have clearly just penetrated without exploding on the
22 surface, so they were most probably armour-piercing shells.
23 There are a lot of indentations on the hull, but we have
24 clearly identified ones large enough to be 15cm shells that
25 haven't penetrated, but they have detonated on the surface.

26

27 CMDR RUSH: If we look at this table and, for instance, go
28 across the structure - we will have a look at it more
29 closely very soon - you're looking at and identifying 15cm
30 shell hits specifically in relation to areas of bridge or
31 director control and the like. So there were 17 contact
32 detonations. Perhaps if you would explain exactly what you
33 mean by that?

34

35 MR BUCKLAND: Yes. On this table, we have identified
36 structure, then we have identified the A turret, B turret
37 and catapult. We have separated them with the asterisk,
38 because they are operating structures, so even though
39 they're identified on the port side, operationally they may
40 have been hit from the starboard side at some stage. The
41 structure is both the hull and superstructure, the barbette
42 and some other structures that we have identified as having
43 been hit, and I think you'll see some of the images later
44 on.

45

46 CMDR RUSH: So if we look at "structure", you were
47 satisfied, as best you could be, that 17 detonated on

1 contact; 14 involved shells that penetrated the hull; and
2 2 were shells that didn't penetrate the hull but exploded?
3

4 MR BUCKLAND: Most probably exploded. You will see in
5 some of the images that you can't actually see fragment
6 marks but an indentation where the weapon may have broken
7 up once it hit the hull.
8

9 CMDR RUSH: And "unknown". What is that?
10

11 MR BUCKLAND: It is unknown in that we couldn't identify
12 whether it was a 15cm shell. There were a lot of
13 fragments.
14

15 CMDR RUSH: So we get to 41 15cm shell hits, as best can
16 be identified, on port side. Then the same system was
17 adopted for table 19 of identifying hits on starboard side
18 of Sydney?
19

20 MR BUCKLAND: Yes. In this table, we have the 4 inch gun
21 locker. That's lying on the sea floor. We know that the
22 gun lockers come from the starboard side, but not where
23 that actual weapon has come from.
24

25 CMDR RUSH: In addition to structure, there was a shell
26 penetration of X turret --
27

28 MR BUCKLAND: Yes.
29

30 CMDR RUSH: -- and the director control tower starboard,
31 a torpedo which lay in the debris field and the 4 inch gun
32 locker, so you were able to count 46 15cm shell hits on the
33 starboard side of Sydney?
34

35 MR BUCKLAND: Yes, correct.
36

37 CMDR RUSH: In relation to the other the Kormoran armament
38 fired at Sydney, were you able to identify any damage as
39 a consequence of that armament?
40

41 MR BUCKLAND: There is one area on one external door that
42 could be light arms fire or light-calibre fire, but when
43 you get a look at the images with the corrosion deposits,
44 the small-calibre is 2cm or 3.6cm - we just don't have that
45 resolution with the images.
46

47 CMDR RUSH: Figure 125 gives the location of weapon damage

1 to the port side of the Sydney around B turret.

2

3 MR BUCKLAND: It might be worthwhile looking at the
4 extended diagram of the hull profile first.

5

6 CMDR RUSH: That is at page 317, figure 284.

7

8 MR BUCKLAND: Here we have tried to put the actual
9 measured sizes of each of the holes that we have identified
10 on the port side on to this diagram, so we tried to make it
11 to scale. You will see a lot of little red dots, but each
12 of those red dots are 6 inches in diameter.

13

14 CMDR RUSH: From that diagram, it appears that it is
15 a concentrated fire towards the midships, effectively, on
16 the bow area of the ship?

17

18 MR BUCKLAND: In this case, it's very easy to resolve the
19 hits along the actual hull section. This is the lower and
20 upper decks. If you go from the forward, from the lower
21 mess, there is the hit below A turret there (indicating).
22 Then if you go aft, you have further hits into what is
23 called the ammunition lobby, but we're looking at the
24 surface here, it's penetrated. Below into the lower mess,
25 you'll see a large hole in that watertight bulkhead, so
26 we're talking about a large hole here. This is 1.5 metres.

27

28 CMDR RUSH: A 1.5 metre hole?

29

30 MR BUCKLAND: Yes. That would be a surface detonation.
31 That would have been a contact detonation, so the fragments
32 would have blown a hole in and blown all that damage into
33 the ship.

34

35 THE PRESIDENT: Is it likely that it was caused by more
36 than one hit?

37

38 MR BUCKLAND: No. It was probably just one hit. It is
39 more likely, if there was another hit there, that would
40 have gone through and hit another bulkhead inside that.

41

42 There are lots of shell hits, about four or five shell
43 hits, in the lower mess areas, which we can discuss later.
44 This is where Damage Control 1 would be. Below the
45 superstructure, we have four or five hits into lower
46 mess 4.

47

1 Straight above that we have the recreational space.
2 This is a very hard area to resolve from the photographs,
3 because there was a lot of damage and collapsing from
4 secondary damage, but there was a lot of damage and
5 build-up of silt and other things, so there would be a lot
6 of other shots here that we could not identify. We would
7 presume, just because of the state of the ship. As you go
8 up, you will see some major hits below the director control
9 tower and to the HAC tower.

10
11 CMDR RUSH: The major hit below director control seems to
12 be of the same dimensions that you spoke of with regard to
13 the hole being in excess of --

14
15 MR BUCKLAND: 1.5 metres?

16
17 CMDR RUSH: So that hit also made a hole of that nature?

18
19 MR BUCKLAND: That's right.

20
21 THE PRESIDENT: Would the shrapnel spray from a hit of
22 that nature extend throughout the bridge?

23
24 MR BUCKLAND: Yes. With the shrapnel, in line of sight,
25 it will keep going. Even shrapnel from there, if it was in
26 line of sight and it wasn't stopped, it would even hit at
27 the aft end of the ship. It's just a matter of what's in
28 between that hit. The blast effects from that shell would
29 be probably 4 to 5 metres, so any personnel or vital bits
30 of equipment would be damaged within that radius, but in
31 line of sight, the fragments could extend to the aft of the
32 ship.

33
34 CMDR RUSH: So do I understand that, as a consequence of
35 the detonation of the shell, the shrapnel itself has the
36 potential to spray and spread completely around the ship
37 until stopped?

38
39 MR BUCKLAND: Until stopped. If you look at a lot of the
40 surface detonations, even though they haven't penetrated,
41 the fragment spray would have sprayed the external section
42 with anything in the water around those shell hits.

43
44 CMDR RUSH: I know we'll come to this later in the report,
45 but the fragments themselves, I understand, are hot?

46
47 MR BUCKLAND: They're hot, yes.

1
2 CMDR RUSH: Are they capable themselves of creating fire?

3
4 MR BUCKLAND: If they lodge into a flammable material,
5 they will cause a fire. They will generate a fire. They
6 will pass straight through without transferring the heat to
7 most things, but once they lodge into the flammable
8 material, the fire will be created.

9
10 So as we move aft, you will see there are more major
11 hits in the ship's galley area. There is a large amount of
12 damage there. Then below that, we're into the telephone
13 exchange area. What's important about this area is that
14 you have the transmitter station and the HA calculation
15 area below these hits, and the main switchboard room.

16
17 With these hits that penetrated in, it would be likely
18 that they would be detonating inside the ship itself, so
19 the compartments inside there are going to be damaged and
20 create fires, so we're likely to lose any communication to
21 the transmitting room from the bridge and the director
22 control.

23
24 If we go back up, you'll see the hits below the smith
25 shop. You will see that this is around where some of the
26 boats are.

27
28 As we go aft, again, even though we have a collection
29 of shots near the bakery, between the bakery and the galley
30 you will see that there aren't any large detonation areas,
31 but the image can't be resolved underneath that deck, below
32 that other boat where the seaplane crane is. It is likely
33 that there are hits in there, but the ROV couldn't see
34 underneath into that area.

35
36 As we move further aft, you will see two hits onto the
37 catapult and another hit into the engineering workshop
38 where Damage Control 2 would be set up.

39
40 CMDR RUSH: And aft of the hit?

41
42 MR BUCKLAND: Going further aft, we have a hit on
43 X turret, on the port part of that gun. However, it is
44 unlikely that the gun was pointing in that direction at the
45 time, so we have assumed that that was probably a starboard
46 shot, in the end. I will explain that later.

47

1 As we go further aft, you will see that there are no
2 other hits further aft than that that we could identify.

3
4 CMDR RUSH: Was the shell hit to the catapult the most, if
5 you like, aft hit on port side?

6
7 MR BUCKLAND: It was the most-aft hit, but I should
8 explain that on Y turret there is a lot of debris. One of
9 the funnels is lying across Y turret. We can see some of
10 Y turret but we can't see the entire Y turret, so we have
11 not identified whether there is any damage there.

12
13 THE PRESIDENT: It may have been hit as well?

14
15 MR BUCKLAND: It may have been hit, but it is covered by
16 one of the funnels.

17
18 CMDR RUSH: Can we turn to figure 285 and adopt the same
19 process, Mr Buckland, from forward to aft?

20
21 MR BUCKLAND: You will see these large hits on starboard
22 side of A turret. Once you see the image of where the guns
23 are now, you will see that obviously the guns weren't
24 pointing towards Kormoran at this stage and it was hit
25 directly on there. We have calculated that that was when
26 the Kormoran was firing over the bow of Sydney, so the guns
27 were pointing away from the page.

28
29 CMDR RUSH: Could I ask one question unrelated to the
30 shell fire. Is it your opinion that the torpedo damage
31 caused any damage to A or B turrets and the capacity of
32 those turrets?

33
34 MR BUCKLAND: Definitely to A turret. The A turret would
35 have lost all power and operation. B turret possibly.
36 Very likely, but possible. We can't really give
37 a 100 per cent guarantee on that. Just from the shock, as
38 the boat lifted up and down, it would have lost that, plus
39 you could have been losing power. We are talking about
40 a ship that has old technology, so it didn't take that much
41 shock to break circuits and stop the power.

42
43 As we come back aft, there are again hits in the lower
44 mess areas. Again, this is where damage control would be
45 setting up to do action for the bow damage, the torpedo
46 damage, yet it has still been hit there and up in the
47 seamen's heads, above, in that recreational space. Again

1 with regard to some of the damage around the superstructure
2 area, because of the state of the ship at the moment, it is
3 hard to get resolution on some of the hits.
4

5 There are further hits again to the director control
6 tower. Then you'll see that there is a large concentration
7 of hits around the stokers' mess, the ship's galley and the
8 forward boiler room. Here we have the forward boiler room.
9 That has been hit. As we come back further, we have hits
10 around the engineering workshop, again where Damage
11 Control 2 would be.
12

13 You will notice that all these hits are above the
14 waterline. Then around the aft boiler room. In our
15 appendix to this report, each of these hits has been
16 identified and measured. We know that the starboard
17 torpedo pods have been hit, but how that was positioned at
18 the time we are uncertain. Then we have hits to the main
19 W/T office and the fan chamber.
20

21 As we come further aft, there is another hit to the
22 officers' galley. Then the most-aft hits are near the
23 senior officers' cabin and the captain's cabin.
24

25 CMDR RUSH: Again, what is the size, for example, of the
26 depiction of the shell hit to the main W/T office?
27

28 MR BUCKLAND: That would be a contact fuse again. I think
29 that is about 600mm to 800mm diameter. Again, the same
30 thing with Y turret; it's difficult to see all of Y turret
31 to know whether any hits have hit the Y turret, but there
32 is no further damage aft.
33

34 CMDR RUSH: You mentioned that each one of the shell hits
35 was examined and measured and that that is picked up in an
36 appendix to the report. I wonder if we can get an idea of
37 what you mean there. I think it is found at page 315 of
38 the report.
39

40 MR BUCKLAND: We put a proviso on these measurements in
41 that we needed to take bits of structure where we could
42 identify what the actual thickness, width and diameter was,
43 and then compare that to the actual shell hole, so we
44 needed some structure for which we knew what the
45 measurements were to be able to measure that.
46

47 CMDR RUSH: Perhaps if we could look at figure 288 on

1 page 322. That is a photograph that has been identified as
2 depicting B turret. Can you indicate to us what you did in
3 relation to identification of the 15cm shell hit on
4 B turret?

5
6 MR BUCKLAND: On B turret, you will see it identifies
7 P01FB03. That is the port side.

8
9 CMDR RUSH: So that is a hole --

10
11 MR BUCKLAND: The hole has been hashed over. You will see
12 the damage around that hole where the plating has been bent
13 into the hole. For that hole size, we've taken
14 a measurement based on the sighting flaps of the gun. We
15 have measured that it is probably 5 inches in diameter, so
16 the possibility is that the weapon didn't totally penetrate
17 in this case.

18
19 You will see that further down, next to the barbette,
20 there's a large hole below the barbette and damage to the
21 barbette. Again, we have identified that this would have
22 damaged the ring gear to the barbette and stopped the gun
23 from operating. You will see that that is a very large
24 hole, 6 feet.

25
26 CMDR RUSH: If we look at figure 289, this is a hole in
27 the lower deck at number 2 and number 3 lower mess deck?

28
29 MR BUCKLAND: You will see that this hole has been
30 measured at 6 feet by 3 feet, so it's a very, very large
31 hole. To the right-hand side of that photograph, is part
32 of a scuttle that has been taken in with the damage. So
33 that is not part of it; that just continues on from the
34 weapon damage. In this case, the weapon would have
35 detonated on contact, but fragments and that hull plating
36 would have been thrown through the ship, causing damage
37 throughout the ship directly behind that hull plate.

38
39 THE PRESIDENT: So you have used a CAD system, calibrated
40 against known measurements, and used it to measure the
41 penetrations?

42
43 MR BUCKLAND: That's right and because of where the ship
44 is sitting at the moment, these are approximate, but they
45 give us some idea of what the holes are and the sizes.

46
47 CMDR RUSH: I'm not going through every one, Mr Buckland,

1 but each shell hole was identified and a description given.
2 There are a couple that I will take you to. The first is
3 at figure 306. There identified is the lower bridge area
4 of the ship.

5
6 MR BUCKLAND: Yes.

7
8 CMDR RUSH: What do we see there?

9
10 MR BUCKLAND: This is clearly a 6 inch by 6 inch, so you
11 would expect that that was caused by the 15cm shell
12 penetrating directly in there without exploding on contact,
13 and either it contacted inside, or, even if the fusing
14 didn't work, we're talking about shells that are hitting
15 the shell plate at over 400 metres per second, 40kg of
16 shell - there's a lot of secondary damage from the
17 fragments that are being generated just from that striking,
18 going through that plate, so there is a lot of secondary
19 fragmentation, anyway, as it crashes through the ship.

20
21 CMDR RUSH: So even if there was no explosion on contact,
22 there would be secondary damage as a consequence of the
23 forces applied by the shell?

24
25 MR BUCKLAND: Yes. It would have generated a lot of
26 secondary fragments.

27
28 CMDR RUSH: Figure 307 is again, as I understand it, port
29 side damage, this time to the director control tower.

30
31 MR BUCKLAND: Yes. And, again, we have identified that as
32 7 inches, so that would have been another hole that has
33 penetrated directly into the control tower. At this stage,
34 we expect that the director control tower wasn't
35 operational.

36
37 CMDR RUSH: May we look at a couple of photographs on
38 starboard side. First, if we look at figure 318, is this
39 on starboard side lower deck?

40
41 MR BUCKLAND: Yes. You will see several holes here. The
42 one identified as S2FB06 is clearly a 6 inch hole, and with
43 the larger contact detonation - you will see there is very
44 large, ragged damage in this area that has torn through
45 into that section. Then there are two other fine holes
46 below that which are just identified as maybe fragment
47 damage from that weapon.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

CMDR RUSH: The lower mess and upper deck seamen's mess area?

MR BUCKLAND: Yes.

CMDR RUSH: If we look at the next figure, 319?

MR BUCKLAND: This is on the starboard side of the upper bridge area. As you can see in this photo, there is a lot of damage and lots of rusticles, which will be explained later, on the surface of that plate, so if there are any holes underneath that rusty looking area, it's impossible to see them, as you can see. However, on the top, you will just see that there's the edge up there where there has been obviously a ripping away as the shells ripped through and detonated. We will need to go to the video to see more of that image there.

CMDR RUSH: The next figure, 320, is a reconstruction of the Sydney bridge.

MR BUCKLAND: That was the area that you were just looking at. We have tried to put in some reconstructions just to show what areas you are actually looking at, because with the state that the ship is in now, sometimes it is difficult to see. That area that we were just looking at is that (indicating), and the damage is just below the range finder.

We are indicating here that any weapon hit up there would have taken out the personnel in that area.

CMDR RUSH: And in relation to the ship as reconstructed, as we saw yesterday on the video imagery, were you able to use that to work out matters such as you've spoken about - the location of personnel?

MR BUCKLAND: Yes, within our vulnerability code we have positioned crew members around, and using our algorithms we can actually calculate who has been incapacitated and what equipment has been damaged.

CMDR RUSH: Perhaps I might ask Mr de Yong this question: those that have seen the photographs on the Finding Sydney website and looking at these photographs may see a difference in the clarity in the imagery. Can you

1 explain that difference?

2

3 MR de YONG: Yes. With regard to the photos that were
4 supplied to us to work with, we have simply passed the
5 images and the video footage through a red filter. There's
6 a loss, there's an absorption, with depth in terms of the
7 red part of the spectrum that tends to cause images taken
8 underwater to have a bluish colour associated with them,
9 which tends to destroy the clarity and the features of the
10 images. So these images have been processed by passing
11 them through a standard red filter that is in a standard
12 commercial Photoshop package. They bring the clarity and
13 the original colour back into the images.

14

15 CMDR RUSH: Mr Buckland, can I ask you to go back to
16 page 159 of the report and figure 134. You mentioned the
17 use of the reconstruction to explain where the damage to
18 the ship was?

19

20 MR BUCKLAND: Yes. There is a series of images in the
21 report which show the reconstruction of the Sydney and
22 identify parts of the images from the Finding Sydney
23 Foundation and where they were originally located. As
24 you'll see there, the director control tower on the
25 left-hand side - that is now sitting on the seabed. That
26 is not part of the ship, the main part of the ship, any
27 more.

28

29 CMDR RUSH: So what these images are doing is, as I
30 understand it, using the photographs and then the
31 computer-imaged ship to indicate areas of shell hits to the
32 particular structure?

33

34 MR BUCKLAND: It is actually showing a confirmation of
35 shell hits, fire damage and just the general state of the
36 ship as it lies at the moment, just to give some idea of
37 the state of the ship as it now sits on the seabed.

38

39 CMDR RUSH: So what we're looking at there is the forward
40 superstructure on starboard side?

41

42 MR BUCKLAND: That's right.

43

44 CMDR RUSH: If we can go through some of these images,
45 firstly figure 135, what do we see there?

46

47 MR BUCKLAND: This is the forecastle deck. I'm not sure

1 how good the resolution is. The upper left-hand photo
2 shows the --

3

4 MR JEREMY: It is just forward of the flag deck. It shows
5 the location of one of the 0.5 inch machine guns.

6

7 CMDR RUSH: And, again in general terms, you have placed
8 the photographs in a position with arrows showing the
9 general nature of damage to the ship?

10

11 MR BUCKLAND: Just so you can locate that photograph and
12 where it is in relation to the ship. It gives you an idea,
13 especially on the right-hand side in those three
14 photographs, of the difficulty on the forecastle deck, even
15 though there are a lot of holes, of identifying any other
16 damage than the ones we have positively identified.

17

18 CMDR RUSH: If we look at the photographs on the
19 right-hand side, the upper right-hand photograph and the
20 bottom right-hand photograph show doors are open.

21

22 MR BUCKLAND: That's correct.

23

24 CMDR RUSH: Is it possible to determine how they were
25 opened or whether that would have been as a consequence of
26 damage or not?

27

28 MR BUCKLAND: No. It is almost impossible. We tried to
29 look at the dogging and whatever else, but we have no idea.
30 In the second picture, you will see that there are clearly
31 fragment holes coming from the door. At this point, the
32 fragments would be going inside the door, but it's open, so
33 it has been opened after the action has started.

34

35 THE PRESIDENT: Either by man or by blast - you can't
36 tell?

37

38 MR BUCKLAND: We can't tell. We would expect that it
39 would be opened by man, in that the fragment holes are
40 going inside and then it has been pulled out, so - unless
41 there was another weapon that did it.

42

43 CMDR RUSH: We are looking there at the forward upper and
44 lower decks starboard. Is there evidence of fire damage
45 demonstrated in those photographs?

46

47 MR BUCKLAND: Yes, you will see the discolouration of the

1 blue to what's now a grey colour, and that discolouration
2 is identified as fire damage, just from the internal heat
3 burning the paint off the surface.

4
5 CMDR RUSH: With regard to the second photograph on the
6 left, is what we see there in that discolouration what is
7 identified as fire damage?

8
9 MR BUCKLAND: That's right.

10
11 CMDR RUSH: Again, in the photograph directly under the
12 image, is it your opinion that that also is fire damage?

13
14 MR BUCKLAND: That is. I would rather our fire expert
15 answer some of the questions on the fire damage.

16
17 CMDR RUSH: Okay. If we go to figure 137, again this is
18 port side now?

19
20 MR BUCKLAND: That's right.

21
22 CMDR RUSH: It shows the forward superstructure of port
23 side and, again, the arrows pointing to the general areas
24 of the damage?

25
26 MR BUCKLAND: The general areas. You will see some
27 secondary damage, which Dr Cannon and Mr Jeremy will talk
28 about later on - some of the sinking damage that has
29 occurred. Again, you will see where there has been some
30 fire damage and weapons damage.

31
32 CMDR RUSH: If we go to figure 139, we're looking there at
33 the smith's shop on port side?

34
35 MR BUCKLAND: That's right.

36
37 CMDR RUSH: We probably won't come back to this, so I'm
38 going to ask for your opinion: is that discolouration, in
39 your opinion, fire damage?

40
41 MR BUCKLAND: Yes. You will see there's weapon damage
42 there. Once we get to another photograph, you will see
43 that there are fragment holes in that area.

44
45 CMDR RUSH: And figure 141. You are there relating the
46 photographs back to the --

47

1 MR BUCKLAND: Back to the damage near the crane area and
2 also near where some of the boats were sitting.

3
4 CMDR RUSH: Is that on port side?

5
6 MR BUCKLAND: On port side. This is around the midships
7 area.

8
9 CMDR RUSH: And in figure 143, you are looking there on
10 starboard side, the aft deck?

11
12 MR BUCKLAND: Yes, this is the starboard side, and we
13 start seeing some of the decking in this photograph and
14 also some of the collapsed deck, which I think Dr Cannon
15 will explain a bit later.

16
17 CMDR RUSH: In figure 144, again, we have the aft upper
18 decks on port side - the other side to the figure we've
19 just seen?

20
21 MR BUCKLAND: That's correct.

22
23 CMDR RUSH: Sir, I will come back with other experts to
24 talk about fire damage.

25
26 THE PRESIDENT: Yes.

27
28 CMDR RUSH: Could we turn, Mr de Yong, to page 171 of the
29 report to consider the ship's boats and Carley floats and
30 look at the potential damage to them. Were there any
31 Carley floats found in wreckage or the debris field?

32
33 MR de YONG: There was no evidence of any Carley floats on
34 the seaboard or remaining on board the remnants of the
35 hull.

36
37 CMDR RUSH: From the original position that we saw
38 yesterday of the ship's boats as of November 1941, were any
39 in their original position?

40
41 MR de YONG: No. There were no boats retained with the
42 main structure of HMAS Sydney. Any boats that we were able
43 to identify were found in the debris field.

44
45 CMDR RUSH: Was there anything to identify the cutters?

46
47 MR de YONG: There was no evidence of any of the cutters.

1 We found five boats in the debris field. They were
2 identified as the two whalers, the two motorboats and the
3 pinnace. There was no evidence of any of the cutters being
4 present in the debris field.

5
6 CMDR RUSH: And the 16-foot jolly?

7
8 MR de YONG: There was no evidence of that, either.

9
10 CMDR RUSH: In relation to the boats that were found in
11 the debris field, had there been a deterioration, as
12 a consequence of the effluxion of time, on the
13 construction?

14
15 MR de YONG: There was certainly a varying degree of
16 deterioration. Some of the boats had deteriorated
17 significantly. What you see on the screen at the moment is
18 one of the motorboats. It shows a degree of deterioration,
19 but there are two motorboats, and one of the motorboats
20 shows very little deterioration. I'm talking about the
21 exterior of the boat at this stage. In all the boats that
22 we found on the seabed, all the interior had significantly
23 deteriorated, all the equipment, particularly for something
24 like the pinnace, the propulsion system and all those sorts
25 of internal structure, had all disappeared. It had all
26 fallen out presumably during the sinking process.

27
28 But there is no question about the fact that some of
29 the boats had deteriorated significantly, some had shown an
30 extreme resilience to deterioration on the seabed, and in
31 fact it is because of the deterioration that it is very
32 difficult to identify with great certainty the degree of
33 fragment damage to the boats, because the fragment damage
34 would have been a point where deterioration would possibly
35 have started. So since the deterioration could have been
36 significant, there is no evidence that the fragment damage
37 was the point of commencement of that deterioration, but it
38 is highly likely that it was.

39
40 CMDR RUSH: Was there any difference in deterioration
41 between the boats that were carvel constructed as opposed
42 to boats that were clinker constructed?

43
44 MR de YONG: Yes. That was one of the main
45 differentiation processes between the two different types
46 of boats. The carvel boats have a smooth outer planking,
47 whereas the clinker boats have a rough outer planking. The

1 carvel boats showed significantly less deterioration, as
2 a general statement, than the clinker-built boats.

3

4 CMDR RUSH: On the screen at the moment is figure 147,
5 which is the 35-foot motorboat.

6

7 MR de YONG: That's correct.

8

9 CMDR RUSH: If we go to figure (a), in relation to that
10 damage, what we are seeing there is general deterioration
11 of the boat. Is there anything specific in relation to
12 that, apart from it appearing to be broken in two?

13

14 MR de YONG: As you say, you can see the physical
15 deterioration to the outer planking. Although being
16 a carvel-built boat, still part of it is quite intact. The
17 interesting thing about this boat is that the damage that
18 you are seeing there, the significant damage that appears
19 to be in the centre of it, seems quite at odds with what
20 you would expect from a weapons engagement. My opinion is
21 that that damage was not as a consequence of any weapons
22 damage.

23

24 Interestingly enough, the ship's catapult is lying
25 almost next to it on the seabed, and my opinion is that
26 during the sinking process, the catapult actually hit this
27 boat and caused that damage.

28

29 CMDR RUSH: In photograph (c), you have identified by
30 arrow possible fragment impacts. Is that done with any
31 degree of certainty?

32

33 MR de YONG: No. They're possible areas where fragment
34 impact may have occurred. It's very difficult to identify
35 fragment impact, particularly on a boat that has been
36 sitting at the bottom of the ocean for such a long period
37 of time and with such deterioration.

38

39 CMDR RUSH: If we could look at figure 148, this is the
40 other motorboat?

41

42 MR de YONG: This is the other motorboat. The motorboats
43 were both on the starboard side, so both these boats were
44 from the starboard part of the ship. Again, it's an
45 identical construction, and, interestingly enough, you can
46 see that it's in much better condition. You can see that
47 the insides are missing, as I noted earlier. There are

1 some remnants of some of the interior engine drive system,
2 but most of it is missing.

3
4 The outer planking is in extremely good condition, and
5 there is limited fire damage to this particular boat.
6 There are sections that have rotted out because the ship is
7 lying partially on the seabed, and the silt has caused some
8 rotting, but it's in remarkably good condition.

9
10 CMDR RUSH: If we could look at the two images on
11 page 175, which is perhaps figure 149, what are we looking
12 at there, Mr de Yong?

13
14 MR de YONG: This is the pinnacle and one of the whalers.
15 Since the pinnacle was on the port side, my assumption is
16 that this is the port side whaler. The pinnacle, again, is
17 in reasonable condition. There are some later images that
18 show some little more detail, but, again, the inside
19 structure has been completely destroyed. Again, I assume
20 a lot of it is a case of the equipment falling out during
21 the sinking process.

22
23 As you can see, the whaler has very little of the
24 outer planking intact because it's a clinker-built boat.
25 One would expect the outer planking to deteriorate much
26 faster than that on the carvel-built boat. The interesting
27 thing about the whaler is that there appears to be fairly
28 significant damage where those two arrows are pointing. It
29 doesn't appear that the damage has been due, in my opinion,
30 to some form of physical effect, as we saw earlier with the
31 ship's catapult being proposed to cause the damage;
32 I believe this damage was caused by a weapons hit.

33
34 CMDR RUSH: At figure 149, the images there are initially,
35 if we look at (c) at the top --

36
37 MR de YONG: Item (c) is the edge of that hole that
38 I believe was caused by weapons hit and you can clearly see
39 that it has caused fire damage to the boat. You can see
40 the blackening of the remaining structure of the boat
41 itself. You can see that on the boat's badge, the paint
42 has been burnt off. If you look at the image, that's
43 correct, in that area there, there's clear evidence of fire
44 damage.

45
46 CMDR RUSH: Was the pinnacle located on the port side of
47 Sydney?

1
2 MR de YONG: Yes, it was.

3
4 CMDR RUSH: My recollection is that there was a whaler on
5 each side of Sydney?

6
7 MR de YONG: There was a whaler on both sides, that's
8 correct, so I am assuming this is the port whaler.

9
10 CMDR RUSH: If we go to figure 150, this is a whaler
11 different from the one we've just looked at on the seabed?

12
13 MR de YONG: That's correct. This is the second whaler.
14 Because the other whaler, I believe, was with the pinnacle
15 and so therefore was the port whaler, my assumption is that
16 this is the starboard whaler we're looking at here.

17
18 CMDR RUSH: The cradles and davits for the boats - we're
19 looking at davits for the cutters and cradles for the other
20 boats. Was there any sign of either in the wreckage?

21
22 MR de YONG: The davits for the two cutters - there is no
23 evidence of the davits at all. If we go to figure 151, we
24 will see the starboard davit. These are the davit holders.
25 There is no davit present. You can see extensive shell
26 damage around this area. You can see weapons hits, that's
27 correct, right in those two positions there.

28
29 As we've seen previously from Mr Buckland, there was
30 extensive damage around the cutter davit area, and, in my
31 opinion, the davits would have been destroyed, and with the
32 davits being destroyed, the boats would have been blown
33 overboard. That would have happened during the encounter,
34 which means that they would never have been found in the
35 debris field.

36
37 CMDR RUSH: Figure 154 is the port side cradle for the
38 gig.

39
40 MR de YONG: This is the cradle on the port side for where
41 the gig used to be. There were two Carley floats on top of
42 this support cradle. You can see that there are clear
43 weapons hits to the structure. You can see clear physical
44 tearing apart of the structure here, whether due to blast
45 or secondary fragmentation, or whatever, but it tends to
46 indicate that the Carley floats that would have been
47 sitting directly above this would have been extensively

1 damaged.

2

3 CMDR RUSH: If I can ask you to go back to figure 152,
4 which is referred to as the starboard side end of the
5 27-foot whaler cradle, again there are pointers there to
6 weapons damage?

7

8 MR de YONG: Yes, three significant shell hits to the hull
9 of the ship, which would have, as Mr Buckland has alluded
10 to so far, produced and generated very large numbers of
11 fragments, so the whaler that would have been sitting on
12 that cradle would have been extensively damaged.

13

14 CMDR RUSH: Finally, to figure 155, which is the holes
15 around davits for the port cutter?

16

17 MR de YONG: This is the forward locating hole for the
18 port cutter. Certainly, the davits are completely gone.
19 There is extensive weapons damage or shell damage at this
20 point here, and there's some potential fire damage as well.

21

22 If you go to figure (b), this is the aft davit holder.
23 You can see a very, very large shell hole right there right
24 by the davit. That would have blown the davit off very,
25 very quickly and it would have taken the boat with it.

26

27 CMDR RUSH: Sir, if we turn to other structural damage to
28 Sydney and the separation of the bow, I think we're
29 referring to Mr Jeremy and Dr Cannon: was the torpedo
30 responsible for the removal or separation of the bow?

31

32 MR JEREMY: Ultimately, yes.

33

34 CMDR RUSH: We'll come to it, but your opinion is after
35 sinking?

36

37 MR JEREMY: After sinking, yes.

38

39 CMDR RUSH: Figure 156. This is the forecastle deck.
40 Could you explain to us what is being referred to there?

41

42 MR JEREMY: This shows what is left of the forecastle deck
43 on the ship and the line of the tears in the deck plating.
44 As you can see, most of those tears follow the riveted
45 seams in the plating and, in some cases, are very close to
46 riveted butts as well. This suggests tearing of that
47 structure and the failure of the rivets.

1
2 Next to the barbette of A turret, there are a couple
3 of tears which may have occurred a little bit later on,
4 either during the sinking process or when the ship actually
5 hit the bottom.

6
7 CMDR RUSH: So if we were to look at a line across the bow
8 of the ship as to the point of separation, is it possible
9 to --

10
11 MR JEREMY: Yes. You can see just forward of my red lines
12 there, there is actually the end of the timber planking on
13 the deck, across at that level there (indicating), and
14 that's very close to where the ship actually separated.
15 These tears are fairly accurately located from the
16 remaining fairlead and other deck fittings, which we can
17 see in the photographs, but there is likely to have been
18 a bit of localised tearing around the bow section as well
19 as it descended to the bottom.

20
21 CMDR RUSH: And figure 157?

22
23 MR JEREMY: This is a piece of shell plating which has
24 been ripped from the ship during the descent to the bottom.
25 It shows two side scuttles, one of which is an original
26 one, and the other one which had been blanked. That was
27 done during the War to reduce the risk of flooding to the
28 ship. The side scuttles in Sydney which were blanked were
29 those below the upper deck, so that's a piece of shell
30 plating - we can't be certain from which side of the ship -
31 between the lower deck and the upper deck.

32
33 CMDR RUSH: You spoke earlier about the sinking being
34 a violent process. Is it the sinking itself that has
35 caused that deformation?

36
37 MR JEREMY: Very likely, yes.

38
39 DR CANNON: There is also a significant amount of the side
40 plating that we haven't been able to identify, so there's
41 the plating that stops on the stern section of the ship,
42 that starts on the bow, and then there's a segment of
43 plates that are in the debris field that we can't identify.
44 So they would have been torn away.

45
46 MR JEREMY: There are some significant targets in the
47 sonar image which were not sighted by the Finding Sydney

1 Foundation, and it's quite possible that some of those are
2 some of these missing sections.

3
4 CMDR RUSH: Was there implosion damage to Sydney?

5
6 MR JEREMY: Yes, extensive implosion damage. Perhaps if
7 we go to some of the images.

8
9 CMDR RUSH: Firstly, figure 159, but before we look at
10 that, can you explain to us what implosion damage is, how
11 it occurs?

12
13 MR JEREMY: If you like to think of an aluminium drink can
14 which is empty which you then squeeze from the outside and
15 it crushes, this is a very similar process. As Sydney
16 sank, the evidence suggests that she probably plunged very
17 rapidly by the bows, the stern probably up into the air,
18 and then dived. As she dived through the water, the
19 compartments in the ship which still had a lot of air in
20 them or were completely intact would have been subject to
21 increasing water pressure from outside, and quite rapidly
22 that would have exceeded the strength of the structure to
23 resist crushing. In many instances, of course, they start
24 to flood very quickly from water getting in through air
25 escapes and ventilation trunks or open hatches, but the
26 sinking would be so rapid that the air would not be able to
27 get out fast enough and the structure would collapse
28 inwards, and there's extensive evidence that this has
29 occurred on Sydney.

30
31 CMDR RUSH: At figure 159?

32
33 MR JEREMY: This is towards the forward end of the major
34 implosion area and it's on the starboard side looking
35 slightly forward, and it is beside the aft deckhouse. You
36 can see a bollard there on the side. There's an awning
37 stanchion bent over just before it. That has probably been
38 bent by debris as the ship sank. You can see just a little
39 bit forward of that, the ship's side is bent in a bit.

40
41 If you look at the silt-filled area between there and
42 the deckhouse side, that's about the forward end of the
43 imploded section. You can see that the bollards are bent
44 in a little bit. In actual fact, we think that the whole
45 after deckhouse has slumped a little bit down, but that may
46 have occurred when the ship hit the bottom.

1 CMDR RUSH: The photo may not depict what your opinion is,
2 but are we just looking at a couple of inches or?
3

4 MR JEREMY: No, we are talking about six frame spaces, and
5 the frame spacing is three feet, so we are talking about
6 18 to 20 feet of the ship there.
7

8 CMDR RUSH: That suffered implosion damage?
9

10 MR JEREMY: No, the total length of the ship that suffered
11 implosion damage is approximately from the forward end of
12 that photograph right to the stern.
13

14 CMDR RUSH: But on that photograph, in relation to what
15 appears to be the downward movement, for want of a better
16 term, caused by implosion damage, are you able to estimate
17 how far down it is?
18

19 MR JEREMY: The depth of the implosion? Yes, on the
20 quarterdeck we can. If we look perhaps at figure 160, you
21 can see there that that is the capstan which was sitting on
22 the deck, the quarterdeck, and the deck has been imploded
23 downwards. The ship's side, there on the starboard side
24 where the bollard is, has been bent inwards. The bollards,
25 of course, are quite distorted from their normal location.
26 I would estimate that that has probably dropped about half
27 between-deck height, so it has probably gone down 4 or
28 5 feet into the next deck down.
29

30 CMDR RUSH: What we're looking at in that photograph is
31 the timber decking of the ship in the background?
32

33 MR JEREMY: Yes.
34

35 CMDR RUSH: At figure 161?
36

37 MR JEREMY: This shows the very stern of the ship. There
38 are further examples here of implosion. You can see the
39 side shell plating right at the stern has been forced
40 inwards. Part of that side shell plating there, I think,
41 is a temporary repair which was carried out to some damage
42 which occurred to the ship when coming alongside in
43 Fremantle some time in the previous year, but there is
44 clear evidence there of implosion, and you can see the deck
45 plating is bent right in and the ship's side has been drawn
46 in as well.
47

1 CMDR RUSH: Is figure 162 a diagram of the implosion area
2 based on the drawings of the ship?
3

4 MR JEREMY: Yes, that is. That shows the approximate
5 extent of the imploded upper deck aft and it also shows the
6 location of two considerable splits in the upper deck right
7 beside Y turret, which may have occurred during the
8 implosion or may also have occurred during the impact with
9 the sea floor.

10
11 THE PRESIDENT: Does implosion damage occur when the water
12 pressure exceeds the structural strength of the ship plus
13 the internal air pressure?
14

15 MR JEREMY: Yes.
16

17 DR CANNON: It's a combination, as John mentioned earlier.
18 There will be intakes that air can either come in or out
19 of, and it's dependent upon the speed at which water can go
20 in. If water goes in at the same time as the load created
21 by the sinking process, then it won't implode. If it's
22 much slower, then it will.
23

24 THE PRESIDENT: Thank you.
25

26 CMDR RUSH: In general terms, from what we have looked at,
27 Mr Jeremy, earlier in relation to torpedo damage and
28 sustained shell damage forward of the ship, the area of
29 implosion damage was relatively free of battle damage?
30

31 MR JEREMY: Yes, it is relatively free, as far as we can
32 tell, yes.
33

34 CMDR RUSH: In relation to its ability to maintain
35 watertight integrity, is that, if you like, demonstrated by
36 that diagram?
37

38 MR JEREMY: Yes. It suggests that most of the aft section
39 of the ship was probably still full of air when the ship
40 left the surface, so it was probably not subject to any
41 major flooding.
42

43 CMDR RUSH: Sir, is that a convenient time?
44

45 THE PRESIDENT: Yes, we will take a brief adjournment.
46

47 SHORT ADJOURNMENT

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

CMDR RUSH: At page 187 of the report you deal with the damage sustained by the ship on impact with the seabed.

MR JEREMY: Yes.

CMDR RUSH: That is perhaps demonstrated at figure 164?

MR JEREMY: Yes, it is. Sydney appears to have landed in a sandbank or an area of silt, so some of the interesting areas to look at to judge just how she hit the bottom are hidden. But there is some evidence of impact damage around the stern.

In my opinion, it is quite possible that the first bits of the ship to actually hit the bottom were the rudder and the cut-up where the keel comes up towards the stern, so that has contributed to the damage to the stern.

CMDR RUSH: Perhaps if we go to figure 165?

MR JEREMY: This shows the port inner propeller of Sydney. As you can see, it is partly buried in sand or silt. It looks actually like sand. The A bracket has broken away from the hull.

CMDR RUSH: Could you point to where the A bracket is?

MR JEREMY: That's it there (indicating). The upper arm of the A bracket has fractured. You can see the end of the fracture of the A bracket. It is very hard to see in this image, but you can see the broken end of the A bracket arm on the ship (indicating). As you can see, that propeller shaft has been bent outwards from the hull during the impact. It has also been partly withdrawn, because that propeller should be right up against the A bracket, so it's likely that either the A bracket has moved forward or the propeller shaft has been partly withdrawn during the impact with the sea floor.

CMDR RUSH: And figure 166?

MR JEREMY: This shows a bend in the starboard bilge keel. In this area, there appears to be less sand and it is quite possibly a solid rocky bottom, so the ship has sat down with a significant thump. There is also evidence in this photograph of some collapse of the shell due to implosion.

1 The next two images show the area affected on the starboard
2 side where the shell has collapsed. It is approximately in
3 that region (indicating) and it appears as if the
4 watertight compartments in that area have collapsed through
5 implosion during the sinking.

6
7 CMDR RUSH: So what is demonstrated there is an area of
8 implosion damage?

9
10 MR JEREMY: That is an area of implosion damage. The bend
11 in the bilge keel is almost certainly as a result of
12 hitting the bottom.

13
14 CMDR RUSH: And at figure 168?

15
16 MR JEREMY: Figure 168 is a section through the ship
17 showing that area of implosion, and the spaces just
18 immediately inside that red line are in fact watertight
19 compartments in the double bottom, which would have been
20 completely sealed when the ship left the surface.

21
22 CMDR RUSH: And in relation to the forecastle deck, in
23 your opinion did that sustain damage in this process?

24
25 MR JEREMY: We think it probably did. The next image
26 perhaps might be appropriate.

27
28 CMDR RUSH: Figure 169.

29
30 MR JEREMY: This shows the forecastle deck immediately
31 forward of A turret. Up in the top left there, that piece
32 of structure with round holes in it is actually part of the
33 safety firing arc mechanism for A turret. But just below
34 the anemone there on the left, you can see that the deck
35 has split and this section of deck has been bent down.

36
37 On the bottom left, we have a mushroom-top ventilator
38 there, which has been damaged possibly by impact by
39 something. Right in the middle of the photograph is
40 a watertight hatch without its lid. On the right of the
41 picture, you can see where there has been a split in the
42 deck along a deck seam, and this flappy piece of plate up
43 forward here - and also the whole deck piece would have
44 been flappy - has possibly ended up in that position partly
45 because of the impact with the sea floor and partly because
46 of the passage through the water on the way down.

1 CMDR RUSH: Speaking very generally, is it possible to
2 give some idea of the force with which the hull of the ship
3 would have met the sea floor?
4

5 MR JEREMY: It would be only very general, I'm afraid.
6 It's quite a heavy hit. There is not much data about how
7 fast ships go when they hit the sea floor, but it could
8 have been perhaps between 10 and 15 knots.
9

10 CMDR RUSH: Was there damage to the ship as a consequence
11 of the tearing away or breaking off of the bow section?
12

13 MR JEREMY: Yes, there was. Perhaps if we look at figure
14 170. This shows the fore end of the bridge. The scuttles,
15 which you can see in the forward screen there, are scuttles
16 for the captain's sea cabin and the navigating officer's
17 cabin. Above it, you can see a large area of plating which
18 has collapsed in. That particular section is quite
19 a smooth collapse, but a bit further up it looks as if it
20 has been hit by something. In behind that screen would
21 have been the wheelhouse, and we think that the forward
22 part of the bridge may have been hit by some large piece of
23 wreckage during the sinking process.
24

25 CMDR RUSH: Apart from the bow section, is there anything
26 else that would explain that?
27

28 MR JEREMY: Well, it could be a piece of ship's side shell
29 or something of that nature, but a fairly large chunk,
30 probably.
31

32 If I may just expand, CMDR Rush, we know that this was
33 not damaged before the ship sank, because the bridge roof,
34 which was right over the top of all of this, is sitting
35 quite intact in the debris field leaning up against the
36 director control tower, so it must have left the ship
37 before this happened.
38

39 CMDR RUSH: Is the deterioration of the ship that was
40 referred to earlier in evidence, and the formation of
41 rusticles, general throughout the ship?
42

43 MR JEREMY: Who is our rusticle expert at this table?
44

45 MR BUCKLAND: This is just the general state of the ship.
46 There is rusticle, rust and other deterioration to the
47 ship.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

CMDR RUSH: Just to make it clear, if it hasn't been made clear already, figure 171 is indicative of the way the rusticle formations congregate or develop over years?

MR BUCKLAND: The right-hand side image shows a lot of the rust and the rusticles. Those large lumps are called rusticles that form on the side of the ship.

CMDR RUSH: Again, in general, is that consistent with other wrecks that have been discovered in similar positions over years?

MR BUCKLAND: Very similar, yes.

CMDR RUSH: Could we have a look at the timber deck at figure 173. The depiction in that figure shows, in general, photographs of the timber decking and then points to their position on the ship. The report indicates that in relation to the thickness of the decking, there appears to be a reduction in thickness.

MR BUCKLAND: Yes. Large areas of the forecastle and the upper decks were covered with wood planking. At the moment, just from observations, it would appear that the wood has deteriorated. The only other information that we can gather from this is that the caulking between each of those planks is elevated. It would appear that the wood planking has rotted or deteriorated.

CMDR RUSH: Again we'll deal with this a bit later, but in relation to fire damage, does the deck seem to have survived that, the wooden decking?

MR BUCKLAND: It appears to have survived that. It's fairly difficult to see, from the state of the ship.

CMDR RUSH: Can we turn our attention to damage to the weapons systems at page 194 and look at the 6 inch guns and fire control. Firstly, in relation to the wreckage, you have produced a diagram of the final orientation of each of the 6 inch guns?

MR BUCKLAND: That's correct. At figure 174, you will see that for A and B turrets their final resting state is pointing to port. X and Y, on the aft guns, are both pointing to port but aimed forward.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

CMDR RUSH: You mentioned before that some of the damage to turrets is indicative of firing from the starboard side. Is that orientation consistent with that?

MR BUCKLAND: If you see the damage to A turret currently, you would expect that all these guns were pointing towards Kormoran at some stage, but on A turret there are large weapon holes on the front face. It's now the front face, but in normal position when that's pointing forward, it would be the starboard face. We would expect that that damage occurred from the Kormoran firing over the bows of the Sydney and hit that face at that stage, so the guns were, by that time, inoperable and pointing to port.

CMDR RUSH: Figure 175, looking at the computer model of the ship, I take it is taken from the photographic imagery and then we get an idea of it sitting there in the reconstruction?

MR BUCKLAND: You get some idea of the way it's pointing, but I wouldn't take too much detail from these, because there has been secondary damage to the gun barrels, so the angle that they're elevated to currently would have been from part of the sinking process.

CMDR RUSH: Figure 178 is a reconstruction of the final orientation of X and Y turrets?

MR BUCKLAND: Correct, and again you will see that they are pointing forward but to port.

CMDR RUSH: Mr Buckland, in relation to the director control, figure 181 shows the director control tower in the debris field.

MR BUCKLAND: Correct.

CMDR RUSH: You have taken us through the damage.

MR BUCKLAND: The director control tower base received several hits, but we predict that the tower stayed with the ship until the sinking process, so this parted on the break-up of the ship through the water.

MR JEREMY: Perhaps, CMDR Rush, I could comment. The photograph, figure 181, also shows the bridge roof lying

1 against the director control tower. It is substantially
2 intact.

3

4 CMDR RUSH: With regard to the 4 inch guns and fire
5 control, Mr Buckland, was it possible to determine the
6 orientation of the guns?

7

8 MR BUCKLAND: Again, we have a reconstruction in
9 figure 183 of the current state of the 4 inch guns. You
10 will see that one is missing, presumably as part of the
11 sinking process. Something may have pushed it off. We are
12 assuming that. Again, regarding the direction that these
13 guns are pointing, both in elevation and direction, they
14 could have easily been hit by things as the ship sank.

15

16 CMDR RUSH: So three of the guns are still fixed to the
17 mounts?

18

19 MR BUCKLAND: Correct. You will see images in figures 183
20 and 185 showing the guns in the wreckage. You will see
21 there where the decking plate from the base of the gun has
22 been wrapped around that gun, again probably from the
23 sinking process.

24

25 CMDR RUSH: And in relation to the plating that was spoken
26 about yesterday around the 4 inch gun deck, was any of that
27 remaining?

28

29 MR BUCKLAND: There was one small section. If you look at
30 figure 187, there is one small section, which it is hard to
31 identify from this photograph, but there is a plate there
32 that's protecting - that is the only part of the plate that
33 we can find.

34

35 THE PRESIDENT: You are not able to determine if these
36 guns were fired, are you?

37

38 MR BUCKLAND: No.

39

40 CMDR RUSH: In relation to the fire control system for the
41 4 inch gun?

42

43 MR BUCKLAND: Again, figure 189 shows the base of the
44 control station. You will see that there has been a large
45 impact at the top. That is the base where the tower would
46 have been. That damage would have resulted in the tower
47 collapsing on to the deck. But, again, it didn't totally

1 part with the ship, because it's in that debris field, so
2 it wasn't lost at the battle site.

3
4 CMDR RUSH: The damage to the tower would have impacted on
5 the system in relation to the 4 inch guns, I take it?

6
7 MR BUCKLAND: Totally. That is for directing of the guns,
8 and also here there were a lot of fragments flying into
9 other things, such as the aerial.

10
11 CMDR RUSH: As far as the quad machine guns are concerned?

12
13 MR BUCKLAND: Again, the mountings are shown. We assume
14 that the quad guns have been washed overboard, again
15 through the sinking process. We don't think they were
16 blown off from weapons damage.

17
18 CMDR RUSH: Were the port and starboard torpedo tubes
19 found with the ship?

20
21 MR BUCKLAND: No. They were found in the debris field.
22 If you look at figure 191, this is where they were mounted.
23 They were mounted on that ring there, so both the port and
24 the starboard weren't with the ship, but they were in the
25 debris field.

26
27 If we go to figure 193, this has been identified as
28 the starboard torpedo quad tubes. There are three
29 torpedoes still in their tubes. There has been a large
30 amount of damage. You can see there is one which sustained
31 minor damage, but the other two are largely damaged. We
32 assume that is from one single shot that has come through
33 and hit the tubes from approximately 90 degrees.

34
35 CMDR RUSH: So when you are indicating the damage and
36 a single shot, in the background, if you like, at the top
37 of the photograph, we see a torpedo that seems to be
38 largely damaged.

39
40 MR BUCKLAND: Correct. On the right-hand side of that,
41 that is where the warhead part of the torpedo is, and on
42 the left-hand side is the air cylinder to run the motor for
43 the torpedo. On the left-hand side of that photograph, you
44 will see the rollers that sit on that mounting that we saw
45 previously.

46
47 CMDR RUSH: So the torpedo tubes were, in effect,

1 inverted?

2

3 MR BUCKLAND: Inverted, yes, as sitting on the ship, this
4 is the bottom of the torpedo tube.

5

6 CMDR RUSH: I think you said that you think that the
7 damage to those torpedoes has been caused by a single shot?

8

9 MR BUCKLAND: A single shot coming from one direction, it
10 is indeterminant as to which direction that shot has come
11 from.

12

13 CMDR RUSH: A shell?

14

15 MR BUCKLAND: It would have been a large shell hit.

16

17 THE PRESIDENT: The propulsion for those torpedoes are
18 those little propellers, I take it?

19

20 MR BUCKLAND: No. That is the fusing for the warhead
21 itself.

22

23 THE PRESIDENT: It fires outwards to the right as we look
24 at it?

25

26 MR BUCKLAND: Exactly.

27

28 THE PRESIDENT: And was a fourth torpedo found anywhere
29 nearby?

30

31 MR BUCKLAND: There is a torpedo loose in the debris
32 field, but we can't identify whether it is from the port
33 side or the starboard side. If we go to figure 198, this
34 has been identified as the port torpedo quad tubes, and
35 here we have two torpedoes still in their tubes and two
36 missing. Then if we go to figure 200, there is a torpedo
37 in the debris field, so we have identified six torpedoes in
38 total from the debris field. There would be two missing.

39

40 CMDR RUSH: You indicated, Mr Buckland, that it was
41 possible to distinguish between the starboard tubes and the
42 port side tubes?

43

44 MR BUCKLAND: Yes. If we go to figure 195, we can
45 identify that they're the starboard or port from two means.
46 There is a platform at the top left of that picture, which
47 indicates that it is the starboard quad tube. The

1 secondary way we worked out that it was the quad tubes is
2 on the end cover plates of each of these tubes, they have
3 a lettering system which indicates the firing order of the
4 tubes for the fire control on board the ship, and these are
5 labelled "Q", "X", "Y", "Z". If we go to figure 196, on
6 the end caps they're actually identified as "Q", "X", "Y",
7 "Z". You need to home in, and if we go to figure 197, it
8 will be easier to see in a minute. In the middle of that
9 circle, there's a letter "Q".

10
11 And there's a letter "Z" that's embossed on those
12 cover plates. If we go to figure 199 on the port torpedo
13 tubes, again we can identify from the side plating but also
14 from the embossing on the end covers, and you will see an
15 "E". On the port side quad tubes, they are labelled "F",
16 "I", "R", "E", which is the indication, again, for the
17 firing. So that's how we identified that they were the
18 port and starboard sets of tubes.

19
20 CMDR RUSH: Is it then possible to determine whether the
21 torpedo tubes were manned and whether they were pointing
22 outwards from their stowed position?

23
24 MR BUCKLAND: No. From the starboard side tubes, from the
25 reconstruction that we did, it was more likely that they
26 were pointed out, when they were hit, than stowed, but we
27 can't give a definite.

28
29 CMDR RUSH: What was it about the tubes that led you to
30 think that?

31
32 MR BUCKLAND: Because of the direction - if you look at
33 figure 193, it is indicating that possibly it is more
34 likely that the weapon came from the front of the screen to
35 the rear of the screen, so as the damage got worse, that's
36 the direction of the shell that came through, so it clipped
37 tube number 2, took a section out of tube number 3 and then
38 hit number 4 and took a larger section.

39
40 In this case, for this side tube, the torpedo that is
41 missing would be the torpedo that was stowed inboard. For
42 that to happen, the shell would have had to come from the
43 port side, but our reconstruction would show that there is
44 a lot of structure in between that tube, so it is more
45 likely that that tube was pointing outwards and then it was
46 hit from one of the shells as it was doing its turn, so the
47 shell has actually come from forward, over the bow, and

1 then hit those tubes. Again, we can't really make it
2 definite.

3

4 CMDR RUSH: So that we get some overall understanding to
5 put the photograph in some context, you have at figure 194
6 given us a diagram of the 21-inch torpedo. What is the
7 overall length of the torpedo?

8

9 MR BUCKLAND: It is 24 feet, so the warhead itself is only
10 a very small section. We might just indicate the head
11 there, and that's where that firing pin that you can see
12 is, around there. Where that weapon damage has occurred is
13 almost between the warhead and the air vessel itself.

14

15 CMDR RUSH: Sir, the intention now, subject to your
16 assent, would be to call Dr Neill, who was responsible for
17 the creation of both the computer model that we have seen
18 and the simulation that I showed in opening, to explain how
19 that was done, and then to bring people back together to go
20 through the interpretation of the evidence that has been
21 put before the Commission thus far, and then finally to
22 deal with the operational aspects of Sydney and fire
23 damage.

24

25 So, gentlemen, if I could ask you to retire for
26 a short period of time, and I call Dr Neill.

27

28 <ROGER ANDREW NEILL, affirmed: [12.16pm]

29

30 CMDR RUSH: Dr Neill, could you state your full name to
31 the Commissioner, please?

32

33 DR NEILL: Roger Andrew Neill.

34

35 CMDR RUSH: And your address?

36

37 DR NEILL: [REDACTED]

38

39 CMDR RUSH: And, Dr Neill, your current position?

40

41 DR NEILL: I'm head of Unmanned Maritime Systems in the
42 Maritime Platforms Division of DSTO.

43

44 CMDR RUSH: Do you have a degree of Bachelor of Science.

45

46 DR NEILL: Yes, a physics degree.

47

1 CMDR RUSH: And also a doctorate, in what area?

2

3 DR NEILL: It's medical physics.

4

5 CMDR RUSH: In your work at DSTO, you mentioned that you
6 are in charge of Unmanned Maritime Platforms, but over
7 a period of time have you also, starting off with the
8 discovery of the AE2 submarine, developed an interest in
9 maritime wrecks?

10

11 DR NEILL: Yes. Mr Buckland has mentioned many times the
12 remotely operated vehicle imagery of the Sydney. Coming
13 out of my expertise with unmanned maritime systems,
14 I obviously developed an interest in the application of
15 those systems to marine archaeology which was, to some
16 extent, out of my interest, but, nevertheless I became
17 involved with the marine archaeological assessment of the
18 submarine HMAS AE2 and, from that, I believe I developed
19 some expertise in this domain.

20

21 CMDR RUSH: And, Dr Neill, in relation to the DSTO work
22 for this report, did you undertake the task of creating
23 a computer-built image of HMAS Sydney?

24

25 DR NEILL: Yes. Again arising from the work that I did
26 with AE2, I found that by building a high-fidelity model of
27 that submarine, it very much facilitated the interpretation
28 of the wreck of that submarine in its location on site in
29 Turkey, so it seemed like an obvious and sensible thing to
30 follow a similar process with the Sydney. We have found
31 that by developing high-fidelity computer models, you are
32 able to do a degree of, I use the term forensic
33 visualisation, accurate representations of various
34 scenarios that may be relevant.

35

36 CMDR RUSH: What did you use to produce and put together
37 the computer model?

38

39 DR NEILL: I started with the original as-built drawings
40 of the Sydney. I then attempted to track the changes and
41 modifications to the ship, obviously working with my
42 colleagues, so by making use of photographs and other
43 sources of information I was able to incorporate changes
44 that we were aware of. Then finally, we cross-correlated
45 the imagery as generated by me with the imagery as seen on
46 the seabed of the wreck of the ship.

47

1 CMDR RUSH: Sir, could we bring up DST0.001.0069? You
2 might take us through it?
3

4 DR NEILL: Yes. This illustrates the process that I used
5 in building the computer model. What I have done on the
6 left-hand side image is taken the profile view of some of
7 the sections of the ship and the plan view and then
8 superimposed those in the correct orientation and position.
9 Then I have built a hull through those plans so that they
10 correspond, as best as possible.
11

12 The very first thing that you find when you do this is
13 that there are inconsistencies between the drawings, so
14 there is inevitably a little bit of interpretation that has
15 to take place.
16

17 Working from that, though, moving to the other side
18 image, I have then, if you like, roughed in, for want of
19 a better term, the major structures of the ship, so you can
20 see the A and B turrets, the breakwater; the superstructure
21 is beginning to be built; and a very early version of, for
22 instance, the director control tower.
23

24 Then as I got hold of more information, acquired more
25 information, I was able then to fill in the missing details
26 I believe with quite a high degree of integrity.
27

28 CMDR RUSH: Perhaps if we can bring up the next image,
29 which is 0415.
30

31 DR NEILL: Yes, no source of information was safe from me,
32 so in the case of the Vickers quad machine guns, obviously
33 we had that one photograph that we had access to, but
34 I discovered that the manufacturer, the company Vickers,
35 actually has a museum and it has photographs of some of the
36 things that it has built, including the quad machine guns.
37 So I was able to access photographs and I was also able to
38 access a drawing of that unit.
39

40 Wherever possible, I've done that with all of the
41 major implements on board the ship. When we started the
42 process, I wasn't sure really what fidelity we needed, so
43 I decided to just go for broke and built it as precisely as
44 we could.
45

46 CMDR RUSH: The next image?
47

1 DR NEILL: As I mentioned a little earlier, we
2 cross-checked the imagery as generated by me in the model
3 against the imagery as evident from the ROV footage, so
4 that is the vicinity of starboard side in the vicinity of
5 the blacksmith's shop, and you'll see things like the
6 grinding wheel that's still in place at the aft end of the
7 blacksmith's shop, the skylight on top of the blacksmith's
8 shop, which has been blown out, and there is the base of
9 the mast sitting just behind the skylight there.

10
11 Generally, there is a very high level of correlation
12 between what we built and what is shown on the ship. There
13 are some very slight differences. There appear to be
14 a couple of vertical supports between the upper deck and
15 the foredeck, which I haven't actually shown, because they
16 weren't shown in the plans. Until we got that footage,
17 I had no way of knowing that those struts were there. So
18 some things I haven't actually corrected, due to the
19 pressure of time.

20
21 CMDR RUSH: There are one or two more in the next image?

22
23 DR NEILL: The next image is really to illustrate the
24 level of fidelity that we generated and the fact that the
25 model is recognisably HMAS Sydney.

26
27 CMDR RUSH: That deals with the model. Yesterday, there
28 was also a simulation in relation to port side and
29 starboard side damage and the aggregation of shell hits to
30 the port side of Sydney and also the latter period of time
31 dealing with Sydney and its roll. Firstly, dealing with
32 the shells and the fire, as indicated, can you give us an
33 indication of what you relied upon in bringing that imagery
34 together?

35
36 DR NEILL: I worked with the team, so as the team
37 generated the plot of shell hits, in the first instance
38 along the port side of the ship, they very carefully
39 positioned each hit and that was mapped. That made it very
40 easy for me then to take those hits and position them on
41 the model with, I believe, quite a high level of precision.

42
43 For instance, we had sidelights in a particular
44 orientation. I was able to position the shell hits using
45 those as reference points, for instance, and relate those
46 to what the team had actually identified, so in that way we
47 were able to build up, I believe, quite a realistic

1 representation of where each of the hits were.

2

3 CMDR RUSH: Perhaps if we do it in sequence, if we could
4 go to the simulation, the first piece of simulation is an
5 aerial view or fly-around of Sydney. It is 0416. Before
6 we look at it, could you tell us what it represents and how
7 it was done?

8

9 DR NEILL: Yes. We used a software package called
10 Blender. It is actually an animation software package, but
11 it's one that is able to be used for doing quite precise
12 reconstruction. We used that to build the static
13 representations that have been shown this morning and also
14 to generate the animations that have been done.

15

16 With that package, it is an artist's package in that
17 you are able to simulate, for instance, the position of the
18 sun; you are able to simulate forces due to wind and, in
19 that way, later on we were able to generate smoke. We
20 have, we believe, a reasonably realistic representation of
21 where the smoke would have been blowing. You are able to
22 generate sea state type representations. So it is quite
23 a powerful package. However, there is a degree of
24 interpretation required to do what we have done.

25

26 CMDR RUSH: Before we show that particular section, you
27 indicated that you worked with a team at DSTO and it was
28 a team effort in relation to bringing together the
29 information that you have attempted to put into the
30 simulation?

31

32 DR NEILL: Yes, very much so. I actually attempted to
33 retain a small degree of independence from the rest of the
34 team, in the sense that we cross-checked against each
35 other, so we worked a little bit independently and, in that
36 way, we developed a high level of confidence that if we
37 came up with consistent answers, we had confidence in each
38 other's interpretations. That seemed to be a very healthy
39 way to act, if you like, as an internal referee, and
40 I think in every instance we came to the same conclusion.

41

42 CMDR RUSH: Perhaps if we have a look at this.

43

44 DR NEILL: With this sequence I was trying to get across
45 four features of the ship which have very much come across
46 in the last day. The first is the fact that, in this
47 generation of ship, the quarterdeck and the foredeck were

1 very much associated with seakeeping and ship handling,
2 with the exception of the depth charge rails, which are
3 just visible on the stern there, the quarterdeck and the
4 foredeck weren't involved with war fighting.
5

6 The evidence has shown that the German crew pretty
7 much ignored those two parts of the ship, and it kind of
8 makes sense when you think of it in that light.
9

10 The second thing which I was trying to portray was in
11 highlighting the concentration on this generation of ship
12 of the command and control in one part of the ship, so very
13 much the bridge, the director control tower, the high-angle
14 control station are all in one place. The only exception
15 to that is the aft control position, which as Mr Jeremy
16 pointed out yesterday had quite minimal equipment, in any
17 case.
18

19 That is very much shown in that imagery where you have
20 quite a large ship with a very, very centralised, and
21 therefore very vulnerable, control station.
22

23 Likewise with the boats, the disposition of all of the
24 ship's boats was really determined by the technology of the
25 day. There was only one crane on board the ship and the
26 boats were very much clustered around that crane in order
27 that it be able to get those boats into the water. Again,
28 that is a point of particular vulnerability for this design
29 of ship, in that you have many of your lifesaving
30 appliances concentrated in one place next to an aircraft
31 which carried very flammable fuel.
32

33 CMDR RUSH: This was raised by a member of the public
34 yesterday: is there any significance in the flag that is
35 depicted there?
36

37 DR NEILL: The flag caused a great degree of stress,
38 actually. That's the Admiralty Battle Ensign, as
39 I understand it, which is the ensign that was used both in
40 the First World War and the Second World War. Regarding
41 the disposition of the flag, it appears that when the ship
42 was entering and leaving harbour, it was normally deployed
43 off a jackstaff at the stern of the ship, but for
44 practicality purposes whilst she was at sea it was deployed
45 off the mainmast in the location where it is shown.
46

47 To be quite honest, my use of the flag was to give an

1 impression of motion.

2

3 CMDR RUSH: The next sequence, Dr Neill, deals with the
4 port side engagement. Firstly, in general terms, counsel
5 assisting provided DSTO with a set of assumptions which
6 appear in the report. Using that as a base, would you
7 indicate what other information you used and how it was
8 that you brought this particular piece of the simulation
9 together?

10

11 DR NEILL: Yes. I started obviously using the assumptions
12 as the basis for building the sequence. I attempted to
13 cross-check particularly the timing of the sequence against
14 what potentially was likely to take place, so based on the
15 assumption that the ships were approximately 1,000 metres
16 apart, based on the speed of Second World War German
17 torpedoes, it meant that depending on whether the torpedo
18 was flying at 30 knots or 40 knots, the time of flight
19 through the water for the torpedo was somewhere between 50
20 and 70 seconds, so that gave me a strong basis to work
21 against in terms of checking against the assumptions.

22

23 The gents determined that the likely maximum firing
24 rate of the Kormoran's guns was around about seven salvos
25 per minute, so I've worked off that and determined the
26 total time that it would take to fire the number of salvos
27 which were indicated in the assumptions, and the timing is
28 quite consistent with what you would expect to see.

29

30 Essentially, I tried to work through the assumptions
31 and do a reality check on each aspect of them. There are
32 a couple of things which I questioned a little, and you
33 will see that I have addressed them in the animation. For
34 instance, the assumptions state that the bridge and
35 director control tower were struck and then, shortly after,
36 Sydney fired a salvo from all four guns.

37

38 If the director control tower had been struck, then in
39 all probability that salvo from Sydney had to be fired
40 under independent initiation from the four guns. So I have
41 shown that in the animation.

42

43 Of course, if the order was slightly wrong, Sydney may
44 have fired that salvo shortly before the director control
45 tower was hit. I just worked with the assumptions.

46

47 The one other thing which I would say is that

1 throughout the animation, I have damaged some items on the
2 ship, for instance, the cutters come away from the ship
3 during the engagement, but I haven't damaged other things,
4 and the reason for that is that it wasn't clear from either
5 the assumptions or the evidence that we could see in the
6 wreck field at what point things were damaged. Therefore,
7 I've left them alone.

8
9 CMDR RUSH: One aspect of this particular sequence is the
10 distribution of, if you like, the shrapnel fragments from
11 each individual hit. Was that based as shown in the
12 animation on any particular advice that you had been given
13 in relation to that?

14
15 DR NEILL: The distribution, the actual spray pattern, is
16 obviously just a visualisation, but it is meant to be
17 representative of what is shown in the report. The radius
18 or diameter of the spray as shown is actually meant to be
19 a representation of the damage blast radius.

20
21 As Mr Buckland pointed out earlier, unless shrapnel
22 actually hits something, it would have kept going much
23 further than I have represented. So I have attempted to
24 represent two things with the one visualisation.

25
26 CMDR RUSH: Just before we show it, is each individual hit
27 on port side basically taken from the material that
28 Mr Buckland referred to in his evidence this morning?

29
30 DR NEILL: Yes. Sorry, the one other thing, though, is
31 that I didn't attempt to differentiate between hits that
32 penetrated the ship and hits that exploded on the surface.
33 The reason for that is that it would be very difficult to
34 represent the scope of the damage of a shell that exploded
35 inside the ship, so I felt that it was really more
36 representative to show it as if it had exploded on the
37 outside.

38
39 CMDR RUSH: Thank you.

40
41 DR NEILL: This first period, which is the first
42 10 seconds or so of this representation, corresponds to the
43 period in which the Kormoran would have been
44 decamouflaging. The assumptions state that the Kormoran
45 also fired a ranging shot during this time. I didn't
46 represent that.

1 The other thing which I didn't point out is that the
2 point of visual reference here is the Kormoran's bridge.

3
4 CMDR RUSH: So this is meant to represent us looking at
5 Sydney from Kormoran's bridge?

6
7 DR NEILL: From Kormoran's bridge, yes. This is about the
8 time that the torpedo would have been fired. The first hit
9 on the bridge is shown as a three-gun salvo from Kormoran.
10 Our report states that Kormoran, in all probability, didn't
11 have centralised firing, so the guns would have been fired
12 independently. I have chosen to show them as if they were
13 fired centrally, and the reason for that is that it makes
14 it easier to see the sequence of salvos, but the actual
15 contact would have been slightly staggered.

16
17 The first salvo, we believe, hit the base of the
18 barbette of the director control tower and the region of
19 the bridge, so the impact of that on the operation of
20 Sydney would have been very dramatic indeed.

21
22 Winding back just slightly, I have shown Sydney's
23 response as a slightly staggered four-gun salvo. Again,
24 that's, as I mentioned, because I believe that the gun
25 crews would have very quickly realised that they had to
26 work in local control. They possibly were still using the
27 firing solution, for want of a better term, that was
28 directed by the director shortly before the hit, but they
29 wouldn't have had the benefit of gyro initiation.
30 Therefore, that may be an explanation as to why that shot
31 apparently went high.

32
33 What you can see just starting here is
34 a representation of the secondary armament from Kormoran
35 focused on the 4 inch gun deck and the quarterdeck. At
36 that point, I have represented the roof coming off
37 B turret.

38
39 The evidence this morning was that the shell that
40 actually hit B turret between the gunsights may not have
41 fully penetrated that turret. Nevertheless, if you work
42 out the kinetic energy of that shell, just the kinetic
43 energy of the shell, regardless of its explosion, is almost
44 equivalent to a tour coach at 100 kilometres an hour
45 running into something. That's the sort of kinetic energy
46 that is involved, and that hitting the front face of the
47 turret in itself may have been sufficient to remove that

1 roof off that turret.

2

3

4 So the sequence continues. The focus was shifted to
5 the A and B turrets and then shifted back more generally
6 along the midships area. The fire started at this point.
7 I have actually represented one of the hits on the port
8 side davits for the sea cutters. You will see that I have
9 represented a hit on the forward davit and then, a little
10 later on, it represents the hit on the aft davit. The
11 order is inconsequential. Whether it was that order or the
12 other, the end result, as Mr de Yong has mentioned, is that
13 the davit would have gone overboard, and that's shown
14 a little later. So the cutter is actually hanging there on
15 the side of the ship. Then a little later, another hit
16 takes off the remaining davit.

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

The assumptions state that Sydney was moving backwards a little bit, possibly because she saw the firing of the torpedo, and attempted to slow down. I don't know the answer to that, but the assumptions state that she slowed down and I have attempted to represent that.

This is the torpedo hit. As was mentioned this morning, the ship would have responded by trimming up by the bow initially. Then the gas bubble that was generated by the torpedo actually creates a hole under the bow and she would then drop into that hole. She would then respond by coming back up again, and then as water flooded into the ship, she would trim down by the bow, so that is represented here over about a 20-second time frame. So she goes up, she drops down, up again, and then she starts to trim down by the bow as water rushes into the bow of the ship.

During that period, we didn't show any hits from the Kormoran. That was really a limitation of the computer technology that we had available. What I have represented there are the remaining hits on the port side, and I have represented them as being fairly low down by the waterline. I have no real reason to know that that was the case, but it does make sense that the Kormoran would attempt to breach the waterline as well as that caused by the torpedo hit, and there are hits there.

CMDR RUSH: Is the next image an aggregation of all port side hits as if they occurred all at once?

1 DR NEILL: Yes. It seemed to be a very effective, I'd say
2 almost chilling, way of representing the impact of those
3 41 hits on the port side of the ship. Really, what comes
4 across very, very strongly is just how completely and
5 comprehensively that midships section of Sydney was covered
6 by the Kormoran's fire, and this is ignoring the secondary
7 fire from 3.7 and 2cm guns. (Sequence shown).

8
9 THE PRESIDENT: That last sequence also excluded the
10 torpedo, did it not?

11
12 DR NEILL: Yes. That was meant to exclusively represent
13 the 15cm shell hits.

14
15 CMDR RUSH: The next sequence, Dr Neill, is the 15cm shell
16 hits to starboard side, and for this you worked on an
17 assumption that Sydney undertook a turn to the port and
18 crossed astern of Kormoran?

19
20 DR NEILL: Yes. That was actually initiated during the
21 last sequence. During the last sequence, I showed the turn
22 up to the point where Sydney was looking directly towards
23 Kormoran. At least based on the assumptions, she continued
24 to turn to port. She then crossed Kormoran's stern and
25 then sailed off, from memory, at 150 degrees bearing and
26 basically sailed away from Kormoran.

27
28 The assumptions state that Kormoran kept firing on
29 Sydney until she was about nine and a half kilometres away
30 from Kormoran. Depending on what speed you assume Sydney
31 was doing, that may have been up to 50 minutes. Basically
32 during that period, Kormoran fired reasonably consistently,
33 we believe.

34
35 Sorry, there is one other thing that I forgot to
36 mention on the port side engagement, if I could mention
37 that. The assumptions state that Kormoran fired around
38 about 11 salvos. If we assume a maximum of four guns could
39 bear at one time, that is a maximum of 44 15cm hits on
40 Sydney. We have identified 41. So if that assumption of
41 11 salvos from Kormoran is correct, then the firing during
42 that first sequence was extremely accurate.

43
44 CMDR RUSH: The next one is sequence 4, with sound.

45
46 DR NEILL: The German account states that they saw the
47 B turret roof fall off the ship. I represented that. It

1 was during that port turn that the Germans reported that
2 they saw that turret roof fall off, so I have represented
3 that. At this stage, I have also represented the hits on
4 what became the forward face of A turret, which was
5 legitimately at starboard side, but because of its
6 disposition was pointing towards the front of the ship.
7

8 At this stage, the fire is very, very well
9 established. There is a lot of smoke. From this point, we
10 have no real knowledge of what order shell strikes would
11 have taken place on Sydney, so I have simply geographically
12 taken the chart that the team generated and I have started
13 at the front of the ship and simply moved back. So that
14 sequence follows.
15

16 Sydney is continuing to undertake the turn, and then
17 she steams off at about 150 degree bearing. Based on the
18 numbers of shells that the Kormoran's crew claim to have
19 fired and the number of hits that are evident on board
20 Sydney, they had somewhere around 10 to 15 per cent strike
21 rate as the range increased.
22

23 CMDR RUSH: The final animation, Dr Neill, relates to
24 later into the evening and the roll of Sydney. We are yet
25 to get evidence in relation to that, but did you rely on
26 the work that had been done by Terry Turner in relation to
27 the computer modelling that he had done as to the flooding
28 and the effect of the flooding and damage on Sydney?
29

30 DR NEILL: Yes. Mr Turner provided me with a time plot of
31 roll versus time. It indicated that Sydney would have been
32 rolling between about 15 degrees and up to 40 degrees, with
33 around about a 10-second time frame per roll.
34

35 Here, I attempted to reproduce a section of the time
36 line which Mr Turner provided me with, and I believe it is
37 quite precise. This is sequence 5.
38

39 The German crew reported that they could still see the
40 glow from the fires, so I have represented the fires in
41 three principal locations, which we'll also talk about
42 later on this afternoon, I believe. Sydney has listed
43 heavily to port and she's rolling across from about 15
44 degrees down to about 40 degrees, 42 degrees maximum.
45 I think this one might be 42 degrees.
46

47 The sea there is shown as having come up to about sea

1 state 4, which is about a 2.5 metre sea height, principal
2 sea height.

3

4 CMDR RUSH: I think the evidence will be that the roll of
5 Sydney developed from 15 degrees to approximately
6 45 degrees. Did you attempt to depict any particular
7 degree in that animation?

8

9 DR NEILL: Yes. That's ranging between around about
10 15 and 42 degrees. I would have to look up the notes, but
11 each roll is actually slightly different, because I tried
12 to reproduce part of Terry's sequence. I believe that this
13 particular roll is a 42-degree roll. The most upright
14 position was 15 degrees.

15

16 CMDR RUSH: Sir, before lunch, I wonder whether we will
17 take an uninterrupted view of the animation so that we get
18 a complete picture, at 0415.

19

20 THE PRESIDENT: Yes.

21

22 (Sequences 1, 2, 3, 4 and 5 shown).

23

24 CMDR RUSH: Sir, I tender the video animation.

25

26 EXHIBIT #107 VIDEO ANIMATION PROVIDED BY DR NEILL

27

28 CMDR RUSH: If that is a convenient time, sir?

29

30 THE PRESIDENT: Yes. We will adjourn to 2 o'clock.

31

32 LUNCHEON ADJOURNMENT

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

1 UPON RESUMPTION:

2

3 CMDR RUSH: Sir, may we now deal with aspects of the
4 interpretation of the evidence. In relation to that, if
5 Mr John Jeremy, Dr Cannon, Mr Buckland and Mr de Yong could
6 return to the witness desk, at least initially.

7

8 Could we deal firstly with the weapons damage and
9 analysis process. We have been over this a little bit,
10 Mr Buckland, but could I just get the process. You refer
11 in the report to using an XVAM analysis to try to interpret
12 the weapons damage to Sydney. Could you give the
13 Commissioner the background of that and how it is used?

14

15 MR BUCKLAND: It is a vulnerability assessment simulation
16 program that DSTO has developed over many years and that is
17 based on a large database from real weapons trials,
18 fragmentation of weapons and blast and fragment damage.

19

20 The simulation looks at the structure of the ship and
21 calculates, based on the velocity and weight of fragments,
22 how far they will penetrate through various bulkheads. It
23 will also look at damage from blasts onto bulkheads within
24 the ship and it also has a simulation to look at crew
25 incapacitation based on critical failure of levels in the
26 program.

27

28 CMDR RUSH: From the perspective of examining the
29 15cm shell fire to various parts of the ship, what do you
30 do?

31

32 MR BUCKLAND: We took the 87 hits that we identified as
33 striking the ship, we took their coordinates and we put
34 them through the simulation to see the relative amount of
35 damage to the ship's structure. For the contact-detonated
36 shots, we detonated them on the surface. For the shots
37 that we identified that penetrated into the structure,
38 based on the velocity of the shell we put a distance into
39 the structure and detonated the shell inside the structure.

40

41 CMDR RUSH: The distance that the shell enters into the
42 ship, I take it, is dependent upon the structure --

43

44 MR BUCKLAND: The program can calculate the residual
45 velocity of fragments going through from one section, so if
46 there is a 10mm plate and it is hit by a 1,200 metres per
47 second fragment, it will calculate the residual velocity

1 and mass of that fragment as it penetrates through. With
2 the warhead hitting the hull, once it strikes the hull
3 plate, there will be a residual velocity, and depending on
4 the fuse delay of that warhead, it will travel in a certain
5 distance. In this case, we tried to detonate most at the
6 centre line of the ship, except in cases where we knew that
7 there was a lot of structure in front of that warhead.

8
9 CMDR RUSH: Dr Skeen has brought up on the monitor
10 figure 1, which is the XVAM model for Sydney. Would you
11 explain what the model represents?

12
13 MR BUCKLAND: We created a representation of the Sydney
14 based on the bulkheads and the hull plating thicknesses.
15 Each of those square rectangular blocks is a representation
16 of a compartment or part of a compartment within the
17 Sydney. This is an output from one of our simulations from
18 a single 15cm shell. The orange compartment is where we
19 have detonated a shell, and you will see that there are
20 2,600 fragments being generated into that compartment.

21
22 In the compartments, as we go out through the
23 structure, this is a representation of the fragments, so
24 then you would move out to a lower number of fragments as
25 you move away from that detonation point out to a point
26 where the dark blue is one or two fragments having
27 penetrated that far.

28
29 As part of the code as well, there is another module
30 which calculates pure blast damage. Then they are
31 combined. It is a probability-type calculation, in the
32 end, for what is the likelihood of damage.

33
34 CMDR RUSH: Does each one of those sections represent a
35 deck of Sydney?

36
37 MR BUCKLAND: Yes.

38
39 CMDR RUSH: So where we see the colour, is that the
40 forecastle deck of Sydney?

41
42 MR BUCKLAND: That's correct.

43
44 CMDR RUSH: The first colour there is blue. What does
45 that represent?

46
47 MR BUCKLAND: This is representing a volume that the

1 fragments are in. Where it is orange, we are calculating
2 that the detonation has occurred there, so there are
3 2,600 fragments in that space. You will see later how we
4 have put in a vector for those fragments so that we know
5 which way the fragments are travelling.
6

7 CMDR RUSH: Does the model take an examination of each of
8 the identified 15cm hits both port and starboard of Sydney?
9

10 MR BUCKLAND: Exactly. We will go through where we have
11 combined the whole 87 shots to get a total damage profile
12 on the ship.
13

14 CMDR RUSH: In the report, going back to page 215, at the
15 bottom of that page you use the term "blast overpressure"
16 generated from the shell having limited damage potential
17 but the explosion producing more than 2,000 lethal
18 fragments. What is the overpressure?
19

20 MR BUCKLAND: We have identified two shells that were
21 used. There is the armour-piercing or the base-fused
22 shell, and that had only 1kg of explosive. The detonating
23 charge, the nose-fuse shell, had approximately 4.5kg of
24 explosive. That explosive, when you detonate it, creates
25 an overpressure into a space, and that overpressure is what
26 does the damage to, in this case, structure, equipment and
27 other things within that space.
28

29 CMDR RUSH: We have on the screen figure 201, which is a
30 cross-sectional profile of the German 15cm AP shell.
31

32 MR BUCKLAND: That's right.
33

34 CMDR RUSH: So the significance of the AP shell is that it
35 is designed to penetrate armour?
36

37 MR BUCKLAND: It is designed to penetrate armour, so it
38 will penetrate a long way through the ship's structure,
39 depending on what it will hit. You will see that it has a
40 very heavy steel section at the head.
41

42 CMDR RUSH: Is there a delay in the fusing of that shell
43 to promote explosion inside the ship?
44

45 MR BUCKLAND: There is a fusing delay that it can be set
46 to, depending on how far they would like that to penetrate
47 through into the ship.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

CMDR RUSH: At figure 202, we have the HE shell?

MR BUCKLAND: This is the HE shell. This is really just to demonstrate the less-thick wall. In this case, there is a higher detonating charge within the shell. This shell would generate 4,000 steel fragments. The armour-piercing shell would still generate approximately 2,000 steel fragments.

CMDR RUSH: As to the 20mm and 3.7cm armament of Kormoran, would you refer us to the projectiles that were fired by each of those?

MR BUCKLAND: The 3.7cm shell would have a similar bursting charge, so it would detonate as well and generate fragments. In this case, we haven't put it into our XVAM analysis. We did this purely on the 15cm shells. A lot of the 20mm rounds also had a small bursting charge within them as well, so they would, on contact, also cause other fragments.

CMDR RUSH: You refer at page 216 to the 3.7cm shell having a velocity of 800 metres a second and the 20mm shell having a velocity of 900 metres a second.

MR BUCKLAND: Correct.

CMDR RUSH: Is that velocity of significance in relation to the damage?

MR BUCKLAND: These are the muzzle velocities. The velocity is important because it is giving the kinetic energy to that shell. Depending on the stand-off distance, you will have greater kinetic energy being close before the velocity drops off.

CMDR RUSH: Do those shells also have a fragmentation?

MR BUCKLAND: Yes, correct.

CMDR RUSH: So they create their own shrapnel field?

MR BUCKLAND: For the 20mm, there is only a limited amount. There is a limited bursting charge within them. A lot are tracer rounds, which have a very small charge the 3.7cm HE would generate. The shells in this case are

1 700 grams, so the actual amount of steel fragments is
2 around that range.

3

4 CMDR RUSH: You mentioned before that the steel fragments
5 from the 15cm shell would go around the ship until stopped
6 by something. Is it the same in relation to the 3.7cm gun
7 and the 20mm gun?

8

9 MR BUCKLAND: It is, but the velocity of those fragments
10 would be much less than that generated by the 15cm shells,
11 so the 15cm shells would have a greater lethality range.

12

13 CMDR RUSH: At page 217, you refer to weapon trajectories
14 and that the elevation required of the 15cm gun for a range
15 of 5,000 metres is only 1.7 degrees.

16

17 MR BUCKLAND: Correct.

18

19 CMDR RUSH: From there, you say that shots on the Sydney
20 appear to have a shallow impact angle.

21

22 MR BUCKLAND: Exactly. It is very difficult to pick up
23 what that angle is, but we have done so from the concentric
24 nature of the shell holes that we've seen. The angle of
25 fall at table 21 in this case is important, apart from the
26 elevation angle of the gun. The angle of fall is the
27 contact angle at which that shell will be landing on the
28 ship or on the hull. Even at 10,000 metres, the angle of
29 fall will be only 8.8 degrees.

30

31 CMDR RUSH: What is the significance of the angle of fall,
32 for instance, at 5,000 metres of 2.2 degrees?

33

34 MR BUCKLAND: It means that the contact point of the shell
35 onto the surface is basically normal to the hull, so that
36 you have a greater chance that it will penetrate into the
37 hull.

38

39 THE PRESIDENT: If we're speaking, as we probably are, of
40 distances between 1,000 metres and 1,500 metres, you would
41 expect that the striking velocity would be greater than
42 673 metres per second and closer to muzzle velocity and
43 that the angle of fall would be less than 2.2 degrees?

44

45 MR BUCKLAND: The striking velocity won't be much more
46 than 673 metres per second. Right up to 5,000 metres,
47 there is not going to be much drop-off. The muzzle

1 velocity, I think, was 800 metres per second at the start.

2

3 THE PRESIDENT: So what is the difference between
4 5,000 metres and 1,500 metres?

5

6 MR BUCKLAND: For the striking velocity, we're probably
7 looking at 700 metres per second.

8

9 THE PRESIDENT: And the angle of fall would be marginally
10 less than 2.2 degrees?

11

12 MR BUCKLAND: That's at an elevation of 1.7 degrees. You
13 have lost 0.5 degree over that range.

14

15 CMDR RUSH: In the bottom paragraph on page 217, you use
16 the word "lethality" of the warheads and you say that they
17 are "extremely lethal over 10,000 metres". Is that
18 accentuated the shorter the range?

19

20 MR BUCKLAND: By the striking velocity. In this case,
21 it's not the actual weapon detonating; it is just the
22 striking velocity, so especially for the AP shot, it is
23 likely to go further into the ship. As it crashes through
24 the ship, it is going to do a lot of damage as it goes
25 through the ship, because you will get a lot of secondary
26 damage. As it hits the shell plate, it will create those
27 bits of fragments from the hull that would go through the
28 ship at that velocity as well, and then it will keep
29 hitting subsequent bulkheads.

30

31 CMDR RUSH: You refer, by way of two diagrams, to the
32 estimated blast and fragment damage contours. At
33 figure 203, that is for the AP weapon detonation. Can you
34 explain by reference to the colours there what you are
35 referring to?

36

37 MR BUCKLAND: Within our simulation, the areas that are in
38 dark red represent a volume-based calculation on the blast
39 overpressure, and everything within that volume will be
40 destroyed within 1.5 metres. The casualty radius there
41 means that any crew who are unprotected by a protected
42 space, a totally enclosed space, would become a casualty
43 within that volume.

44

45 On the right-hand side, there is a profile of
46 fragments which will have a greater lethality range, but if
47 that requires them to be unimpeded, they are a

1 line-of-sight calculation. For the AP shell, you will see
2 that the fragments will be generated from the weapon
3 between 75 degrees and about 125 degrees. The main
4 generation of fragments will come from that perpendicular
5 to the shell, and you will have 2,000 fragments coming out
6 from that spot. You will have a few fragments that will be
7 fired forward of that shell, which is the shell head
8 itself, and then a few other fragments which will be forced
9 backwards.

10
11 CMDR RUSH: Then figure 204 shows the contours for the
12 nose-fused 15cm HE shell.

13
14 MR BUCKLAND: That's right. Because of the larger
15 detonating explosion, the amount of explosive, the casualty
16 radius is higher. It is up to a 5-metre radius.
17 Obviously, if that shell detonates on one side of
18 a watertight bulkhead, that watertight bulkhead will
19 protect the people on the other side, unless it is within
20 3.2 metres, and then it will create holes within that
21 bulkhead.

22
23 THE PRESIDENT: Do you get a greater number of fragments
24 if the striking velocity is greater?

25
26 MR BUCKLAND: You will get more secondary fragments from
27 the missile itself. From the actual shell casing, you will
28 get the same number of fragments that it detonates, but
29 from the armour-piercing shell, if it still has forward
30 velocity before it detonates, you will get that extra
31 velocity from the fragments and you will get an extra
32 lethality from the fragments as it pushes through.

33
34 THE PRESIDENT: Created on the way through?

35
36 MR BUCKLAND: That's right.

37
38 CMDR RUSH: Mr Buckland, you deal with torpedo damage
39 mechanisms. We've discussed today the mechanism, if you
40 like, of the initial tearing of a hole in the hull of the
41 ship and also the penetration through, in this aspect, the
42 starboard side of the ship. Does the bubble that is
43 created also have the consequences of damage and flooding?
44

45 MR BUCKLAND: I probably explained this morning that the
46 explosive will blow a hole into the actual hull itself and
47 you will have secondary fragments from that hull material

1 being blown through the ship structure. From the explosive
2 detonation, the ship will heave and there will be a shock
3 that goes through the ship. As the bubble collapses, the
4 water will then cause another damage effect on the hull.

5
6 CMDR RUSH: Are gases and fumes created from the torpedo?
7

8 MR BUCKLAND: From all explosions, there will be a
9 generation of the explosive gases that will be pushed into
10 the air spaces and volume, and that's from the bubble
11 itself. The bubble itself is just hot gases, and they will
12 be pushed throughout the ship.
13

14 CMDR RUSH: The flooding consequences of torpedo damage --
15

16 DR CANNON: I was going to make a recommendation,
17 CMDR Rush, that as the tools that were used for this
18 flooding compartment were done by Mr Turner, it might be
19 appropriate if we swap one of us and ask him to deal with
20 that.
21

22 CMDR RUSH: Mr de Yong, we will come to your section a bit
23 later. Perhaps if you withdraw.
24

25 <TERRENCE GERARD TURNER, affirmed: [2.21pm]
26

27 CMDR RUSH: Would you state your full name to the
28 Commissioner, please?
29

30 MR TURNER: Terrence Gerard Turner.
31

32 CMDR RUSH: And your address?
33

34 MR TURNER: [REDACTED]
35

36 CMDR RUSH: Your occupation?
37

38 MR TURNER: Defence scientist.
39

40 CMDR RUSH: What are your qualifications?
41

42 MR TURNER: I have a Bachelor of Science and a Master of
43 Science. I'm a chartered engineer and I'm also a Member of
44 the Royal Institution of Naval Architects.
45

46 CMDR RUSH: At DSTO, what is your general area?
47

1 MR TURNER: I have been at DSTO for 19 years. In the
2 early stages of my career, I worked in the vulnerability
3 and survivability area that Mr Buckland has given an
4 overview of over the last two days. For the last eight
5 years, I have worked in the Naval Architecture Group
6 looking at seakeeping and stability of Naval vessels.
7

8 In the latter part of 2007 and the early part of 2008,
9 I spent 12 months over in The Netherlands working on a
10 collaboration looking at damage stability of Naval vessels,
11 which considers the effect that floodwaters have on the
12 stability of vessels.
13

14 CMDR RUSH: Mr Turner, in relation to the flooding
15 consequences from torpedo damage, did you bring to bear
16 that experience and also various tools together for the
17 analysis of that?
18

19 MR TURNER: Yes, I did. The program of work that
20 I undertook whilst overseas is a collaboration between six
21 Navies and the US Coast Guard on developing tools whereby
22 we specifically focus on the stability of flooded
23 conditions of Naval vessels.
24

25 CMDR RUSH: Are there computer software packages involved
26 in bringing that together?
27

28 MR TURNER: Yes.
29

30 CMDR RUSH: As a consequence of the torpedo damage, did
31 you undertake a study as to whether the ship would have
32 survived the torpedo without the additional damage that
33 we've been through today?
34

35 MR TURNER: Yes. The first part of the analysis that
36 I undertook was considering the damage from the torpedo
37 alone and whether the Sydney would have survived that
38 event.
39

40 CMDR RUSH: In relation to establishing that and looking
41 at that, you set out at page 222 figure 205. That
42 represents what?
43

44 MR TURNER: That is a diagram that was used by the crew on
45 board Sydney to look at the flooding condition of a typical
46 weapon strike of a 700-pound warhead.
47

1 This damage extent has not been used in this analysis,
2 as reviewing the footage from the ROV, the damage extent is
3 significantly larger than what is demonstrated on this
4 diagram. This diagram was created from the knowledge that
5 was at the time during World War II.

6
7 CMDR RUSH: Who created this diagram?

8
9 MR JEREMY: It is an Admiralty document.

10
11 THE PRESIDENT: Of the 1940s?

12
13 MR JEREMY: It is dated 1940, yes.

14
15 CMDR RUSH: Mr Turner, after looking at that and assessing
16 that the damage was greater and the applicability of that
17 diagram, did you go on then to look at other materials to
18 bring it together?

19
20 MR TURNER: Yes. We looked at the footage from the ROV,
21 the work that Mr Buckland and others had done on
22 determining the actual location of the torpedo hit and
23 information also from Mr Buckland's area looking at the
24 torpedo damage extent as well. We included all of that in
25 the analysis.

26
27 CMDR RUSH: At figure 206, after assessing that, did you
28 produce a representation of what you considered to be the
29 flooding effect of the torpedo damage?

30
31 MR TURNER: Yes. This diagram actually shows the region
32 that potentially could flood, but it must be noted that
33 this region will only flood up to the new water level when
34 the Sydney trims down by the bow.

35
36 With the ROV footage, we saw that a lot of the
37 internal structure was now missing. Whether that was a
38 consequence of the torpedo damage or the sinking was yet to
39 be determined, but we assumed that all internal damage
40 within that region was missing.

41
42 We went back to approximately frame 53, which is one
43 watertight bulkhead aft of where we assumed all the damage
44 would have occurred. So this analysis is going to give us
45 the worst-case scenario that possibly could have happened
46 due to the torpedo strike alone.

1 CMDR RUSH: On the worst-case scenario, what is
2 represented as flooded in that diagram would be the event?
3

4 MR TURNER: Yes, but the entire blue section won't have
5 flooded just due to the torpedo strike alone. If we can go
6 up to table 23, I undertook a series of analysis where
7 I worked from the forward perpendicular aft, one watertight
8 bulkhead at a time, which coincides with these frames.
9 I looked at the change in the draughts at the aft and the
10 forward perpendiculars to determine how far we would need
11 to go back, up to frame 53, such that the vessel still
12 remained float. Even with the flooding back to frame 53,
13 which, as I said, is one watertight bulkhead beyond where
14 we believe the damage occurred, these figures indicate that
15 although she has trimmed significantly by the bow, there
16 was still enough buoyancy to remain afloat.
17

18 CMDR RUSH: At figure 207, there is an animated outline of
19 Sydney intact in calm water. That is to represent the
20 state that would be expected of her in her normal
21 condition?
22

23 MR TURNER: That's correct.
24

25 CMDR RUSH: At figure 208, there is shown the Sydney in
26 calm water after sustaining the flooding through the
27 torpedo damage.
28

29 MR TURNER: Yes. That figure there is after sustaining
30 the damage from the torpedo and flooded back to that one
31 watertight bulkhead aft of where we believe the damage has
32 occurred. You will notice on the forward perpendicular, if
33 you compare that with figure 207, the previous figure, the
34 change in their draught. This representation is also
35 consistent with some of the accounts from the German
36 survivors, where they believe that at various stages they
37 could see the propellers coming up out of the water as
38 well.
39

40 CMDR RUSH: How would that occur?
41

42 MR TURNER: Due to the flooding in the forward section,
43 she will trim down by the bow, which means that the aft
44 section of the ship will be sticking higher out of the
45 water.
46

47 CMDR RUSH: That is Sydney in calm water?

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47

MR TURNER: This is in calm water, yes.

CMDR RUSH: Is that flooding damage impacted if the sea state is not calm; would it be different?

MR TURNER: The level of flooding will change by only a minor state. What will change is the actual motion of the Sydney itself. In sea state 3, you are probably more likely to see the rudder coming in and out of the wave than what you would see in calm water, but the actual flooding extent would be very similar.

CMDR RUSH: Turning now to the shell damage to the Sydney and going back to an area we've covered but just trying to interpret the damage, if we could have figure 209, which shows the shell detonations aggregated on port side. I'm not sure whether it is Mr Jeremy or Mr Buckland or Dr Cannon who will want to go to this, but the general areas of the ship that that covers - we're talking about the bridge, the midships generally?

MR JEREMY: We're talking about some of the most important areas of the ship - the bridge superstructure and that area of the hull which happens to contain the main switchboard rooms, transmitting stations, lower power rooms and some of the W/T compartments, as well as the lower steering position.

CMDR RUSH: So is there any opinion formed as to the effect of the damage on the capacity in that area of the ship for control of the ship?

MR JEREMY: Substantially incapacitated.

CMDR RUSH: Over the course of this morning, there was evidence of shell damage. If we start with A and B turrets, at figure 214 there is reference to the damage to B turret. As far as A and B turrets are concerned and port side damage, have you any opinion as to the ability of those turrets, as a consequence of the damage, to operate or to move in general terms?

MR JEREMY: I think that neither turret would be operable. B turret would have been out of service as a result of the hits. It probably would not be trainable, in any case, because of damage to the roller bearing path, and A turret

1 is likely to have been damaged beyond further use by the
2 torpedo, if not by shell fire.

3
4 MR BUCKLAND: May I just add a point, that the hit in
5 between the barrels of B turret would indicate that those
6 turrets were pointing directly at Kormoran at some stage.

7
8 CMDR RUSH: With director control removed from the ship,
9 the turrets move into operation, as far as the turrets are
10 concerned, operating by themselves, effectively. Looking
11 at that photograph that is currently depicted, can you
12 point to the gun port or the gunsight there? It appears to
13 be closed.

14
15 MR JEREMY: It is open on B turret.

16
17 CMDR RUSH: From your review of the photographs of the
18 turrets, was that the position with all turrets or not?

19
20 MR JEREMY: No. The gunsighting ports are open on B and
21 open on X; they're closed on A; and Y is substantially
22 obscured by the funnel, which is draped over it, so we're
23 not sure what the position is with Y turret.

24
25 CMDR RUSH: For the turret to operate manually and to
26 bring the guns to bear, is it necessary for the gunsight to
27 be open?

28
29 MR JEREMY: Not if B turret is, for example, leading A.
30 B might be sighting for A, and X for Y, which is one
31 possible combination. But if all the turrets are operating
32 independently, we would expect to see all the gunsight
33 ports open.

34
35 CMDR RUSH: Are you able to tell us what the method of
36 communication between A and B turrets and X and Y turrets
37 would have been?

38
39 MR BUCKLAND: Yes. They used telephone communication, but
40 they say that that was really difficult to do because of
41 the noise in the turrets. The thing about operating the
42 gun is that the control orders who is going to fire the
43 gun. There was a gun controller for A and B and X and Y,
44 so that the guns would fire together in that line of
45 command. As you come down from the command, the gunnery
46 officer himself would be taking control of the gun turret.

1 CMDR RUSH: I will come back to the damage to the ship's
2 boats. As far as smoke and toxic gas are concerned, you
3 have referred, Mr Buckland, to that being generated as a
4 consequence of torpedo fire. Would you anticipate that
5 that would affect an immediate area around where the
6 torpedo hit the ship or not?
7

8 MR BUCKLAND: It definitely would be getting to that area
9 where the detonation occurred, but on each of the
10 15cm shells, the detonations inside would also generate
11 gaseous products. It would just become a black cloud after
12 the detonation. This is without fires even originating.
13 So in those rooms, then, you wouldn't be able to see
14 through to be able to get damage control crews into those
15 areas.
16

17 CMDR RUSH: Could I ask you, gentlemen, to turn to
18 page 242. Something that Mr Jeremy referred to this
19 morning, the turn to port, is discussed there. I think
20 largely it is a reiteration of what you have already
21 referred to, Mr Jeremy, but in the context of the report it
22 states there that if the ship was maintaining a straight
23 course and the telemotor pipes in use were damaged, the
24 helmsman would find the wheel dead in his hands.
25

26 MR JEREMY: Yes, it would be unresponsive. He could turn
27 it and find nothing happening.
28

29 CMDR RUSH: I think you anticipate that the turn to port
30 was a deliberate move by the crew of Sydney?
31

32 MR JEREMY: I believe it must have been, yes.
33

34 CMDR RUSH: The starboard side shell damage is examined,
35 and I think, Mr Buckland, you referred to this this morning
36 in relation to damage to the turrets. The damage to the
37 turrets could be said to look as though it is on the port
38 side, but it could in fact be as a consequence of the way
39 the guns were facing as the ship came to its change of
40 position after the turn to port?
41

42 MR BUCKLAND: For A turret, and there is a hit in the side
43 of X turret, which indicates that the turrets by that time
44 weren't pointing towards Kormoran, so they have been hit in
45 the side of the plate. I think that the shots in the
46 starboard side of A turret, by this time, too, showed that
47 there was continuous firing from the Kormoran as it was

1 doing the turn.

2

3 CMDR RUSH: At page 246, there is reference at figure 235
4 to the starboard side torpedo tubes. From your examination
5 of the torpedo tubes both port and starboard, do you have
6 an opinion as to whether Sydney fired any torpedos?

7

8 MR BUCKLAND: No, you can't tell whether it has fired any
9 torpedos. Obviously, these torpedos in the starboard side
10 tube were designated to fire in a set sequence.

11

12 CMDR RUSH: That's what I want to ask you about. You have
13 referred, for instance, to the sequence F, I, R, E. From
14 looking at the torpedos that are missing from the port and
15 starboard sides and having regard to the sequence, are you
16 able to inform us as to whether the torpedos that are
17 missing are out of sequence of what would be the normal
18 firing sequence?

19

20 MR BUCKLAND: In the case of the starboard torpedos that
21 we see on the screen at the moment, the sequence of firing
22 was Q, X, Y, Z. In this case, the torpedo that is missing
23 is Z, which would have been the last to be fired from that
24 sequence.

25

26 CMDR RUSH: Would that tend to suggest that it wasn't
27 fired?

28

29 MR BUCKLAND: It would tend to suggest that it wasn't
30 fired.

31

32 CMDR RUSH: The other three torpedos, as we see, are
33 extant.

34

35 MR BUCKLAND: Yes.

36

37 CMDR RUSH: In relation to the port side?

38

39 MR BUCKLAND: They were fired in the order of F, I, R, E,
40 and F and I are missing, which would be the first two that
41 would be fired.

42

43 THE PRESIDENT: If there is one missing on the starboard
44 side, two are missing on the port side and one is found on
45 the seabed, that means that a maximum of two could be
46 fired?

47

1 MR BUCKLAND: That's correct.

2

3 THE PRESIDENT: And if Z is missing on the starboard side,
4 it is unlikely to be that, which means that the probability
5 is that it was F and I which were fired on the port side?

6

7 MR BUCKLAND: If there were any fired, they would be the
8 ones on the port side, most probably. However, we can't
9 tell whether they have been fired or they are missing in
10 the debris field.

11

12 THE PRESIDENT: Is there any mechanism at all whereby they
13 could have fired Z on the starboard side before firing Q, X
14 and Y?

15

16 MR BUCKLAND: I don't have enough understanding of why
17 they needed to fire the three, as in whether there was a
18 shut-off switch that they couldn't fire it. As
19 I understand it, that's the firing order they would have
20 gone for, and, based on the damage, you would think that
21 they wouldn't have been able to fire. But I don't think
22 that we can come to the conclusion of which ones were fired
23 and which ones weren't.

24

25 THE PRESIDENT: Why not?

26

27 MR BUCKLAND: Because we don't know if those tubes have
28 been emptied as the one that's just sitting out on the
29 seabed.

30

31 THE PRESIDENT: But if you can't fire Z before you fire Q,
32 X and Y, then Z wasn't fired.

33

34 MR BUCKLAND: That's right, yes.

35

36 THE PRESIDENT: So the one on the seabed is likely to
37 be Z?

38

39 MR BUCKLAND: There is a possibility, yes.

40

41 MR JEREMY: It is equally possible that it is one from the
42 port side and that there were in fact only six torpedos on
43 board. It is equally possible that the other torpedos are
44 lying around somewhere. There is no way of knowing.

45

46 THE PRESIDENT: It is improbable beyond belief, in my
47 view, that they had only six torpedos on board. Their

1 fleet torpedoes would have been manned fully, I should have
2 thought, with four on each side.

3
4 MR JEREMY: One would think so.

5
6 THE PRESIDENT: On that thesis, if Z could not be fired
7 before Q, then any which were fired would have to be from
8 the port?

9
10 MR BUCKLAND: Yes.

11
12 THE PRESIDENT: And the maximum from port would be two?

13
14 MR BUCKLAND: Exactly.

15
16 THE PRESIDENT: Which is in conflict, if I may say so,
17 with all of the German evidence --

18
19 MR BUCKLAND: Yes.

20
21 THE PRESIDENT: -- which is that they were unable to fire
22 from the port side, because they were strafing the
23 respective operators with small-arms fire.

24
25 MR BUCKLAND: Yes. They could have possibly fallen out,
26 like Z has or Q has.

27
28 CMDR RUSH: Mr Buckland, I want to take you back to the
29 damage to the starboard side torpedo tube. I asked you
30 questions about it before the lunch break. In relation to
31 the damage to those tubes, as I understand it, your belief
32 is that at the time of that damage, the tubes may have been
33 pointing out rather than stowed fore and aft?

34
35 MR BUCKLAND: Yes.

36
37 CMDR RUSH: I just wonder whether the damage is also
38 consistent with their being stowed?

39
40 MR BUCKLAND: They could be damaged; it is just that
41 depending on the direction of the weapon, it is more likely
42 that they were deployed. However, it could have been a
43 weapon that came through from the port side and hit those
44 three tubes.

45
46 THE PRESIDENT: Could I ask a layman's question. Looking
47 at that picture on the screen now, as I understand your

1 evidence, it is that the shell which hit it came from
2 bottom to top diagonally across it, with the last damage
3 being the greatest damage shown on the top torpedo. Why is
4 that so? If you look at it now, why could the missile not
5 have come diagonally from the top side to the bottom side,
6 causing the greatest damage with the first hit and bending,
7 as you can see, that intervening piece of metal, on a
8 trajectory which causes lesser damage to the second and
9 minimal damage to the third?

10
11 MR BUCKLAND: That's a possibility. It is very hard from
12 that to see which way the metal has been bent. It is just
13 that as you go through, it is likely that once it connects
14 first, the velocity would cause it to yaw up and take out
15 the larger section on the furthest side. The largest
16 damage is on the inboard, if it was stowed. It is almost
17 impossible to judge. You can come up with arguments on
18 both directions.

19
20 CMDR RUSH: That photograph shows the torpedo tube as it
21 lies on the sea floor, obviously, in an inverted or
22 upside-down state.

23
24 MR BUCKLAND: That's right.

25
26 CMDR RUSH: Could I ask you to go to page 251. As
27 I understand it, what we are dealing with here,
28 Mr Buckland, is the application of what was referred to as
29 the XVAM analysis and the results of that analysis using
30 the 87 15cm shell hits to Sydney.

31
32 MR BUCKLAND: That's right.

33
34 CMDR RUSH: If you look at figure 243 on page 252, we're
35 looking at the superstructure and bridge compartments. You
36 have set out there in the right-hand side the areas
37 affected by weapons, and there is a red, grey and blue
38 section. Can you indicate to us what the different colours
39 represent?

40
41 MR BUCKLAND: These indicate areas that have been damaged
42 by weapons or have a high probability of fragment in those
43 areas. The red areas are the areas predicted to be
44 affected by fragment damage from the 15cm shell.

45
46 The grey areas are areas which we have overlaid, which
47 would have had a high risk to the small-calibre fire

1 because of the exposed nature of those areas. In this
2 case, we've indicated torpedo damage just to say that that
3 is being ignored from our study, because there was no
4 damage by the torpedo.

5
6 CMDR RUSH: Going through this deck by deck, that's the
7 superstructure and bridge, and then figure 244?

8
9 MR BUCKLAND: Then we go down to the forecastle deck.
10 Again, these are the areas that have been predicted to be
11 affected by the 15cm fragment hits. The grey areas are
12 areas that have a high likelihood of being exposed to the
13 small-calibre weapons.

14
15 CMDR RUSH: And figure 245 is the upper deck?

16
17 MR BUCKLAND: Now we're in the upper deck. In this case,
18 we're showing the area that we're ignoring for torpedo
19 damage, because by this time, the torpedo has affected that
20 area. Again, as you can see, just below the superstructure
21 area has all been affected by fragment damage.

22
23 CMDR RUSH: Then at figure 246, the lower deck
24 compartments?

25
26 MR BUCKLAND: This is a very important deck for people to
27 flow through the ship. You will see that there is going to
28 be a widespread effect from fragments entering into the
29 ship on this deck.

30
31 CMDR RUSH: Figure 247 relates to the platform deck?

32
33 MR BUCKLAND: We have areas below the superstructure deck
34 and the forward engine room, boiler room.

35
36 CMDR RUSH: Figure 248, in the hold, is just torpedo
37 damage?

38
39 MR BUCKLAND: Just torpedo damage, yes.

40
41 CMDR RUSH: As a consequence of all of that analysis, you
42 go on to look at the probability of crew casualties.

43
44 MR BUCKLAND: Exactly, yes, if we go up to figure 249.

45
46 CMDR RUSH: In figure 249, you are looking at the
47 casualties in the superstructure deck compartment from the

1 15cm shells?

2

3 MR BUCKLAND: These are spaces that have a high
4 probability for crew casualties in confined spaces from the
5 15cm shells. In the areas that are coloured red, you would
6 expect that all crew within these areas have become
7 casualties. You will see that the yellow is a medium risk
8 and green is low risk. The areas that haven't been
9 coloured haven't been assessed.

10

11 CMDR RUSH: You have done the same at figure 250 in
12 relation to the --

13

14 MR BUCKLAND: We go through each deck. Figure 250 is the
15 forecastle deck, and you will see the areas that have been
16 affected by 15cm shellfire. In figure 251, we have areas
17 forward and aft that have been affected.

18

19 CMDR RUSH: That's in the upper deck?

20

21 MR BUCKLAND: Yes.

22

23 THE PRESIDENT: Just pausing there, you said that the red
24 areas represent where there is likely to have been
25 100 per cent casualties. Is there a percentage that one
26 can put on the yellow or not?

27

28 MR BUCKLAND: Yellow represents approximately 80 per cent
29 casualties; and the green, low, is 50 per cent casualties.

30

31 CMDR RUSH: Figure 252 represents the lower deck?

32

33 MR BUCKLAND: Again, you will see that there is less
34 effect at the aft end and in the lower deck area. These
35 regions are very critical for damage control, for people
36 going up to try to do any damage control on the torpedo
37 damage. We're talking about a time delay thing, as you saw
38 with Dr Neill's simulation this morning, in that we're
39 looking at hits randomly over the ship, so as crew were
40 moving in and out of these areas to do damage control,
41 we're having various effects on being able to calculate
42 where crew are. However, if they were in these
43 compartments at the time, they would have had that high
44 risk of becoming a casualty.

45

46 CMDR RUSH: The platform deck is shown at figure 253?

47

1 MR BUCKLAND: Yes. These become some of the critical
2 regions in the breaker room and the transmitter room.

3
4 CMDR RUSH: And the hold, for 15cm shells --

5
6 MR BUCKLAND: There is nothing.

7
8 CMDR RUSH: Then, as a consequence of that assessment, did
9 you make an estimate, as best you could, of the casualties
10 caused as a consequence of the battle?

11
12 MR BUCKLAND: Correct. Table 24 gives a summation of a
13 scenario where we've located crew based on our best
14 assumption of crew at Action Stations. Obviously, this is
15 a time domain, in that we've put down casualties from
16 weapon effects, and in the second column we have put down
17 probable casualties being trapped in the lower decks due to
18 fire, smoke and evacuation effects.

19
20 The problem is that this isn't purely an effect from
21 the weapons damage from the fragment or blast damage. We
22 now have fires; we have structure being displaced
23 throughout the ship; we have the flooding up the forward;
24 we have the smoke being pushed through the ship, and it's
25 not a nice place to be.

26
27 CMDR RUSH: Is it your estimate that 70 per cent of the
28 crew would have been incapacitated as a consequence of the
29 weapons damage and being trapped in spaces due to fire?

30
31 MR BUCKLAND: Correct. On the scenario in that case, it
32 is at least 70 per cent. Based on this, the crew that
33 would have survived are now in the aft area of the ship.

34
35 THE PRESIDENT: Could we scroll down table 24, please.

36
37 MR BUCKLAND: That space is the space where we've
38 predicted that there has been no weapons damage and that is
39 still sealed off from the effects from the smoke, mostly.

40
41 THE PRESIDENT: The last column sets forth the probability
42 of casualties due to fire, smoke and evacuation effects.
43 That is additional to the second-last column, which
44 addresses the weapons effects?

45
46 MR BUCKLAND: Yes, that's correct.

47

1 THE PRESIDENT: Could we continue scrolling down. That
2 table accounts, as best you can, for all of the crew on the
3 assumption that they may have been at Action Stations?
4

5 MR BUCKLAND: Correct. Again, for this type of event, as
6 it is over 25 minutes, the crew would be moving through to
7 do damage control procedures.
8

9 CMDR RUSH: Under "Weapons Effects", Mr Buckland, at
10 page 258, you conclude that there was a total weight of
11 3,900kg of 15cm shell that hit Sydney, with a minimum of
12 200,000 individual shrapnel fragments generated as a
13 consequence?
14

15 MR BUCKLAND: Correct, and there would be the extra
16 fragments from the secondary effects of the high-velocity
17 15cm shells as they punched through the ship.
18

19 CMDR RUSH: Just dealing briefly with damage control, as a
20 consequence of the damage that has been established, is
21 there any view formed as to the effect on damage control
22 parties through the ship?
23

24 MR BUCKLAND: With regard to damage control, the main
25 stations are DC1 and DC2. The damage control stations were
26 both hit by weapons, so there would have been a large
27 number, especially in the forward lower mess 2, I think it
28 was, where damage control 1 was positioned. That would
29 have generated a lot of casualties from that one space.
30

31 THE PRESIDENT: There is a diagram somewhere.
32

33 CMDR RUSH: Figure 255, Commissioner.
34

35 MR JEREMY: No, these DC stations are a different
36 illustration.
37

38 DR CANNON: It is halfway down page 267, I think. It is
39 figure 259.
40

41 MR BUCKLAND: The green areas on that diagram indicate
42 where the damage control stations were. The forward damage
43 control space was affected badly by weapons damage; the
44 middle damage control station in midships was affected; and
45 there was a slight effect on Damage Control 3 at the rear.
46 By this stage, there would be people trying to put out
47 fires and help other casualties within the ship, so the

1 exact numbers throughout the ship would be a dynamic
2 number.

3

4 CMDR RUSH: Looking at page 260, there is reference to
5 access through the ship as a consequence of the damage. If
6 there were damage control parties trying to get about and
7 perform their duty, would you indicate your opinion of how
8 difficult it would have been to get in and about to various
9 parts of the ship as a consequence of this damage?

10

11 MR BUCKLAND: It is very hard to appreciate what it would
12 have been like. The ship is generating smoke. Each weapon
13 hit has created a lot of internal damage to electricity.
14 The power has gone out, so it's dark. You have smoke in
15 the ship. You will have the non-structural bulkheads being
16 blown out into corridors, so there is no access for crew to
17 get in and out of spaces.

18

19 The crew in the lower decks need to exit up through
20 the higher upper decks, and that will be limited as doors
21 and hatches will also become jammed from the blast
22 overpressure and the weaker doors will be blown out into
23 the corridors.

24

25 Every time a shell hit, there would have been more
26 fires being generated. As we go along over the 25 minutes
27 of the engagement, these fires are starting to coalesce and
28 become larger, and because of the nature of the hits across
29 the ship, the crew would not have known where it was safe
30 to be.

31

32 MR TURNER: In addition to all of that, you also have
33 flooding that the crew is having to contain at that stage
34 as well.

35

36 MR JEREMY: Perhaps it is also worth mentioning the way
37 that the minor bulkheads within the ship were built. The
38 photograph at figure 257 shows a damaged, blown-out
39 bulkhead in HMAS Derwent caused by a charge, as stated
40 there, but the minor bulkheads within HMAS Sydney were of
41 two kinds: bulkheads around wet spaces or electrical
42 spaces were constructed of lightweight swaged mild steel,
43 which was welded; but around other spaces, they were
44 constructed of three-sixteenths of an inch thick
45 steel-faced plywood, and this did not go all the way to the
46 deck head. It stopped one foot short of the deck head, and
47 the space above it was filled with wire mesh. Those

1 bul kheads would have offered no resi stance, effectively, to
2 blasts and would have also helped to feed the fires. The
3 lack of the bul kheads going up to the deck head would also
4 have meant that the passage of smoke would have been very
5 easy, very simple.

6
7 THE PRESIDENT: Passages for crew to traverse would have
8 been blocked?

9
10 MR JEREMY: Many of them would, I fear, yes.

11
12 CMDR RUSH: That brings to point the ability to fight
13 fires in the circumstances that prevailed as a consequence
14 of the damage. In general terms, do you have a view as to
15 what that ability was?

16
17 MR BUCKLAND: I'm not sure whether you would like to cover
18 that with Mr Gamble tomorrow or later.

19
20 CMDR RUSH: Yes. Dealing, then, with smoke, Mr Jeremy,
21 you just answered the Commi ssi oner's question, in essence,
22 from the fires generated, that it is likely that there was
23 smoke through the ship. You spoke yesterday about the
24 ventilation. To go back to that, with the fires in the
25 ship and on the deck of the ship, that was likely to create
26 smoke inside the ship?

27
28 MR JEREMY: Yes. In a modern warship, you have the
29 opportunity to crash stop ventilation fans and remotely
30 operate ventilation flaps, which can close off sections of
31 the ship very, very rapidly in the event of damage and
32 fire, but this wasn't the case in Sydney. Ventilation fans
33 would have to be stopped locally or damaged to stop, and
34 you had only predominantly natural exhaust ventilation
35 throughout the ship and no means of clearing the smoke.

36
37 CMDR RUSH: What we've seen thus far indicates that the
38 aft section of the ship was relatively undamaged and there
39 was impl osi on damage there. Would that section of the ship
40 have been affected by smoke?

41
42 MR JEREMY: Possibly, but I don't think we have any way of
43 knowi ng.

44
45 CMDR RUSH: In relation to the electrical circui try, as a
46 consequence of the damage sustained to Sydney what was the
47 impact on it and what was the likeli hood of its complete

1 operation?

2

3 MR BUCKLAND: Again, I think this is like an increasing
4 amount of damage. Initially, you could cross your ring
5 main to do damage control operations, but eventually, with
6 the switchboard and the breaker rooms being damaged, you
7 would probably have lost electricity to at least the
8 forward part of the ship.

9

10 CMDR RUSH: Mr Turner deals with the loss of Sydney.

11

12 MR TURNER: Yes, the subsequent flooding leading up to the
13 loss of the Sydney.

14

15 CMDR RUSH: We may come back to the ship's boats and try
16 to complete a section here, sir.

17

18 At page 268, in relation to the loss of Sydney, there
19 is a discussion in relation to its structural integrity.
20 It then goes on to sea loads and ultimate strength.

21

22 MR TURNER: Dr Cannon is dealing with the structural side
23 of things, and I will be dealing with the flooding.

24

25 CMDR RUSH: In relation to the loss of Sydney and the
26 structural integrity of the ship, Dr Cannon, what was
27 involved here? What were you looking at? What were you
28 trying to do?

29

30 DR CANNON: A number of suggestions have been made that
31 the trigger for the loss of Sydney was the separation of
32 the bow whilst the ship was on the surface, so the purpose
33 of this investigation was to determine whether that was
34 feasible or not.

35

36 The investigation undertook a number of different
37 phases. First of all, it was to build a structural model
38 of the Sydney, particularly around frame 27, which is where
39 the torpedo damage was. We picked frame 27 purely because
40 that was where we had the information of the plating
41 thicknesses, the stiffeners, the structure in that region.

42

43 The second part of the analysis involved building a
44 model of the ship, the hull form, so that we could
45 determine its buoyancy. We also imposed on that model the
46 mass distribution of the ship, and this enabled us to run a
47 simulation to determine the wave loads that were

1 experienced by the ship in the sea conditions experienced.

2
3 Both these models were compared to other ships. They
4 were compared to the original design conditions to make
5 sure that the model was validated.

6
7 Then we ended up running an ultimate strength
8 calculation. This ultimate strength calculation is
9 basically taking the ship as abeam, applying some loads
10 onto it and increasing the loads slowly until we get to a
11 point where some form of structure fails.

12
13 If you go to figure 260, you will see the intact
14 segment of the ship at frame 27. We apply a load to it and
15 we plot the maximum load that the ship can withstand whilst
16 it is intact. That is given by that point there.

17
18 The next thing we did to this particular structural
19 model was to impose a certain amount of damage. You can
20 see that in the lower figure there, we have taken
21 47 per cent of the structure away from the bow region where
22 the torpedo hit. Again, we apply a load slowly, and that
23 follows the pink line in that diagram up to the point of
24 failure, which is the end of the straight line there. That
25 gives us the capability or the residual strength of the
26 structure.

27
28 If you then go to the next figure down, figure 261,
29 this is quite a complex diagram, but I will try to talk you
30 through it. The first point, up towards the end where the
31 dark blue line is, the end of that straight line on the
32 previous figure, is giving you the capability of the
33 structure whilst it is intact. You can go down to where it
34 says "47 per cent". That's about there (indicating) -
35 47 per cent damage. That is showing you the reduction in
36 the end of that pink line in the previous graph. So we
37 have a big torpedo hole. The capability of my structure is
38 not as much.

39
40 The lower blue line underneath it, which is running
41 more or less parallel, is a factor that I have put on the
42 calculations because I'm dealing with a partly riveted,
43 partly welded structure, so it is a bit of uncertainty that
44 I am bringing into my analysis and reducing the strength of
45 the ship's structure. That tells you the capability of the
46 structure.

1 Then also on this graph, the horizontal lines in
2 different colours going across the graph are the loads that
3 I would expect from various sea states. You can see the
4 maximum of sea state 8, there are the loads that I would
5 expect that part of the ship to experience in sea state 8,
6 and because the capability of the structure is above it, it
7 is remaining intact. As I go down, you end up at sea
8 state 6. The waves are a lot smaller and therefore the
9 safety margin is much, much greater.

10
11 As we go further down, ultimately to the green line,
12 sea state 4, as Dr Neill indicated earlier, is an average
13 wave height of about 2.5 metres. That's the sea state that
14 has been suggested was occurring at the demise of Sydney.
15 You can see that the loads there at that part of the ship
16 are incredibly small. Even if I accept 47 per cent of the
17 damage, the capability of the ship's structure is much
18 bigger than the wave loads I would experience.

19
20 Therefore, this figure, along with the next figure,
21 which is laid out in exactly the same format, apart from
22 this time I have assumed the torpedo has taken out the
23 entire cross-section of the Sydney, so I am going up by
24 deck level from the keel, show that Sydney was a
25 sufficiently tough ship, with that size of hull, to keep
26 the bow intact.

27
28 That's the analysis we did to come to the conclusion
29 that the bow stayed intact.

30
31 CMDR RUSH: The ultimate conclusion being that the bow
32 remained intact prior to the sinking of Sydney?

33
34 DR CANNON: Yes. That must be taken in concert with the
35 other evidence that was shown earlier. Firstly, the
36 compactness of the debris field suggested that the bow
37 remained intact. Secondly, the tearing of the hull plate
38 around the side suggested that it was a more violent
39 process and there was no compressive buckling occurring.
40 Thirdly, the loads are suggesting that it wouldn't break
41 off. So there are three pieces of evidence there that come
42 together to conclude that she would have remained intact in
43 that particular environment.

44
45 CMDR RUSH: Did you also conduct a test in relation to the
46 watertight bulkheads?

47

1 DR CANNON: Yes. Yesterday, we talked about watertight
2 bulkheads that were in the lower compartment of the ship.
3 The design of watertight bulkheads is for a damaged case.
4 So if we flood a ship, we flood a compartment, and we would
5 expect some plastic deformation of those bulkheads. They
6 are due to contain that damage in that compartment. Then
7 you bring the ship back and repair the bulkheads. That was
8 a standard design practice of the day.
9

10 We looked through Sydney and picked some typical
11 bulkheads to confirm that this was the design practice that
12 was used. If you go to figure 264, again this is probably
13 another complicated diagram, but on the left-hand side, if
14 we imagine the axis as being a watertight bulkhead, if that
15 watertight bulkhead had water on one side of it and it had
16 air on the other side of it, then the green line gives you
17 an indication of what the yield strength or the loads that
18 you could put on that plate would be, such that you don't
19 get any permanent deformation.
20

21 The red line shows the load that you would have to put
22 on to get quite a significant amount of plastic
23 deformation. If that bulkhead was loaded on one side with
24 water and not on the other side, the blue line is showing
25 you the loads that I would expect on that bulkhead.
26

27 As with normal design practice, I would expect that
28 all watertight bulkheads that had water on one side and no
29 water on the other would experience significant
30 deformation.
31

32 If there was any hole, fragment damage or defect
33 within that bulkhead, the loads to cause that plastic
34 deformation would come down drastically. Given these loads
35 and given the materials, it is highly probable that some of
36 these internal bulkheads were lost during the sinking of
37 Sydney. We can't go in to confirm that, but it is highly
38 probable, given the state that we have, that a bulkhead did
39 give way and initiate some rapid flooding.
40

41 CMDR RUSH: Was that during the sinking or prior to
42 sinking?
43

44 DR CANNON: Immediately prior to sinking, if it was one of
45 the forward bulkheads.
46

47 CMDR RUSH: The impact of one bulkhead giving away is

1 what?

2

3 DR CANNON: It depends on where that particular bulkhead
4 is located within the ship. If it is one of the forward
5 ones and it is contained by the next bulkhead, it may stay
6 afloat. If it is a watertight transverse bulkhead, it may
7 improve the list of the ship. If it is the after-most one,
8 it might be the one that caused the rapid sinking.

9

10 CMDR RUSH: Then was analysis conducted of the time to
11 float?

12

13 MR TURNER: That's correct.

14

15 CMDR RUSH: Was that undertaken by you, Mr Turner?

16

17 MR TURNER: Yes.

18

19 CMDR RUSH: The purpose of this was to ascertain what?

20

21 MR TURNER: To ascertain the duration that the Sydney
22 potentially remained afloat after the battle.

23

24 CMDR RUSH: There were a number of assumptions that you
25 took in relation to forming the opinion?

26

27 MR TURNER: Yes. The first assumption was damage extent,
28 so what damage penetrations the floodwaters could actually
29 move through. I have considered this in two different
30 scenarios. The first scenario was where I just used the
31 penetrations that were observed by studying the ROV footage
32 and the torpedo damage. The second scenario was using that
33 damage as well as the additional internal damage that was
34 predicted by Mr Buckland's analysis as well.

35

36 Another assumption I was using was the sea states.
37 Based on the assumptions from the assumption list that was
38 provided to DSTO by the Commission, as well as some of the
39 accounts from German survivors, I have undertaken analysis
40 of the top of sea state 3, which we believe was the sea
41 state that the ships were in when the battle took place.
42 When the Germans evacuated their ship, they were saying
43 that the sea states were moving to sea state 4 and
44 deteriorating, so I also undertook an analysis at the top
45 of sea state 4 to look at the effect that a change in sea
46 state would have on the survival time of the Sydney.

47

1 The other assumption I have used is the speed of the
2 Sydney. If you look at the distance between the location
3 of the wreck of the Kormoran and the wreck of the Sydney
4 and utilising the time that the German survivors say that
5 they observed the glow from the Sydney to disappear on the
6 horizon, we believe that the Sydney travelled away from the
7 site of the battle at an average speed of about 2.93 knots.
8 This speed would have been affected by the change in sea
9 state and the additional flooding that was occurring
10 throughout this time, so for this analysis I used a
11 constant speed of 5 knots.
12

13 I have also assumed that the Sydney was at Action
14 Stations, which implies that all the doorways and hatches
15 were closed. If they were open, that would have also
16 contributed to additional progressive flooding throughout
17 the vessel.
18

19 CMDR RUSH: Was the heading of the ship of relevance in
20 relation to this analysis?
21

22 MR TURNER: Yes, it was. I considered various headings
23 around the compass, which I will show you on a plot in a
24 minute. If you look at the relative positions of the two
25 wreck sites - that's the wreck site of the Kormoran and the
26 wreck site of the Sydney - and the recorded sea directions
27 at the time from meteorological data, we believe that the
28 Sydney was travelling off in what we refer to as beam seas.
29 That's the relative direction of the waves to the heading
30 of the ship. In other words, the Sydney was travelling
31 potentially in that direction, and the waves were coming to
32 the starboard side of the vessel.
33

34 CMDR RUSH: Mr Turner, in relation to this analysis, did
35 you work to two scenarios?
36

37 MR TURNER: Yes. As I described before, there were two
38 scenarios: the first was utilising the ROV footage and the
39 damage extent that was observed from that alone; the second
40 was the additional information from Mr Buckland.
41

42 CMDR RUSH: Could I ask you to go to the figures that you
43 have set out at page 280. There are a number of profiles
44 through the decks. Would you indicate to us what they
45 represent?
46

47 MR TURNER: The shaded-in areas indicate the compartments

1 that could potentially flood from the time of the battle to
2 the eventual loss of the Sydney. They don't give an
3 indication as to the floodwater heights in each of those
4 compartments; they just highlight that at some stage during
5 that duration, potentially there could have been
6 floodwaters in those compartments.

7
8 CMDR RUSH: How do you ascertain that potential?

9
10 MR TURNER: Once again, using the information obtained
11 from the ROV footage and the information on damage obtained
12 from Mr Buckland's analysis and doing some simulations
13 myself, I can see where the floodwaters are moving into the
14 vessel.

15
16 CMDR RUSH: If we compare the profile that we had of the
17 flooding damage due to the torpedo alone and then the
18 profile, for instance, at figure 265, there is, obviously,
19 more extensive flooding. What is the cause of that
20 flooding or the potential of that flooding?

21
22 MR TURNER: The forward section flooding that you see in
23 this image that is on screen at the moment, from the
24 forward perpendicular up to B turret, so all the section
25 through there (indicating) is due to the torpedo damage.

26
27 All of the other sections that you see shaded in are
28 through penetrations that were initially above the
29 waterline, but as the sea states deteriorate, with the
30 waves running along the side of the ship, those
31 penetrations sometimes go below the waterline, hence you
32 get the ingress of floodwaters. And as the vessel changes
33 trim due to the floodwaters as well as starts rolling due
34 to the progressive flooding of the vessel, some of those
35 higher-up penetrations would eventually go under the water
36 as well.

37
38 CMDR RUSH: You have produced figures in relation to each
39 of the decks as far as that flooding is concerned?

40
41 MR TURNER: That's correct.

42
43 CMDR RUSH: At figure 266, we see the upper deck.

44
45 MR TURNER: Yes.

46
47 CMDR RUSH: At figure 267, we see the lower deck.

1 Figure 268 is the platform deck and figure 269 is the hold.
2 The area in the hold that is forward there, I take it,
3 comprised the watertight compartments?
4

5 MR TURNER: That's the flooded region due to the torpedo
6 strike. The white sections are watertight.
7

8 CMDR RUSH: Have you detailed the results of this
9 analysis?
10

11 MR TURNER: May I go to figure 270. I will explain how to
12 read this plot, initially. This is using the assumption of
13 the damage from the ROV footage alone. The only
14 penetrations that the floodwaters can actually go through
15 are through the openings in the hull observed from the ROV
16 and the torpedo damage that was observed from the ROV.
17

18 If you look at the axes heading north-south up the
19 page and east-west across the page where they are labelled
20 "head seas", "following seas", "port seas" and "starboard
21 seas", that's indicating the relative direction that the
22 ship is heading into the waves. As I said before, we
23 believe that the Sydney, after the battle to the demise of
24 the vessel, was travelling along the starboard seas
25 direction.
26

27 CMDR RUSH: So if we were to look at the way Sydney was
28 travelling through this plot, it was travelling from the
29 bottom of the plot to head seas at the top?
30

31 MR TURNER: No. If you look at this plot, you have to
32 think of it travelling out towards the "starboard seas"
33 label, out to the right-hand side.
34

35 Also on the plot is a series of concentric rings.
36 They indicate the analysis that has been undertaken after
37 the time of the battle. The very middle of the plot is
38 time zero in terms of my simulation. I have assumed that
39 all the damage has occurred instantaneously, because we
40 can't put an accurate time record as to where the actual
41 hits occurred relative to each other. Then, as you move
42 out to the 2, the 4, the 6, the 8, et cetera, right out to
43 the 12, that's how many hours over which the analysis has
44 taken place.
45

46 Where you observe the green areas, that's where the
47 Sydney has remained afloat for that duration. In further

1 plots, you will see some red area, and that is where the
2 Sydney has foundered or is no longer afloat.

3
4 This particular plot here is for sea state 3 and, as
5 I said, considering just the damage from the ROV footage.
6 You can see, regardless of the direction in which the
7 Sydney was heading, this analysis is showing that the
8 Sydney remained afloat for up to at least 12 hours.

9
10 The reason why I have chosen to go out only to the
11 12-hour period is the time constraints imposed on us by the
12 Commission. We needed to come up with some results, and
13 this is actually three times the believed duration that she
14 remained afloat, anyhow, so I believe that this was a
15 fairly reasonable duration to consider whether she had sunk
16 within that 4.5-hour period.

17
18 CMDR RUSH: So that relies on sea state 3?

19
20 MR TURNER: Yes, this is top of sea state 3, which is a
21 significant wave height of 1.25 metres. This is the sea
22 state at which the battle took place.

23
24 CMDR RUSH: On that scenario, Sydney remained afloat with
25 that damage, as far as you have taken it, for 12 hours?

26
27 MR TURNER: For at least 12 hours, yes.

28
29 CMDR RUSH: At least 12 hours, with the potential of more?

30
31 MR TURNER: Potentially more, yes.

32
33 Could we scroll down to figure 271. This figure shows
34 a time history of the roll of the Sydney when she was
35 sailing off in the direction in which we believe she was
36 sailing at 5 knots at the top of sea state 3. So although
37 this analysis indicates that Sydney survived up to at least
38 12 hours, you see that after a bit under the 4-hour mark,
39 the Sydney was rolling somewhere between 15 degrees and
40 42 to 45 degrees to port. This was the analysis that
41 Dr Neill's animations were based on - the time history of
42 the roll that he referred to this morning.

43
44 CMDR RUSH: So that roll is taking place even in sea
45 state 3?

46
47 MR TURNER: Yes, and this has implications on any crew

1 movements or damage control that may have been attempted to
2 be undertaken. With the vessel rolling to these angles, it
3 would have made it virtually impossible.
4

5 Could we go to figure 272. This is a screen shot from
6 Dr Neill's animation showing the roll angle of the Sydney
7 at approximately 40 degrees in the beam seas, so the
8 direction that we believe she was sailing, in the top of
9 sea state 3. It just gives you a visualisation of how
10 difficult it would have been to move about the vessel.
11

12 CMDR RUSH: That, again, is sea state 3. As Dr Neill
13 explained, that is a roll down and back up again, going
14 through the motion.
15

16 MR TURNER: Yes, it is all to the port side, so it's
17 rolling down to approximately 40 degrees, back up to
18 15 degrees to the port. As Dr Neill mentioned this
19 morning, each one of those rolls will actually go to a
20 different angle, depending on the wave environment
21 coinciding with that particular roll and the actual
22 movement of the floodwater inside the vessel.
23

24 CMDR RUSH: It is caused by the floodwater inside the
25 vessel?
26

27 MR TURNER: It's caused by a combination of the floodwater
28 inside the vessel and the ship's motion in the waves, the
29 induced motion due to the waves.
30

31 THE PRESIDENT: Are those degrees that you mentioned,
32 15 degrees to 42 degrees, all to port?
33

34 MR TURNER: Yes.
35

36 THE PRESIDENT: She never reaches an even keel?
37

38 MR TURNER: Not in this scenario, no.
39

40 CMDR RUSH: I take it that the deck on that roll to that
41 extent is starting to be covered in water?
42

43 MR TURNER: Yes. Occasionally, you will get what we call
44 deck edge immersion. Literally the deck edge is starting
45 to dip below the water and the waves, and this has
46 implications on any holes or penetrations that were
47 originally in that deck level. They were now getting below

1 the water level and additional water was coming in through
2 those penetrations.

3
4 If we now go to figure 273, this is exactly the same
5 scenario but now looking at the top of sea state 4. So we
6 have the same speeds, the same series of ship headings and
7 the same penetrations. So these are just considering the
8 penetrations through the hull from the ROV.

9
10 If you see the red region now, if you move out from
11 the centre of the plot to the edge of the green and the
12 red, say where that "2" mark is along the starboard axis,
13 this will indicate that if Sydney was sailing in that
14 direction and the sea states were in top of sea state 4, it
15 would have been just under two hours before she foundered,
16 or before she was no longer afloat.

17
18 We have a couple of regions, 60 and 120 degrees, so
19 either side of the "starboard seas", where it indicates
20 that if she had been sailing in those directions,
21 potentially she could have remained afloat for longer than
22 12 hours, but any deviation off those headings would have
23 put you back into that red zone and she potentially would
24 have gone under. That's the effect of the increase in sea
25 state alone.

26
27 The duration that we are observing here, just under
28 the two hours and up to the four hours, is consistent with
29 the duration of the accounts from the German survivors that
30 they saw the glow of the Sydney on the horizon disappear as
31 well.

32
33 I will move on to the next diagram. If we go to
34 figure 274, this scenario is now considering the damage
35 observed in the hull from the ROV footage, the torpedo
36 damage observed from the ROV footage and the additional
37 predicted internal damage due to blast and fragmentation,
38 as predicted from Mr Buckland. As Mr Buckland explained
39 before, the internal detonation of some of these munitions
40 can result in bulkheads and deck and deck heads being
41 damaged and fragmentation all through which floodwaters can
42 flow.

43
44 The one assumption I have used here is that all doors
45 and openings still remain closed, so in the event where
46 internal detonation may have dislodged some of those, I did
47 not have time to consider those in these analyses as well,

1 but that would have just accelerated some of the flooding
2 across the vessel.

3
4 This particular plot is looking at the vessel in the
5 top of sea state 3. So if you recall the plot before,
6 which was all green, and compare it with this one, the only
7 difference now is the consideration of the extra internal
8 damage, as predicted by Mr Buckland.

9
10 Once again, you have a region where Sydney may have
11 survived up to 12 hours, but you can see that with any
12 deviation, for instance, off starboard seas down to about
13 120, you are up around the four-hour mark where she may
14 have sunk.

15
16 If we now go to figure 275, this has exactly the same
17 damage definitions but considering the seas in the top of
18 sea state 4. You can now see where the boundary between
19 the green and the red areas lies is within the two to maybe
20 four, four and a bit hour mark that Sydney has survived
21 after the battle.

22
23 CMDR RUSH: So that's the impact of the difference between
24 sea state 3 and --

25
26 MR TURNER: Yes, the only difference between the previous
27 figure and this one, once again, is the sea condition, so
28 we have gone from the top of sea state 3 to the top of sea
29 state 4.

30
31 CMDR RUSH: From that, Mr Turner, you conclude, obviously,
32 that the sea state was important in relation to Sydney's
33 survival?

34
35 MR TURNER: I think that the sea state definitely had a
36 significant effect on the survival time of the Sydney. We
37 weren't able to get an appreciation of the true extent of
38 damage internally within the ship, even considering some of
39 the predicted damage that Mr Buckland found, which has
40 significant implications on the survival time of the ship
41 as well.

42
43 THE PRESIDENT: Quite apart from the sea state, if it had
44 remained at 3, unless she remained in a purely starboard
45 seas condition, she was in serious jeopardy?

46
47 MR TURNER: Exactly right. We have really no

1 understanding as to the manoeuvrability or the
2 controllability that they had at that time as well, so how
3 easy or how difficult it was to maintain heading we're not
4 sure. So you are right, any deviation from it could have
5 significantly changed the duration that she remained
6 afloat.

7
8 CMDR RUSH: Then, Mr Turner, you look at the sinking of
9 Sydney and the way in which Sydney sank and attempt to draw
10 conclusions in relation to that.

11
12 MR TURNER: Stuart, do you want to cover this, the final
13 demise?

14
15 DR CANNON: If you move to figure 276 first, I will start
16 off with this and then probably pass over to John. This
17 small flow chart is giving you an indication of the types
18 of processes that could have gone on during the sinking of
19 Sydney. She was obviously intact and fighting at the start
20 of the battle there. The first event is the torpedo hit.

21
22 One of the questions that we were asked was, did the
23 bow separate from the rest of the ship? The answer, we
24 think, is no. There are other reasons why we think the bow
25 remained intact. If the bow did break off, the structure
26 up at the bow is very heavy. There are a lot of anchor
27 chains. There are collision bulkheads. There is a lot of
28 metallic structure there. The ship itself is very fine.
29 There is not much buoyancy in that compartment.

30
31 If you take away the bow, generally the ship will trim
32 by the stern. She will be deeper in the water by the stern
33 and lift out towards the bow area. Many of the holes that
34 have been described earlier may be above the water now and
35 not underwater. So we've assumed that she was trimmed by
36 the head and that some sort of progressive flooding
37 occurred.

38
39 Then there are a number of options available. As to
40 the loss of buoyancy, she may have flooded suddenly and
41 eventually there was more water inside than air spaces to
42 hold the ship up, and that would have caused some sort of
43 rapid sinking.

44
45 We talked earlier about whether a bulkhead would
46 collapse, and, again, if an internal bulkhead collapsed,
47 that would change the times that Mr Turner has talked

1 about.

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

37

38

39

40

41

42

43

44

45

46

47

The total rollover - this is where the ship rolls over upside-down. We believe there is evidence from the wreck site that this didn't occur - things such as the 6 inch guns would have fallen off the ship during that process.

Eventually, the ship would have sunk fairly rapidly, and this would have been as a result of the motion that Dr Neill showed in his video. She would have rolled over to 45 degrees and eventually got to a roll angle from which she couldn't recover. Once she couldn't recover, she would start to sink to the seabed. It is probably appropriate that I pass over to John on that one.

MR JEREMY: We can never really know exactly what happened, of course, towards the end. It might have been a slow process or it might have been sudden. We don't know whether the ship still had power. If she was rolling from 15 degrees to 40 degrees, it is quite possible that even an intact and operating diesel generator was no longer functioning. The ship may have been in darkness.

It's quite possible that, towards the end, there was a bulkhead collapse and the ship immediately lost buoyancy, went down by the bows and plunged towards the ocean floor.

We described earlier the effect that this would have had on intact compartments within a relatively short space of time. Possibly within 30 metres of the surface, and almost certainly within 100 metres of the surface, the intact compartments would have imploded and the ship would have continued her plunge towards the sea floor. As she accelerated, the bow would have been torn off, with the loss of other structure which has passed by the ship.

The ship, being heavier, is more likely to overcome the resistance that the blunt end of the hull imposes, and she appears to have been hit by quite a few pieces of wreckage as she has gone on the way down.

This illustration shows what might have happened on the way down as the ship initially plunged, and then, as she loses the bow and fills with water right throughout, she would tend to level off and then perhaps assume a slight angle by the stern as she descends to the sea floor. We think that she probably hit the sea floor with her stern

1 first with a little bit of forward motion, which has
2 resulted in some buckling damage, of course, to the bottom
3 of the ship. It has resulted in the propeller shafts being
4 extracted from within the ship to some degree, and it has
5 broken some of the shaft brackets.

6
7 If we go back to the previous illustration, you can
8 see roughly what the stern of the ship looks like now at
9 about frame 167, where you can see the shaft brackets for
10 the inner propellers, the after-most propellers, have been
11 broken off and bent out from the ship. You can see where
12 the deck has collapsed downwards and the side has been
13 pulled inwards above the lower deck. Below the lower deck,
14 there is evidence that the ship's side, in way of those
15 watertight compartments, has collapsed inwards.

16
17 Other things would have happened, of course, during
18 that impact with the bottom. Structure weakened by fire
19 would partially have collapsed and we can see some evidence
20 of that in the forward superstructure, although some of
21 that might also be the effect of 67 years of corrosion.
22 However, the 4 inch gun deck has also partly collapsed, and
23 that is probably the result of hitting the sea floor. We
24 don't know how fast she might have been going, but the time
25 might have been somewhere between 5 and 10 minutes.

26
27 CMDR RUSH: Examples have been given in the report of
28 warships that have been hit by torpedo and survived. From
29 the analysis here, I appreciate that we've covered it
30 generally, but could I ask what is the difference here to
31 put Sydney out of the category of ship that has survived
32 torpedo damage?

33
34 MR JEREMY: It has to be the intense shell fire and the
35 perforation of the hull, which caused multiple sources of
36 flooding both from the outside of the ship to the inside
37 and between compartments internally.

38
39 CMDR RUSH: Sir, unless you have any questions, I intend
40 to call Mr de Yong to go back to the lifesaving boats and
41 deal with the search and survivors.

42
43 THE PRESIDENT: There is just one thing. There is a great
44 deal of evidence from a very large number of German
45 witnesses that the battle occurred at distances which have
46 been estimated between 900 metres and up to 2,000 metres,
47 with the predominance of the evidence being probably in the

1 order of 1,000 metres to 1,200 metres. The tables that
2 have been set out in your report show velocities and angles
3 of impact of 15cm shells. Are you able to tell me whether
4 or not the shell impact damage that you observed is
5 consistent with gunnery occurring in that range of, say,
6 1,000 metres to 1,500 metres?
7

8 MR BUCKLAND: Not from the damage itself; probably more
9 from the accuracy and the number of hits. It may have been
10 at close range, but from the elevation tables, we can see
11 that even up to 10,000 metres, the 15cm guns still have a
12 very high velocity to rip through the ship. So that is
13 still within that close range, but it is further than
14 900 metres to 1,000 metres.
15

16 THE PRESIDENT: Commonsense suggests that the more distant
17 a target, the less accurate you are likely to be.
18

19 MR BUCKLAND: Extremely. It is a very hard thing to shoot
20 from a ship accurately.
21

22 THE PRESIDENT: Is there any more science, apart from
23 commonsense?
24

25 MR BUCKLAND: Not really. Because of the velocities from
26 the 15cm shells even from a great distance, you are still
27 getting enough velocity from the shell to penetrate through
28 the bulkheads. We cannot give you an exact range of the
29 battle, based on the evidence that we have.
30

31 THE PRESIDENT: Can you tell from the photographs that you
32 have the angle of entry of shells?
33

34 MR BUCKLAND: I'm not sure whether Mr de Yong will show
35 you a picture of a boat reconstruction showing the angle of
36 reconstruction that they did with the shell coming in.
37

38 CMDR RUSH: I think it is figure 220.
39

40 DR CANNON: I think it is figure 218.
41

42 THE PRESIDENT: That is the port side whaler, yes.
43

44 MR TURNER: I will allow Mr de Yong to return to the
45 witness chair.
46

47 MR de YONG: This is a visualisation. When I gave

1 evidence earlier, I talked about the fact that one of the
2 whalers, the whaler on the port side, I believe, had
3 suffered a significant weapons hit. We then went back and
4 looked at the weapons damage on the port side that
5 Mr Buckland had identified. If we go to the image above,
6 figure 217, you will see that there is a shell hit to the
7 aircraft store that we identified should have caused damage
8 to the whaler.

9
10 In fact, Dr Neill recreated that shell hit on the
11 whaler. If we go down to the image at figure 218,
12 figure 218 is exactly that. Dr Neill was able to
13 reconstruct, from the damage to the whaler, the trajectory
14 of the shell. He matched it almost perfectly with the
15 shell hit on the structure itself. The angle or the
16 trajectory of that shell was virtually zero degrees; it was
17 virtually horizontal, which indicates that it was fired
18 from very close range.

19
20 THE PRESIDENT: Thank you.

21
22 MR BUCKLAND: There is a lot of other evidence with the
23 shell hits on the hull that shows that it hit fairly well
24 normally rather than having an angle of fall, so they are
25 close. Also, there have been groups of shots that have
26 landed in one area, which show that as the gun could fire
27 only six to seven shots per minute, there wasn't much
28 movement away, from the relative movement of the ship, so
29 that would indicate that it was close range.

30
31 THE PRESIDENT: Thank you very much.

32
33 CMDR RUSH: Sir, may I have an idea of whether you want to
34 keep going today?

35
36 THE PRESIDENT: I am happy to keep going. How long do you
37 think you would be?

38
39 CMDR RUSH: We would probably be another 40 minutes, sir.

40
41 CMDR RENWICK: I have no objection, sir, to proceeding.

42
43 SHORT ADJOURNMENT

44
45 CMDR RENWICK: Sir, with your leave, may I ask one
46 question arising from the evidence. Immediately before the
47 break, Mr Buckland and Mr de Yong gave some evidence about

1 what could be deduced from figure 218 on page 230. You
2 will recall their evidence, sir. Might I ask either of you
3 gentlemen to look at page 217, paragraph 2, where the first
4 sentence says this:

5
6 Many of the shots on Sydney hull appear to
7 have a shallow impact angle; however, it is
8 impossible to measure with any accuracy the
9 actual impact angle from the photographs of
10 Sydney.

11
12 Do I take it that what is at figure 218 is the sole
13 exception to that general principle at page 217, because
14 you have two points of reference, namely, the round going
15 through the whaler and then the impact on the side of the
16 structure of the ship itself?

17
18 MR BUCKLAND: That's correct.

19
20 MR de YONG: That's correct, yes.

21
22 CMDR RENWICK: Thank you. That was the only matter.

23
24 CMDR RUSH: Sir, there is just one matter that has been
25 brought to our attention - a photograph from the Sea Power
26 Centre that I might ask be brought up. The Australian War
27 Memorial brought it to our attention. I will just ask for
28 comment. It is depicted as the armour plating that was
29 erected around the 4 inch gun deck. The reference is at
30 Alexandria, Egypt, July 1940, the erection of that armour
31 plating on the 4 inch gun deck. In relation to height and
32 location, is that consistent with piece of the gun deck
33 that was identified I think by Mr Jeremy earlier in your
34 evidence? Is that consistent with the height and the type
35 and the nature of the material?

36
37 MR JEREMY: It is completely consistent and it is also
38 consistent with another image in the report - figure 72.
39 Figure 72 shows it quite clearly. We can see it on the
40 right-hand side of that photograph.

41
42 CMDR RUSH: I tender the photograph.

43
44 THE PRESIDENT: That will be exhibit 108.

45
46 EXHIBIT #108 PHOTOGRAPH FROM SEA POWER CENTRE, DEPICTING
47 ARMOUR PLATING ERECTED AROUND THE 4 INCH GUN DECK ON

1 HMAS SYDNEY

2

3 CMDR RUSH: I have no other questions of these gentlemen.
4 I call Mr de Yong.

5

6 THE PRESIDENT: You have no other questions?

7

8 CMDR RENWICK: No, thank you, sir.

9

10 THE PRESIDENT: Thank you very much, gentlemen.

11

12 CMDR RUSH: Mr de Yong, if I may briefly deal with the
13 likely damage to ship's boats as a consequence of the
14 battle damage that we've discussed this afternoon. You
15 have identified in previous evidence where the boats are.
16 Taking an overall perspective, what do you say as to the
17 consequences for ship's boats in the context of the damage
18 that has occurred to the ship?

19

20 MR de YONG: I have already discussed this, to a degree,
21 in earlier evidence, but the evidence of the ship's boats
22 on the seabed indicates that there is damage to the whaler,
23 and we've just had a discussion about that. If we look at
24 the port side first, we have the damage to the whaler. The
25 pinnacle seems relatively intact on the seabed, but
26 I clarify that by saying that it is very difficult to look
27 at and detail fragment damage on the wooden boats.

28

29 As for the cutter, the davits are gone. We've seen
30 the damage around the davit holders, and the cutter would
31 have fallen off very early in the engagement.

32

33 If we move to the boats on the starboard side, both
34 motorboats are on the seabed. One is in good condition;
35 one is in not-so-good condition. Because of the absence of
36 the davit holders and the davits, I believe that the cutter
37 was blown off and was unavailable for any lifesaving
38 operation.

39

40 As to the whaler on the starboard side, as
41 I identified earlier in my evidence, I believe there is a
42 single shell hole to that whaler as well, which would have
43 rendered it fairly useless for lifesaving.

44

45 CMDR RUSH: What about the Carley floats?

46

47 MR de YONG: As I commented earlier, there is no evidence

1 of any Carley floats on board the wreck or in the debris
2 field. Carley floats, as I also indicated earlier, were
3 held to the ship fairly lightly. In my opinion, they would
4 have been blown off during the engagement and possibly
5 seriously damaged due to fragments and possibly fire during
6 the engagement.

7
8 CMDR RUSH: Mr de Yong, did you also examine information
9 in relation to the search that was conducted for Sydney,
10 and did you particularly look at the air search and the
11 results of that search?

12
13 MR de YONG: Yes, I did. The action between Kormoran and
14 Sydney occurred on 19 November. The search was initiated
15 on 24 November. That was a limited fan search conducted
16 from Rottneest Island. If you look at figure 279 in the
17 report, this is a compilation of all the search sorties
18 that were flown, excluding the first search on the 24th,
19 because it was too far to the south to have really been of
20 any use, so it is not included in this compilation here.

21
22 In total, there were 118 sorties flown. That involved
23 825 flying hours, six Naval ships and 15 merchant ships in
24 total. A number of items were found, predominantly the
25 Germans from the Kormoran in their lifeboats, and a number
26 of other items, such as lifebelts, Carley floats and
27 various other smaller items were discovered.

28
29 THE PRESIDENT: Only one Carley float, I think, that may
30 have come from Australia, and two Carley floats from the
31 German ship.

32
33 MR de YONG: That's correct.

34
35 CMDR RUSH: They were located by ships that were
36 searching?

37
38 MR de YONG: All the items of that nature were discovered
39 by the ships. No items of that nature were discovered by
40 any of the air sorties.

41
42 The initial search was directed to look for Sydney.
43 They were therefore looking for an object in the ocean that
44 was over 550 feet long. Therefore, the search would have
45 been conducted at a commensurate height. At that height,
46 it would have been virtually impossible to detect possibly
47 lifeboats, let alone Carley floats or individuals floating

1 in the water. Subsequent sorties were instructed to find
2 Sydney or to find lifeboats.

3
4 CMDR RUSH: Just to clarify from the figure and diagram
5 currently being shown, were the sorties flown over the
6 areas where Carley floats and lifejackets were eventually
7 found by ships?

8
9 MR de YONG: Yes. The red arrow gives a very approximate
10 indication of where the wrecks were found. The dots to the
11 direct north of that - the two purple dots and a green
12 dot - indicate the areas where those items were discovered.
13 As you can see, a large number of air sorties were flown
14 over those items as they drifted from where the battle
15 occurred to where they were eventually discovered, and none
16 of them were detected by any of the aircraft.

17
18 CMDR RUSH: Mr de Yong, did you have available to you
19 research that had been undertaken by the US Coast Guard in
20 relation to surveillance by aircraft and the heights that
21 it is necessary to fly at to pick up the objects that were
22 picked up - the Carley floats or the lifejackets or,
23 indeed, persons in the water?

24
25 MR de YONG: I believe that the air sorties were flown at
26 a height of approximately 1,500 feet. The US Coast Guard
27 has done extensive work looking at search and rescue of
28 individuals. The particular reference that appears in the
29 report is to some recent work done by the US Coast Guard
30 trying to spot individuals in the water.

31
32 The evidence from an extensive evaluation conducted by
33 the US Coast Guard is that any individual in the water
34 distanced from the searching aircraft by more than
35 approximately 0.6 nautical miles would have very, very low
36 probability of being detected.

37
38 That search was conducted by a US Coast Guard aircraft
39 flying at 627 feet. However, it was probably flying faster
40 than the aircraft that were used during the search for the
41 survivors of Sydney. So there are some differences, but it
42 does point to the fact that there is a high probability
43 that it was very difficult to detect individuals floating
44 in the water from 1,500 feet during that search process.

45
46 CMDR RUSH: Did you also examine, Mr de Yong, the
47 likelihood of survivors from either of the ships if they

1 had abandoned ship into the water?

2

3 MR de YONG: One of the interesting things about the
4 search process was that we tended to concentrate on the
5 survivors from Sydney, but there were some 60 crew from
6 Kormoran who actually attempted to abandon ship, and their
7 life raft or their rubber raft overturned during the
8 process of abandoning ship and they all fell into the
9 water. They had personal life vests on, but none of them
10 were detected by any of the search aircraft, either.

11

12 CMDR RUSH: Was hypothermia a consideration in the area of
13 the loss of Sydney and Kormoran?

14

15 MR de YONG: No, it wasn't. The water temperature around
16 the battle site was 23 or 24 degrees, based on historical
17 meteorological data. If an individual is in the water,
18 hypothermia is generally only a problem when the water
19 temperature drops certainly below 20 degrees but usually
20 below 10 to 15 degrees.

21

22 Let's look at figure 283. This is some recent data
23 looking at the survival of individuals in the water. This
24 is from modelling data, as you will appreciate. None of
25 this data could be verified, but it gives you a general
26 idea of how long a person can survive in the water at
27 different water temperatures.

28

29 There is a wide spread there, but essentially it tells
30 you that at a temperature between 20 and 25 degrees a
31 person can survive in the water for periods up to 40 or
32 50 hours before drowning or other consequences cause major
33 problems and the person will not be able to survive.

34

35 CMDR RUSH: Did you also examine the consequences for a
36 body in the water in the area of the engagement between
37 Sydney and Kormoran?

38

39 MR de YONG: One of the things that happens when a person
40 drowns is that the body doesn't remain on the surface; the
41 body sinks, because it loses its buoyancy. Generally, it
42 sinks to the seabed. What happens then is that a process
43 occurs within the body where the body starts to decompose.
44 Gas forms within the abdomen. That causes the body to
45 retain or increase its buoyancy, and the body floats back
46 up to the surface again.

47

1 That usually occurs within a time period of
2 approximately three to ten days, but it is very broad. It
3 is heavily dependent upon the temperature of the water and
4 it is also heavily dependent upon the depth to which the
5 body sinks.

6
7 In the case of Sydney, my analysis suggests that any
8 body that would have drowned would have sunk to the bottom
9 of the seabed. The putrefaction process, the decomposition
10 and gas-formation process, would have occurred, but the
11 weight of water above the body would simply have been far,
12 far too great for any of the bodies to have floated back up
13 to the surface.

14
15 CMDR RUSH: Do the temperatures of the water at the depths
16 that we're talking about have any impact on that?

17
18 MR de YONG: If there was any chance of the body floating
19 to the surface - and I couch that with a very, very big
20 "if" - the water temperature at 2,500 metres I think was
21 approximately 2.5 degrees, based on historical data. It is
22 highly likely that at that water temperature, a body would
23 not have floated back to the surface, if it was able to
24 float or to rise again, until well after five to ten days.

25
26 The air search was terminated during that period of
27 time, so it is highly likely that if any body was able to
28 rise, it would have risen to the surface after the air
29 search was terminated.

30
31 CMDR RUSH: In your report, you refer to the average
32 surface temperature of the water as being between, I think,
33 23 and 24 degrees.

34
35 MR de YONG: Yes.

36
37 CMDR RUSH: Is there any material or evidence as to the
38 risk of shark attack with temperatures of that nature?

39
40 MR de YONG: It is certainly an issue. Again, we know
41 from a number of examples of World War II ship sinkings
42 that, in warmer waters, shark attacks on survivors were
43 common. There are a number of particular examples - the
44 USS Indianapolis. In the case of Sydney, we know that one
45 of the German lifeboats reported that their lifeboat was
46 followed by a number of sharks, so shark attack on any
47 survivors is certainly a high probability.

1
2 Again, US Coast Guard and US Navy data suggests that
3 the probability of a shark attack on someone who is
4 floating in an ocean increases significantly when the water
5 temperature increases above 20 degrees C.

6
7 THE PRESIDENT: But the high probability is that none of
8 these bodies would have risen?

9
10 MR de YONG: The high probability is that none of the
11 bodies would have risen, that's correct.

12
13 CMDR RUSH: I have no further questions, sir, at this
14 stage. Thank you, Mr de Yong.

15
16 Sir, I wish to call Mr Gamble and Ms Suendermann in
17 relation to a couple of matters - the operational aspects
18 of Sydney in relation to fire and also in relation to
19 damage control.

20
21 <BRIGITTA SUENDERMANN, affirmed: [4.20pm]

22
23 <GRANT IAN GAMBLE, affirmed: [4.20pm]

24
25 CMDR RUSH: Mr Gamble, would you state your full name and
26 address to the Commission, please?

27
28 MR GAMBLE: Grant Ian Gamble [REDACTED]
29 [REDACTED]

30
31 CMDR RUSH: And your qualifications?

32
33 MR GAMBLE: A Bachelor of Science degree, majoring in
34 physics and computer science.

35
36 CMDR RUSH: You are employed, and have been for some time,
37 by the DSTO?

38
39 MR GAMBLE: I'm a Defence scientist within the DSTO. I've
40 been there since 1991.

41
42 CMDR RUSH: Your particular area?

43
44 MR GAMBLE: I work in an area that deals with fire and
45 smoke, damage control and lifesaving and evacuation
46 systems.
47

1 CMDR RUSH: Is that in relation to the Maritime Platforms
2 Division?

3
4 MR GAMBLE: In support of Navy submarines and surface
5 ships.

6
7 CMDR RUSH: Could you state your full name and address,
8 please, Ms Suendermann?

9
10 MS SUENDERMANN: Brigitta Suendermann, [REDACTED]
11 [REDACTED]

12
13 CMDR RUSH: And your qualifications?

14
15 MS SUENDERMANN: I have a Bachelor of Applied Science and
16 a Masters of Applied Science.

17
18 CMDR RUSH: You are employed by the DSTO, and have been
19 for some time, in what area?

20
21 MS SUENDERMANN: Also with the Maritime Platforms Division
22 in fire and damage control research, undergoing analysis of
23 fire risk assessments on ships, mathematical fire modelling
24 and fire trials.

25
26 CMDR RUSH: Did you jointly attempt to examine the
27 organisation of the ship, doing so without a watch and
28 station bill?

29
30 MR GAMBLE: Yes.

31
32 CMDR RUSH: From that examination, did you produce
33 a table - table 14 on page 104 - based on other ships and
34 other Navies, of the likely distribution of personnel
35 through the ship?

36
37 MS SUENDERMANN: Yes, we did.

38
39 THE PRESIDENT: At Action Stations?

40
41 MS SUENDERMANN: At Action Stations, yes.

42
43 CMDR RUSH: Just to show that, at page 104, if we go down
44 the column to the fourth, we're dealing with the painter,
45 the plumber, the blacksmith and the joiner. At Action
46 Stations, they are at a damage control station?
47

1 MS SUENDERMANN: At a guess, an educated guess. The
2 painter I don't know about. The plumber is obviously quite
3 useful, and the same with the joiner and the blacksmith.
4 They're useful for damage control purposes.

5
6 CMDR RUSH: You went to US Navy data and the like to try
7 to establish a pattern in relation to the distribution of
8 men in Sydney?

9
10 MS SUENDERMANN: That's correct. We went to the US Damage
11 Control Book of 1945, because information from the British
12 Navy wasn't available to us. That was four years later.
13 The organisation will not have changed significantly. We
14 used this information for where we expected people to be at
15 Action Stations.

16
17 CMDR RUSH: From that information and also other material,
18 firstly, did you work out where the damage control sections
19 would be located at Action Stations on Sydney?

20
21 MS SUENDERMANN: Yes. Looking at information from
22 HMAS Hobart, which had an incident on torpedo hit a few
23 years later, they detailed three damage control stations,
24 which have been indicated already today.

25
26 CMDR RUSH: That's at figure 78.

27
28 MS SUENDERMANN: They are the green blobs. They are all
29 on the lower deck. The forward one is underneath, in the
30 mess area, between the two turrets. The central one, DC2,
31 is in the electrical engineer's workshop and predominantly
32 would deal with the engine spaces, which are distributed
33 either side. The aft one is also in a mess area and is
34 fairly close to the wardroom flat. The damage control
35 headquarters is in the lower steering compartment on the
36 platform deck.

37
38 CMDR RUSH: So the damage control headquarters is on the
39 platform deck in the forward steering compartment?

40
41 MS SUENDERMANN: The lower steering compartment.

42
43 CMDR RUSH: Who was the officer in charge of damage
44 control?

45
46 MS SUENDERMANN: We have a discussion about that, whether
47 it is actually the executive officer or possibly the senior

1 engineer on board. There is usually a group of officers
2 involved in damage control with the overseeing of the
3 organisation.

4
5 CMDR RUSH: You set out the damage control and examples of
6 damage control at figure 81.

7
8 MS SUENDERMANN: Yes.

9
10 CMDR RUSH: That is at page 115, which we are just coming
11 to. The splinter boxes and the wood shoring and the like
12 would look, according to the diagram, to be a fairly
13 old-fashioned method of damage control.

14
15 MS SUENDERMANN: It is still in current use today.

16
17 CMDR RUSH: If we can look at the individual sections in
18 that figure, at (a) we're dealing with a system of plugging
19 using pieces of timber.

20
21 MS SUENDERMANN: Correct. If you have a hole in a
22 bulkhead, the more obstacles you can put into that hole the
23 less leakage you are going to have through it. The idea of
24 this method is to stop the ingress of water into your
25 compartment, so if you can jam objects into it, that will
26 slow down the leakage.

27
28 They have on board wedges and lumps of wood
29 specifically for blocking holes, and obviously the hammer,
30 but they could use anything on hand to block holes.

31
32 CMDR RUSH: Figure (b) shows bracing. What is the purpose
33 of that?

34
35 MS SUENDERMANN: You can see that there is a bow in the
36 vertical, which means that there is some pressure on the
37 other side - presumably water - so you can try to brace it;
38 you can try to strengthen that bulkhead. The bracing
39 pieces usually are lengths of wood, four-by-two typically.
40 Again, still carried on board ships today.

41
42 CMDR RUSH: Then there is a figure demonstrating a
43 splinter box.

44
45 MS SUENDERMANN: A splinter box is made from steel. Some
46 of them, I think, were made on board. They carried them.
47 As the central part of this diagram shows, you put them

1 over the damaged hull to cover the entire hole, if
2 possible. You would presumably do this to a deck that is
3 still above the waterline. It is a bit hard to do it when
4 you are under the water.

5
6 CMDR RUSH: Then the splinter box, as we see, is shored in
7 place.

8
9 MS SUENDERMANN: Yes. It has to be held in place. There
10 should be men in place to watch these various types of
11 repair.

12
13 CMDR RUSH: Apart from the repair types set out in those
14 figures, are you aware of any other types of damage control
15 for the plugging of holes in ships?

16
17 MS SUENDERMANN: There are other forms. These are just
18 examples of how you would use the shoring. You could block
19 them up in various ways. You can shore over hatches; you
20 can brace doors.

21
22 MR GAMBLE: There was an example from the Second World War
23 where a split in a bulkhead or a deck was sealed with wads
24 of clothing and then shored in place with timber. That's
25 another method that could be used.

26
27 CMDR RUSH: From your examination of the systems that were
28 available, having regard to the damage that we've seen that
29 was sustained by Sydney, have you any view as to the
30 effectiveness of this form of damage control?

31
32 MR GAMBLE: There were examples in the Second World War of
33 ships sustaining torpedo damage, both forward and aft. In
34 those examples, bulkheads were shored to be reinforced, to
35 ensure that they didn't collapse under the pressure of
36 floodwater. In the cases where that happened, they were
37 single events, so just a torpedo hit; there weren't
38 subsequent torpedo hits or shell hits to those ships.

39
40 CMDR RUSH: Were the damage control parties equipped by
41 number and by resources to cope with the sort of damage
42 that Sydney sustained?

43
44 MR GAMBLE: We don't believe so. In addition, casualties
45 from the weapon impacts would have caused a loss of numbers
46 in the damage control organisation, making it more
47 difficult to repair the damage.

1
2 CMDR RUSH: You identified the positions on the ship for
3 the various damage control parties. Were they each given
4 responsibility for a particular section of the ship?
5

6 MS SUENDERMANN: Yes, they would have been responsible for
7 the areas around where they were located, but if there had
8 been no damage in their area, they would have been called
9 along to other areas to assist.

10
11 CMDR RUSH: Mr Gamble, I am going to ask you this
12 generally: have you also examined, to an extent, the
13 electrical circuitry of Hobart?
14

15 MR GAMBLE: There is a number of examples of descriptions
16 of electrical systems on British-designed ships in the
17 Second World War, and they give a good overview of how
18 those systems were operated.
19

20 CMDR RUSH: In relation to the damage sustained by Sydney
21 from torpedo and shellfire, overall, do you have an opinion
22 as to the impact that that would have had on the electrical
23 systems?
24

25 MR GAMBLE: We heard a general description earlier of the
26 electrical distribution system which is known as the
27 ring main. The ring main and the electrical generators,
28 four in total, were all located on the platform deck. Also
29 on the platform deck was the switchboard room, which was
30 the control and monitoring system for the electrical
31 distribution system, and six breaker rooms. Basically,
32 these allowed electrical power to be run from the ring main
33 to individual electrical pieces of equipment.
34

35 If we look at the predicted extent of damage plans, at
36 figure 247 --
37

38 CMDR RUSH: That is the damage to the platform deck
39 compartment.
40

41 MR GAMBLE: Yes. As I said, this is where most of the
42 major components of the electrical generation and
43 distribution system were installed. In the forward section
44 of the ship we can see predicted damage to two complete
45 sections of the ship. That is two sections between
46 watertight bulkheads. So it is quite a large area of
47 damage. Forward of this damage and aft of the torpedo

1 damage were two of the breaker rooms which distributed
2 power to individual pieces of electrical equipment in the
3 forward section of the ship. Aft of these two sections
4 were another two breaker rooms and the switchboard room.
5

6 The switchboard room is also predicted to have
7 suffered damage, and while the loss of the switchboard room
8 wouldn't have rendered the electrical system inoperable, it
9 would have caused delays and difficulty as crew would have
10 to move around the ship, particularly on the platform deck,
11 to operate the breakers which opened and closed supply to
12 various pieces of equipment or circuits.
13

14 There is also predicted damage at that level to the
15 forward boiler room and also some to the forward engine
16 room. This is an area where, at the side of the ship, the
17 ring main cables ran, basically.
18

19 So all of that predicted damage combined results in a
20 probable loss of the electrical system to the forward
21 section of the ship, and if we go up to the lower deck, in
22 figure 246, in this case the predicted damage is even
23 greater than on the platform deck in the forward section of
24 the ship.
25

26 So the branch lines from the breaker rooms would run
27 up to the lower deck and then further up the ship to
28 control the various pieces of equipment - lighting and
29 ventilation, motors for the various pieces of equipment and
30 the like - so it is likely that or most of these branch
31 lines would be damaged as well, rendering the system
32 inoperable in the forward section.
33

34 The damage to the aft of the ship is not as severe,
35 and it is possible, particularly on the platform deck, that
36 the ring main in this area and the breakers were intact.
37

38 When the ship moved to Action Stations, the crew would
39 have split the ring main into four sections. Two of those
40 sections would have supplied the forward section of the
41 ship and two supplied the aft section of the ship. So it
42 is possible that the aft two sections remained intact.
43

44 CMDR RUSH: The electrical system relied upon, I think,
45 two generators to maintain --
46

47 MR GAMBLE: There were two steam-powered generators, one

1 in the forward engine room and one in the aft engine room,
2 and two diesel-powered generators which were outside of the
3 aft boiler room. Each of these would supply ring main
4 cables on either side of the ship, and through the use of
5 emergency cables which the ship would have also carried,
6 the generators could have supplied other sections of the
7 ring main or equipment directly using emergency cables.

8
9 CMDR RUSH: Having regard to the damage to the ship and
10 the roll of the ship as depicted, what impact on damage
11 control and personnel involved in damage control do you see
12 that having?
13

14 MR GAMBLE: The roll angles described were quite steep.
15 There is a report from HMAS Australia in 1945 when the ship
16 was damaged by Japanese aircraft deliberately hitting the
17 ship. One of those caused flooding and the ship was
18 deliberately listed to 10 degrees to reduce the water
19 pressure on a particular bulkhead. Comments from that
20 damage report say that the ship would have been unworkable
21 at a greater angle, so greater than 10 degrees would have
22 rendered the ship effectively unworkable. So at between
23 I think 15 and 40 degrees it would have been very difficult
24 to undertake any operations on the ship.
25

26 CMDR RUSH: Can I ask you to turn to page 170. You there
27 examine fire damage. At figure 145 there are set out
28 examples of fire damage to the ship. You have picked four
29 photographs to depict that damage. Perhaps if we examine
30 the officers' galley on the forecastle deck. What are we
31 looking at there to delineate the fire damage?
32

33 MR GAMBLE: Okay. This first example of fire damage,
34 around the outside of the compartment there, along the
35 edges and the corner, we can see paint that has blackened
36 and is damaged from heat, so either from heat transfer from
37 inside that compartment or flames on the exterior of that
38 compartment.
39

40 CMDR RUSH: Perhaps if we go across to the adjacent
41 photograph of the captain's sleeping space on the upper
42 deck.
43

44 MR GAMBLE: This type of patching pattern, if you like, is
45 typical of heat transfer from inside a compartment to the
46 outside. Generally, we see the centre of the steel plating
47 damaged by fire or by heat, and less damage at the top and

1 the bottom and in the corners of those compartments, where
2 there is heavier steel structure which takes longer to heat
3 up and can conduct the heat away, so causing less damage.

4
5 CMDR RUSH: So as a consequence of the photographic and
6 video imagery, were you able to produce a diagram of the
7 various decks of the ship and indicate where the fire
8 damage was to Sydney, based on that evidence?

9
10 MR GAMBLE: We did predict fire damage to the exterior of
11 the ship. We used the damage to the paint as the indicator
12 for this. We disregarded a number of areas where the paint
13 or the metal was degraded. These weren't consistent with
14 fire damage. But large areas of the upper decks were,
15 including from the bridge --

16
17 CMDR RUSH: Perhaps if we look at figure 146.

18
19 MR GAMBLE: On the port side, we see basically from the
20 bridge extending right down to the lower deck we have fire
21 damage, and on the starboard side from the bridge down to
22 upper deck. Amidships we have the structure below the
23 aircraft catapult. You can see that there were fires
24 there. On the aft upper deck and forecastle decks we also
25 have predicted some fire damage in that area.

26
27 CMDR RUSH: The areas that you have just gone to were on
28 both the port and starboard side.

29
30 MR GAMBLE: On port and starboard.

31
32 CMDR RUSH: Then on the forecastle deck?

33
34 MR GAMBLE: The plan images are simply an estimate of the
35 fire internally based on the external damage. While we
36 can't see inside the ship to look at that damage, it is a
37 reasonable prediction of the internal fire spread.

38
39 CMDR RUSH: You have indicated areas there both forward
40 and aft on the forecastle deck and, just below that, the
41 upper deck, of fire damage internally.

42
43 MR GAMBLE: Yes, internally.

44
45 CMDR RUSH: Then on the lower deck, smaller areas of fire
46 damage.

47

1 MR GAMBLE: On the port side forward and starboard side
2 aft.

3
4 CMDR RUSH: That is what you were able to ascertain from
5 what was shown on the evidence provided from the images of
6 the ship.

7
8 MR GAMBLE: Yes, along with the shell impacts, which
9 provide the most probable cause of ignition of combustible
10 materials in those areas.

11
12 CMDR RUSH: Would the fires be limited to that, or is
13 there potential for fire inside the ship that just can't be
14 determined.

15
16 MR GAMBLE: There is potential for greater areas of fire
17 inside the ship that simply haven't transferred to the
18 exterior paint.

19
20 CMDR RUSH: There are just a couple of other matters. At
21 page 233 of the report, in paragraph 7.2.3, there is a
22 statement that the fires would have eventually joined to
23 form a larger conflagration, joined together. What are we
24 talking about there.

25
26 MR GAMBLE: Because of the large number of hits to the
27 forward bridge structure and below, there were a lot of hot
28 fragments flying around, so it is possible that a number of
29 small fires were initially ignited and eventually those
30 fires would have spread and formed the large area of fire
31 that we see predicted.

32
33 CMDR RUSH: Finally, did you undertake, by looking at the
34 design plans for Sydney, the task of trying to assess, if
35 he was in the forward steering position, how the XO might
36 have got to the after steering position?

37
38 MR GAMBLE: Yes. It is assumed that the XO's position at
39 Action Stations would be the lower steering position, which
40 also acted as damage control headquarters. This practice
41 was in place, and is still used in modern Navies, to
42 separate the commanding officer and the executive officer,
43 so that if the commanding officer becomes a casualty, the
44 executive officer can assume command.

45
46 In this case, there was predicted damage to the bridge
47 early in the battle, in which case the XO would probably

1 have to assume command, being the highest-ranking
2 able-bodied officer on the ship. To do this, he would most
3 likely move to the aft control position.

4
5 There is a number of possible routes to move to that
6 location. The lower steering position is on the platform
7 deck, so the XO would have to move up to the lower deck.
8 There is only one possible route for this. Then there is a
9 number of routes to move along the lower deck for most of
10 the journey or some of the journey, and then move up to the
11 upper deck and eventually up to the aft control position.

12
13 CMDR RUSH: Do all the routes, at one stage or another,
14 have the XO on the upper deck?

15
16 MR GAMBLE: Yes. The XO needs to move to the upper deck
17 at some stage. On the route that offers the most
18 protection, the XO stays on the lower deck and moves up
19 through a hatch which is on the starboard side of the ship
20 and some what protected by the aft structure. That would
21 be the route that would offer the most protection from fire
22 from Kormoran.

23
24 THE PRESIDENT: That practice of separating the captain
25 from the executive officer occurs only when the ship goes
26 to Action Stations; is that right?

27
28 MR GAMBLE: I believe so.

29
30 CMDR RUSH: In general terms, the time taken to move from
31 that steering position to the aft steering position is
32 three to four minutes?

33
34 MR GAMBLE: Somewhere between two and a half and four
35 minutes, depending on the route chosen. The major
36 difference in time is that if the executive officer stays
37 below deck there are more doors to go through and at Action
38 Stations these would be closed and all the clips or dogs
39 would be in place. So it takes some time to open a door.

40
41 CMDR RUSH: What you are saying is, for crew to move from
42 that area of the ship where the XO may be, in general
43 terms, to the aft area of the ship, if the ship be at
44 Action Stations, is quite an intricate and detailed
45 journey?

46
47 MR GAMBLE: It is quite a distance from the base of the

1 area of the bridge to the aft structure of the ship. If we
2 bring up one of the diagrams on page 238, if we move to the
3 bottom, this is the slowest route but that which offers the
4 greatest protection. You will see that the bottom drawing
5 is the platform deck. There is a short movement to a hatch
6 up to the lower deck. There is then movement along the
7 lower deck for quite a distance, going through a number of
8 watertight doors, to a point where movement up through a
9 hatch can be made to the upper deck. Then there is a short
10 movement aft and then up a ladder to the forecastle deck.
11 Then there is another ladder and movement across some open
12 space to the door of the aft control position, which is on
13 the port side of the compartment. This is where, in the
14 case of the loss of the bridge, the ship would be
15 controlled from.

16
17 CMDR RUSH: I think they are the matters that I wanted to
18 raise, sir.

19
20 THE PRESIDENT: Thank you. Could we bring up figure 82,
21 please, on page 116. This, as I understand it, is an
22 illustration of what any person surviving below after the
23 attack would have to do to try to get to a compartment
24 through a watertight barrier; is that right?

25
26 MR GAMBLE: Correct.

27
28 THE PRESIDENT: What is involved in going, for instance,
29 from the 4 inch HA magazine up to the sick bay or,
30 alternatively, up above the galley into the upper deck.
31 Would somebody have to walk up or climb up a series of
32 ladders?

33
34 MS SUENDERMANN: Yes.

35
36 THE PRESIDENT: In that instance that I have mentioned, up
37 through some three or four decks?

38
39 MS SUENDERMANN: That's correct. Most of the watertight
40 bulkheads below the lower deck don't have passage across
41 them; there is no doorway, so you need to go up. The
42 exception is the high-angle calculation position. From
43 there you need to traverse a bulkhead at 76 in order to get
44 out of the room. So you go through a series of doors
45 through the transmitting station, through the low power
46 compass room - it actually may not be that room. These
47 rooms are along the centre line. So I'm not sure if the

1 doors are actually along the centre line, but they are
2 within that section of the ship.
3

4 You then need to go up a ladder. If you are at Action
5 Stations, you need to un-dog the hatch at the top of the
6 ladder. You then have to dog it again, because you are
7 still at Action Stations and you still need to maintain
8 watertight integrity in all places. In this case, you then
9 need to go up another ladder, with a hatch again, and you
10 can either go aft to the boiler room or forward through the
11 stokers' mess, and up either a ladder into the galley, or
12 you can go across to the lower mess, again, through a door.
13 The bright red arrows indicate that there is a doorway
14 through the watertight bulkhead. You need to un-dog that
15 door and then re-dog it on the other side.
16

17 THE PRESIDENT: The reason I raise it is because it seems
18 to me that the prospect of anyone being able to achieve
19 that --
20

21 MS SUENDERMANN: Is remote.
22

23 THE PRESIDENT: -- in circumstances where there was no
24 power, so no light, where much of this area had been
25 subject to heavy bombardment and was on fire and
26 smoke-filled, would seem to me to be extremely remote.
27

28 MS SUENDERMANN: Correct. There would be a lot of damage
29 blocking access as well.
30

31 THE PRESIDENT: It would seem to me that the person
32 seeking to do so also wouldn't know if they were going to a
33 safer or a less-safe place.
34

35 MS SUENDERMANN: Correct.
36

37 CMDR RUSH: I have no other matters, sir.
38

39 THE PRESIDENT: LCDR Katter, do you have any questions?
40

41 LCDR KATTER: Nothing further, sir.
42

43 THE PRESIDENT: Thank you.
44

45 CMDR RUSH: Sir, there are two questions that I have which
46 I think Mr Jeremy may be able to answer. They are very
47 brief. I think as a matter of completeness I would like to

1 do that.

2

3 THE PRESIDENT: Yes, very well.

4

5 (Mr Jeremy returned to the witness box.)

6

7 CMDR RUSH: Mr Jeremy, the Commission of Inquiry has
8 received some submissions in relation to the wrecks -
9 including Kormoran, but particularly concentrating on
10 Sydney - suggesting that the ship that we have examined
11 over the course of the last two days is not the Sydney. Do
12 you have any comment on that, or any doubt?

13

14 MR JEREMY: I have absolutely no doubt whatsoever that
15 that is HMAS Sydney.

16

17 CMDR RUSH: The other matter is that in some photographs
18 which don't appear in the report, but it doesn't matter for
19 the purpose of the question, there are leather shoes that
20 have been identified in the debris field near the hull of
21 the ship. Do you have any opinion as to the likelihood of
22 where those shoes came from?

23

24 MR JEREMY: I believe it is possible that they may have
25 come from lockers which were located around the upper deck
26 of the ship for the engine room personnel to change their
27 footwear after leaving the machinery spaces so that they
28 didn't track oil through the ship. So it is possible that
29 those shoes and boots have come from those lockers.

30

31 CMDR RUSH: Thank you. They are all the matters, sir.

32

33 THE PRESIDENT: Thank you very much. Thank you indeed for
34 a very comprehensive report.

35

36 I will now adjourn. There will be further hearings of
37 this Inquiry in Sydney, here, on 19 January, and then there
38 will be some further hearings in Perth commencing on
39 3 February. I will adjourn until 19 January.

40

41 AT 5PM THE COMMISSION WAS ADJOURNED
42 TO MONDAY, 19 JANUARY 2009 AT 10AM

43

44

45

46

47