

JBS&G (43153-57984)

18 June 2014

Doug Wu
Project Manager
Boulderstone Pty Ltd
Via email: Doug.Wu@lendlease.com

**AMR 116 - Daily Airborne Asbestos Fibre Monitoring
Randwick Barracks, 373a Avoca Street, Randwick NSW**

Dear Doug,

Please find as **Attachment 1** the daily airborne asbestos fibre monitoring report for works completed at the Randwick Barracks Project site on **17 June 2014**.

All air monitoring was completed in strict accordance with the *Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres* [NOHSC: 3003(2005)], with NATA certification applying to all sample collection, handling and analytical procedures.

All reported results were satisfactory and below the minimum action levels for control monitoring as outlined in:

- Work, Health and Safety (2011) Regulation; and
- WorkCover Authority of NSW (2011) Code of Practice – *How to Safely Remove Asbestos*.

If you have any questions regarding these results, please feel free to contact the undersigned on 02 8245 0300 or by email msamuel@jbsg.com.au.

Yours sincerely:



Michael Samuel
Licensed Asbestos Assessor (LAA 000157)
JBS&G

Attachments: 1) Daily Airborne Asbestos Fibre Monitoring Report

Attachment 1 – Daily Airborne Asbestos Fibre Monitoring Report

Certificate of Analysis



NATA Accredited
Accreditation Number 1261
Site Number 1254

Accredited for compliance with ISO/IEC 17025.
The results of the tests, calibrations and/or
measurements included in this document are
traceable to Australian/national standards.

JBS & G (NSW & WA) Pty Ltd
Level 1, 50 Margaret St
Sydney
NSW 2000

Attention: Michael Samuel
Report: 422074-A
Client Reference: **RANDWICK 43153**
Received Date: 17 June 2014
Date Reported: 18 June 2014

METHODOLOGY:

Asbestos Sampling Sampling as per the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)]

Pump Calibration Mini Buck Model M-5 S/N A54456 : Calibrated against National Bureau of Standards Test No. IR74-461 utilising a 1000 ml burette with an electric stop watch (SW1).

Asbestos Counting Conducted by ASET in accordance with the National Occupational Health & Safety Commission - Guidance Note on The Membrane Filter Method For Estimating Airborne Asbestos Fibres 2nd Edition [NOHSC:3003(2005)] and (ASET Method 2).

Site Reference: RANDWICK 43153
Date Sampled: 17 June 2014
Report: 422074-A

Eurofins mgt Sample No.	Client Sample ID	Pump ID	Location	Start (time)	End (time)	Start Flow Rate (L/min)	End Flow Rate (L/min)	Average Flow Rate (L/min)	Fibres / 100 fields	Result (Fibres/mL)
14-Jn13458	A372	SKC 002	NORTH PORTION OF SITE SOUTH BOUNDARY – PATHWAY	8:05	13:30	1.8	1.8	1.8	1.0	< 0.01
14-Jn13459	A341	SKC 003	NORTH PORTION WEST BOUNDARY – ACCESS RD	8:08	13:33	1.8	1.8	1.8	1.5	< 0.01
14-Jn13460	A269	SKC 009	NORTH PORTION EAST BOUNDARY – SITE SHEDS	8:11	13:35	1.8	1.8	1.8	0.0	< 0.01
14-Jn13461	A329	SKC 138	SOUTH PORTION EAST BOUNDARY – FIELD	8:14	13:37	1.8	1.8	1.8	1.0	< 0.01
14-Jn13462	A359	SKC 142	SOUTH PORTION SOUTH BOUNDARY – HOUSES	8:17	13:40	1.8	1.8	1.8	1.5	< 0.01
14-Jn13463	A146	SKC 144	SOUTH PORTION WEST BOUNDARY – AVOCA ST SOUTH	8:20	13:42	1.8	1.8	1.8	1.0	< 0.01
14-Jn13464	A310	SKC 153	SOUTH PORTION NORTH BOUNDARY – SITE ACCESS	8:23	13:44	1.8	1.8	1.8	2.0	< 0.01
14-Jn13465	A295	SKC 517	SOUTH PORTION WEST BOUNDARY – AVOCA ST NORTH	8:26	13:46	1.8	1.8	1.8	1.5	< 0.01
14-Jn13466	A356	SKC 008	NORTH PORTION INSIDE LUNCH ROOM	8:29	13:49	1.8	1.8	1.8	2.5	< 0.01
14-Jn13467	A363	BLANK	BLANK						0.0	

Comments

Asbestos analysed by: ASET, NATA accreditation no. 14484, report reference: ASET39802/42982/1-10

Sample Integrity

Custody Seals Intact (if used)	N/A
Attempt to Chill was evident	No
Sample correctly preserved	Yes
Organic samples had Teflon liners	N/A
Sample containers for volatile analysis received with minimal headspace	N/A
Samples received within Holding Time	Yes
Some samples have been subcontracted	Yes

Qualifier Codes/Comments

Code	Description
N/A	Not applicable

Authorised by

Jean Heng
Client Services



Peter Richardson
Field Services Manager

Final Report – this report replaces any previously issued Report.

- Indicates Not Requested

* Indicates NATA accreditation does not cover the performance of this service

Uncertainty data is available on request

Eurofins | mgt shall not be liable for loss, cost, damages or expenses incurred by the client, or any other person or company, resulting from the use of any information or interpretation given in this report. In no case shall Eurofins | mgt be liable for consequential damages including, but not limited to, lost profits, damages for failure to meet deadlines and lost production arising from this report. This document shall not be reproduced except in full and relates only to the items tested. Unless indicated otherwise, the tests were performed on the samples as received.