



SUBM.001.0120

The following photograph of 'Y' turret is also of great interest in that it does not appear to be a MK XXIII turret. It shows no damage to the front of the turret and yet it has no Safety Depression Gear below each barrel, nor does it show any signs of any ever having been there. On some British ships this Safety Depression Gear was only on 'A' and 'B' turrets, but the three Australian Modified Leander cruisers had it on all turrets. There are any number of photographs available that show this quite clearly.

The turret also appears to have a fishing net draped over it and the tubes on top of it are not rounds from the 4" guns, but seem to be pipes. The left hand one has something going into the end of the pipe, either net or silt. The turret also appears to be the wrong shape as well. It appears too narrow and round rather than wider and flatter. (See comparison photographs).

