

R 040927Z MAY 13  
FM HMAS ARARAT  
TO RAYUKB/COMAUSMHPFOR  
RAYUUB/AUSPBGRP  
INFO RAYUKB/AUSFLTSAFETY  
RAYIKB/FLTSPTFOR  
RAYLSA/DGNAVCERTSAFE  
AIG 3611  
BT

~~RESTRICTED~~

SIC W2M/LAL/I2B

SUBJ: ASSAIL SIX (HMAS ARARAT) OHSIR 05/13

A. ABR 6303 PART 2 CHAPTER 6 ANNEX B

B. AF MEMO 12/11

C. ABR 6303 PART 2 CHAPTER 15 ANNEX D

1. ASSAIL SIX (HMAS ARARAT) OHSIR 05/13

2. 161730I/K APR 13 AT SEA

3. HULK OF SIEV 657

4. DANGEROUS OCCURRENCE - FIRE ONBOARD HULK WHILST BEING STEAMED FOR DESTRUCTION

5.A. HULK OF SIEV 657 BEING STEAMED FOR DESTRUCTION. HOLDING PARTY IDENTIFIED SMOKE COMING FROM THE ENGINE ROOM AND COMMENCED FIRST AID ATTACK. UNABLE TO COMBAT THE FIRE, HOLDING PARTY WITHDREW TO SEABOAT AND RETURNED TO ARA. HULK BURNT TO THE WATERLINE. QA CONDUCTED.

B. NO

C. N/A

6. PRECONDITIONS FOR UNSAFE ACTS-SUBSTANDARD CONDITIONS-EQUIPMENT -OTHER EQUIPMENT CONDITIONS. ENGINE ABILITY RETROSPECTIVELY ASSESSED AS LIMITED.

7. ALL ACTIONS IAW SOP'S. CREW REBRIEFED ON SAFETY WHEN ACTING AS HOLDING PARTY.

8.A.YES

B. 170830I/K APR 13 - DANGEROUS INCIDENT. ADVISED NO FURTHER ACTION REQUIRED.

C. N/A

9. HRI (P)10 (F)12 (M)10 (E)12

10. ASSESSED AS ALARP

11. HRI (P)10 (F)12 (M)10 (E)12

12. POC: s22 (XO ASSAIL SIX) E:s22 (AT)FLEET.DEFENCE.GOV  
.AU

BT