

R50 – 7 PNEUMATIC TYRED MARCO ROLLER

P56H014

Correct as at 01 Jan 2010

- | | | | |
|----|--|--|---|
| 1. | Roller Description | 50t Marco Roller, 4 Wheel | |
| 2. | Current Location | Gladstone Airport | |
| 3. | Body Condition | Painted orange and is generally in an average condition, extensive surface rust with paint flaking off and requires sandblasting and repainting. Structural integrity visually appears fit for purpose | |
| 4. | Tyre Condition | Pneumatic Tyres. Tyres appear to be in good condition.

Wheel bearings may need to be inspected in a workshop, however, they appear to be maintained and greased. | |
| 5. | Ballast Weights | Weights are individual and uncaged, some handles are bent and damaged. Require individual inspection and assessment prior to loading | |
| 6. | Recent Upgrades | 2006 | Major repairs and upgrades conducted including replacements of tyres and rims |
| 6. | Operational Issues | No brakes on roller, wheel chocks may be required to be purchased | |
| 7. | Recent Hire | 2009/10
2009
2006/07
2006 | RAAF Base Pearce new C17 pavements
RAAF Base Amberley parking aprons
Gold Coast Airport
Canberra Airport |
| 8. | Photographs (taken 26 Jun 2009) | | |



Front View



Rear View



Side View



Top View



Tyres



Ballast Weights