



This photograph shows the boat area beside the funnel on the port side. Note the chocks for the boats. In the following photograph taken from the ROV footage all of these fittings are missing, presumably removed before the ship sank. Photograph is of HMS Apollo (ie HMAS Hobart) but the Sydney would have had the same layout.